

TABLE E.5—EXCLUSIONS FROM ADJUSTMENTS TO THE INITIAL BASE ASSESSMENT RATE

Adjustment	Calculation	Exclusion
Unsecured debt adjustment	The unsecured debt adjustment shall be determined as the sum of the initial base assessment rate plus 40 basis points; that sum shall be multiplied by the ratio of an insured depository institution's long-term unsecured debt to its assessment base. The amount of the reduction in the assessment rate due to the adjustment is equal to the dollar amount of the adjustment divided by the amount of the assessment base.	Exclude the quarterly average amount of assets purchased under MMLF and quarterly average amount of loans pledged to the PPPLF.
Depository institution debt adjustment	An insured depository institution shall pay a 50 basis point adjustment on the amount of unsecured debt it holds that was issued by another insured depository institution to the extent that such debt exceeds 3 percent of the institution's Tier 1 capital. This amount is divided by the institution's assessment base. The amount of long-term unsecured debt issued by another insured depository institution shall be calculated using the same valuation methodology used to calculate the amount of such debt for reporting on the asset side of the balance sheets.	Exclude the quarterly average amount of assets purchased under MMLF and quarterly average amount of loans pledged to the PPPLF outstanding.
Brokered deposit adjustment	The brokered deposit adjustment shall be determined by multiplying 25 basis points by the ratio of the difference between an insured depository institution's brokered deposits and 10 percent of its domestic deposits to its assessment base.	Exclude the quarterly average amount of assets purchased under MMLF and quarterly average amount of loans pledged to the PPPLF outstanding.

IV. Mitigating the Effects on the Assessment Base Attributable to the Paycheck Protection Program Lending Facility and the Money Market Mutual Fund Liquidity Facility.

Total Assessment Amount Due = Total Assessment Amount LESS: (SUM (Quarterly average amount of assets pledged to the PPPLF and quarterly average amount of assets purchased under the MMLF) * Total Base Assessment Rate)

Federal Deposit Insurance Corporation.

By order of the Board of Directors.

Dated at Washington, DC, on May 12, 2020.

Robert E. Feldman,

Executive Secretary.

[FR Doc. 2020–10454 Filed 5–18–20; 2:30 pm]

BILLING CODE 6714–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–0503; Product Identifier 2018–SW–006–AD]

RIN 2120–AA64

Airworthiness Directives; Leonardo S.p.a. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Leonardo S.p.a. (Leonardo) Model AW189 helicopters. This proposed AD would require various repetitive inspections of the main rotor (MR) damper. This proposed AD is prompted by reports of in-service MR damper failures and the development of an improved MR damper. This condition, if not corrected, could lead to loss of the lead-lag damping function of the MR blade, possibly resulting in damage to adjacent critical rotor components and subsequent loss control of the helicopter. The actions of this proposed AD are intended to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by July 20, 2020.

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Docket:** Go to <https://www.regulations.gov>. Follow the online instructions for sending your comments electronically.

- **Fax:** 202–493–2251.

- **Mail:** Send comments to the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590–0001.

- **Hand Delivery:** Deliver to the “Mail” address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0503; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed rule, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39–0331–225074; fax +39–0331–229046; or at <https://www.leonardocompany.com/en/home>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N–321, Fort Worth, TX 76177.

FOR FURTHER INFORMATION CONTACT: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone 817-222-5110; email matthew.fuller@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to participate in this rulemaking by submitting written comments, data, or views. The FAA also invites comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

The FAA will file in the docket all comments received, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, the FAA will consider all comments received on or before the closing date for comments. The FAA will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. The FAA may change this proposal in light of the comments received.

Discussion

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD No. 2016-0145R1, dated January 17, 2018 (EASA AD 2016-0145R1), to correct an unsafe condition for Leonardo S.p.A. Model AW189 helicopters with MR damper part number (P/N) 4F6220V00251 installed. EASA advises that a MR damper failed, which resulted in complete seizure of the body end lug and an in-flight disconnection of the damper. EASA states that a combination of factors may have contributed to the MR damper disconnection, and that this condition could result in loss of the lead-lag damping function of the MR blade, damage to adjacent critical rotor components, and subsequent reduced control of the helicopter. The contributing factors include cracks, slippage marks, damaged broach ring teeth, and loss of torque.

According to EASA, the AW189 MR damper is a similar design to the MR dampers installed on Model AW139

helicopters, where multiple MR damper failures have been reported involving the body end lug, the eye end lug, and the rod end. To correct this condition, EASA issued a series of superseded and revised ADs to require repetitive inspections of certain MR dampers, and similar corrective actions as those for Model AW139 helicopters. EASA AD 2016-0145R1 requires various one-time and repetitive inspections of the MR damper, a torque check of the damper body end, and replacing any MR damper with a crack or that fails the torque check. EASA AD 2016-0145R1 also allows installation of a new MR damper, P/N 8G6220V00151, as an optional terminating action for the repetitive inspections.

FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA is proposing this AD after evaluating all known relevant information and determining that an unsafe condition is likely to exist or develop on other helicopters of the same type designs.

Related Service Information Under 1 CFR Part 51

The FAA reviewed Finmeccanica Bollettino Tecnico No. 189-080, Revision A, dated July 15, 2016, which contains procedures for visual and dye penetrant inspections of the MR damper for cracks and for verifying the torque of the damper body ends.

The FAA also reviewed Leonardo Helicopters Alert Service Bulletin No. 189-102, Revision A, dated December 21, 2017, which contains procedures for installing an MR damper with reduced torque values and specifies replacing MR damper P/N 4F6220V00251 with new MR damper P/N 8G6220V00151.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Other Related Service Information

The FAA reviewed Finmeccanica Bollettino Tecnico No. 189-069, dated February 12, 2016, which contains procedures for installing a special washer on the MR damper rod end, modifying the installation torque of the MR damper, and inspecting the rod end bearings.

Proposed AD Requirements

This proposed AD would require compliance with certain procedures described in the manufacturer's service bulletins. For helicopters with a MR damper P/N 4F6220V00251, this proposed AD would require:

- Within 10 hours time-in-service (TIS), reducing the installation torque of the nuts on the bolts attaching the MR damper to the MR hub;
- Within 30 hours TIS or before a MR damper body end accumulates 500 hours TIS since first installation on a helicopter, whichever occurs later, and, thereafter at intervals not to exceed 500 hours TIS, replacing the affected MR damper;
- Before the MR damper accumulates 300 hours TIS since new or overhaul, dye penetrant or eddy current inspecting the rod end and body end of each MR damper for a crack, and thereafter, before the first flight of each day, visually inspecting the rod end and body end of each MR damper for a crack. If there is a crack, this proposed AD would require replacing the MR damper;
- Within 30 hours TIS and thereafter at intervals not exceeding 10 hours TIS for MR dampers that have accumulated less than 300 hours TIS since new or overhaul or within 5 hours TIS and therefore before the first flight of each day for MR dampers that have accumulated 300 or more hours TIS since new or overhaul, inspecting each rod end and body end bearing for rotation, and replacing the rod end or MR damper as applicable if there is any rotation;
- For certain serial-numbered MR dampers, within 30 hours TIS and thereafter at intervals not exceeding 20 hours TIS, inspecting the lag damper broached ring nut for damage, correct engagement, and alignment. If there is damage on the ring nut, incorrect engagement, or mis-alignment, this proposed AD would require removing the rod end and broached ring nut from service. These repetitive inspections would terminate after the MR damper has accumulated 600 hours TIS;
- Within 50 hours TIS and thereafter at intervals not exceeding 100 hours TIS, inspecting the bearing friction torque of each MR damper body end and rod end, and replacing the MR damper if the torque value exceeds 30.0 Nm (265.5 lb in);
- Within 50 hours TIS and thereafter at intervals not exceeding 100 hours TIS, inspecting the MR damper anti-rotation block for wear and replacing the anti-rotation block if there is wear beyond acceptable limits;

- Within 50 hours TIS, replacing each special washer P/N 3G6220A05051 with special washer P/N 3G6220A05052;
- For certain MR dampers, within 50 hours TIS, inspecting the broached ring for damage and alignment, removing the broached ring from service if there is damage, and replacing the broached ring if the rod end and broached ring cannot be aligned; and
- Prior to installation on any helicopter, inspecting certain serial-numbered MR dampers for correct torque of the broached ring.

Differences Between This Proposed AD and the EASA AD

The EASA AD requires contacting the manufacturer under certain conditions, while this proposed AD would not.

Costs of Compliance

The FAA estimates that this AD would affect 3 helicopters of U.S. Registry. The FAA estimates that operators may incur the following costs in order to comply with this AD. Labor costs are estimated at \$85 per work-hour.

Adjusting the tightening torque would require about 10 work-hours, for an estimated cost of \$850 per helicopter and \$2,550 for the U.S. fleet.

Replacing an MR damper would require about 2 work-hours, and parts would cost about \$18,000, for an estimated cost of \$18,170 per MR damper.

Performing a dye penetrant or eddy current inspection of the MR damper would require about 8 work-hours, for an estimated cost of \$680 per helicopter and \$2,040 for the U.S. fleet.

Visually inspecting the rod ends and body ends would require about 0.5 hour, for an estimated cost of \$43 per helicopter and \$129 for the U.S. fleet, per inspection cycle.

Inspecting the rod ends and body ends for bearing rotation would require about 0.5 hour, for an estimated cost of \$43 per helicopter and \$129 for the U.S. fleet, per inspection cycle.

Inspecting the broached ring nut would require about 0.5 hour, for an estimated cost of \$43 per helicopter and \$129 for the U.S. fleet, per inspection cycle.

Inspecting for bearing friction would require about 2 hours, for an estimated cost of \$170 per helicopter and \$510 for the U.S. fleet, per inspection cycle.

Inspecting the broached ring teeth for proper alignment and applying torque would require about 8 work-hours, for an estimated cost of \$680 per helicopter and \$2,040 for the U.S. fleet.

Replacing a rod end would require about 3 work-hours and parts would

cost about \$500, for a cost an estimated cost of \$755 per rod end.

Replacing a broached ring would require about 3 work-hours and parts would cost about \$100, for an estimated cost of \$355, per broached ring.

Replacing a broached ring nut would require about 3 work-hours and parts would cost about \$125, for an estimated cost of \$380 per broached ring nut.

Replacing an anti-rotation block would require about 3 work-hours and parts would cost about \$50, for a cost an estimated cost of \$305 per anti-rotation block.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Will not affect intrastate aviation in Alaska, and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Leonardo S.p.a: Docket No. FAA–2020–0503; Product Identifier 2018–SW–006–AD.

(a) Applicability

This AD applies to Leonardo S.p.A. Model AW189 helicopters, certificated in any category, with a main rotor (MR) damper part number (P/N) 4F6220V00251 installed.

(b) Unsafe Condition

This AD defines the unsafe condition as a crack in an MR damper, which if not detected and corrected, could lead to loss of the lead-lag damping function of the MR blade, resulting in damage of the MR damper, detachment of the MR damper in-flight, and subsequent loss of control of the helicopter.

(c) Comments Due Date

The FAA must receive comments by July 20, 2020.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 10 hours time-in-service (TIS), reduce the torque of the nut on the bolt attaching each MR damper to the MR hub by following paragraphs 4 through 7 of the Accomplishment Instructions, Part I, of Leonardo Helicopters Alert Service Bulletin No. 189–102, Revision A, dated December 21, 2017 (ASB 189–102).

(2) Within 30 hours TIS or before the MR damper body end (body end) accumulates 500 hours TIS, whichever occurs later, and thereafter at intervals not to exceed 500 hours TIS, replace the MR damper.

(3) Within 30 hours TIS, before the MR damper accumulates 300 hours TIS, or within 300 hours TIS since the last overhaul, whichever occurs later, dye penetrant inspect using a 5X power magnifying glass or eddy current inspect each MR damper rod end (rod end) and body end for a crack in the areas depicted in Figure 2 of Finmeccanica Bollettino Tecnico No. 189–080, Revision A, dated July 15, 2016 (BT 189–080).

(i) If there is a crack on the body end, before further flight, replace the MR damper.

(ii) If there is a crack on the rod end, before further flight, replace the rod end and, within 300 hours TIS, dye penetrant or eddy current

inspect the rod end for a crack as described in paragraph (e)(3) of this AD.

(iii) If there are no cracks, before further flight, mark the rod end and body end with a dot of black polyurethane paint as shown in Figure 13 of BT 189–080.

(iv) Thereafter, before the first flight of each day, using a mirror and a magnifying glass visually inspect each rod end and body end for a crack in the areas shown in Figure 14 of BT 189–080. If there is a crack in the rod end, before further flight, replace the rod end. If there is a crack on the body end, before further flight, replace the MR damper.

(4) Within the compliance times listed in paragraphs (e)(4)(i) and (ii) of this AD, inspect each rod end bearing and body end for bearing rotation in the damper seat. An example of rotation (misaligned slippage marks) is shown in Figure 4 of BT 189–080. If there is any bearing rotation in the rod end, before further flight, replace the rod end. If there is any bearing rotation in the body end, before further flight, replace the MR damper.

(i) For MR dampers that have accumulated less than 300 hours TIS since new or since the last overhaul, within 30 hours TIS and thereafter at intervals not to exceed 10 hours TIS.

(ii) For MR dampers that have accumulated 300 or more hours TIS since new or since the last overhaul, within 5 hours TIS and thereafter before the first flight of each day.

(5) For helicopters with an MR damper with a serial number (S/N) MCR0001 through MCR0154 and MCR0174 through MCR0195, within 30 hours TIS and thereafter at intervals not to exceed 20 hours TIS until the MR damper has accumulated 600 hours TIS, visually inspect each MR damper broached ring nut for broken teeth, proper engagement, and alignment as depicted in Figure 5 and shown in Figures 6, 7, and 8 of BT 189–080. If there is a broken tooth, improper engagement, or misalignment of the broached ring nut, before further flight, remove from service the rod end and broached ring nut.

(6) Within 50 hours TIS and thereafter at intervals not to exceed 100 hours TIS:

(i) Rotate the body end around the damper axis to put it near the middle position and determine the bearing friction torque value of the body end, using as a reference Figure 11 of BT 189–080.

Note 1 to Paragraph (e)(6)(i) of this AD: Applying too much force while rotating the body end around the damper axis may cause damage.

(A) If the torque value of the body end is more than 30.0 Nm (265.5 in lb), before further flight, replace the MR damper.

(B) If the torque value of the body end is 30.0 Nm (265.5 in lb) or less, determine the bearing friction torque value of each rod end, using as a reference Figure 11 of BT 189–080. If the torque value of the rod end is more than 30.0 Nm (265.5 in lb), before further flight, replace the rod end.

(ii) Inspect each MR damper anti-rotation block for wear by following paragraphs 4.3 through 4.3.6 of the Compliance Instructions, Part VI, of BT 189–080. If there is wear, before further flight, replace the MR damper anti-rotation block.

(7) Within 50 hours TIS:

(i) On each MR damper, replace special washer P/N 3G6220A05051 with special washer P/N 3G6220A05052.

(ii) For helicopters with an MR damper with a S/N MCR0001 through MCR0041, MCR0043, MCR0045 through MCR0151, MCR0153 through MCR0157, MCR0159 through MCR0179, and MCR0185 through MCR0370; and for MR dampers with a rod end P/N M006–01H004–045 or P/N M006–01H004–053 installed, do the following:

(A) Inspect each broached ring for wear, bent teeth, missing teeth, and stripped threads. Pay particular attention to the four pins that engage the piston grooves. If there is any wear or damage to the broached ring, before further flight, remove from service the broached ring. An example of an acceptable broached ring is shown in Figure 4, Annex A, of BT 189–080.

(B) Align each rod end and broached ring by applying a torque of 60 Nm (531 in lb) to 80 Nm (708 in lb). If the rod end and broached ring cannot be aligned, before further flight, replace the broached ring.

(8) Except for MR dampers with a S/N MCR0042, MCR0044, MCR0152, MCR0158, and MCR0180 through MCR0184, do not install an MR damper P/N 4F6220V00251 on any helicopter unless the MR damper has passed the requirements in paragraph (e)(7)(ii) of this AD.

(f) Credit for Previous Actions

(1) Actions accomplished before the effective date of this AD in accordance with the Compliance Instructions, Part II, of Finmeccanica Bollettino Tecnico No. 189–069, dated February 12, 2016 (BT 189–069), are considered acceptable for compliance with the corresponding actions in paragraph (e)(7)(i) of this AD.

(2) Actions accomplished before the effective date of this AD in accordance with the Compliance Instructions, Part III, of BT 189–069, are considered acceptable for compliance with the corresponding actions in paragraph (e)(7)(ii) of this AD.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Section, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone 817–222–5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

(1) Finmeccanica Bollettino Tecnico No. 189–069, dated February 12, 2016, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Leonardo S.p.A. Helicopters, Emanuele Bufano, Head of Airworthiness,

Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39–0331–225074; fax +39–0331–229046; or at <https://www.leonardocompany.com/en/home>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N–321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD No. 2016–0145R1, dated January 17, 2018. You may view the EASA AD on the internet at <https://www.regulations.gov> in the AD Docket.

(i) Subject

Joint Aircraft Service Component (JASC)
Code: 6200, Main Rotor System.

Issued on May 14, 2020.

Lance T. Gant,

*Director, Compliance & Airworthiness
Division, Aircraft Certification Service.*

[FR Doc. 2020–10752 Filed 5–19–20; 8:45 am]

BILLING CODE 4910–13–P

EQUAL EMPLOYMENT OPPORTUNITY COMMISSION

29 CFR Part 1695

RIN 3046–AB18

Procedural Regulations for Issuing Guidance

AGENCY: Equal Employment Opportunity Commission.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Equal Employment Opportunity Commission (EEOC or Commission) proposes to amend its procedural regulations to establish rules for issuing guidance. These rules make guidance documents readily available to the public, ensure that guidance will be treated as non-binding, require a notice and public comment period for significant guidance, and establish a public petition process for the issuance, amendment, or repeal of guidance.

DATES: Comments must be received on or before June 19, 2020.

ADDRESSES: You may submit comments by any of the following methods—please use only one method:

- **Federal eRulemaking Portal:** <http://www.regulations.gov>. Follow the instructions on the website for submitting comments.

- **Mail:** Comments may be submitted by mail to Bernadette B. Wilson, Executive Officer, Executive Secretariat, Equal Employment Opportunity Commission, 131 M Street NE, Washington, DC 20507.

Instructions: All comments received must include the agency name or Regulatory Information Number (RIN)