

information on the availability of this material at the FAA, call (781) 238-7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 27, 2020.

Gaetano A. Sciortino,

*Deputy Director for Strategic Initiatives,
Compliance & Airworthiness Division,
Aircraft Certification Service.*

[FR Doc. 2020-24794 Filed 11-6-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0898; Project Identifier AD-2020-01284-T; Amendment 39-21320; AD 2020-23-04]

RIN 2120-AA64

Airworthiness Directives; Gulfstream Aerospace Corporation Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Gulfstream Aerospace Corporation (Gulfstream) Model GVII-G500 and Model GVII-G600 airplanes. This AD requires revising your existing airplane flight manual (AFM) and airplane maintenance manual (AMM) to include information pertaining to the fuel boost pump. This AD was prompted by a report of misassembled impellers onto the shaft of the fuel boost pump during production. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 24, 2020.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of November 24, 2020.

The FAA must receive comments on this AD by December 24, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-

30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Gulfstream Aerospace Corporation, Technical Publications Dept., P.O. Box 2206, Savannah, GA 31402; phone: (800) 810-4853; email: pubs@gulfstream.com; website: <https://www.gulfstream.com/en/customer-support/>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0898.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0898; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Jared Meyer, Aerospace Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, Georgia 30337; phone: (404) 474-5534; fax: (404) 474-5605; email: jared.meyer@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA was notified by Gulfstream of the possibility of misassembled impellers onto the shaft of fuel boost pumps used in the production of GVII-G500 and GVII-G600 airplanes. The supplier of fuel boost pumps discovered two misassembled fuel boost pumps on two different make/models of non-Gulfstream aircraft. The Gulfstream GVII-G500 and GVII-G600 fuel boost pumps are very similar in design and are manufactured in the same facility using the same manufacturing processes, so the same condition could exist on the Gulfstream fuel boost pumps.

A misassembled fuel boost pump could result in a woodruff key becoming dislodged and causing friction between static and rotating components internal to the fuel boost pump. This friction could generate heat or sparks inside the fuel tank, which, if the pump were to run dry, could result in a fuel tank fire or fuel tank explosion.

The unsafe condition, if not addressed, could result in a potential source of ignition in the fuel tank and may lead to fire or explosion.

Related Service Information Under 1 CFR Part 51

The FAA reviewed the following AFM supplements, which contain new warnings about operating the boost pumps with empty fuel tanks for the Abnormal Procedures and Emergency Procedures sections of the AFM. These documents are distinct because they pertain to different airplane models:

- Gulfstream Aerospace GVII-G500 Airplane Flight Manual Supplement No. GVII-G500 (Issue 1)-2020-05, dated September 8, 2020;
- Gulfstream Aerospace GVII-G500 Airplane Flight Manual Supplement No. GVII-G500-2020-06, dated September 8, 2020; and
- Gulfstream Corporation GVII-G600 Airplane Flight Manual Supplement No. GVII-G600-2020-06 dated September 8, 2020.

The FAA also reviewed the following AMM documents, which contain revised maintenance procedures pertaining to the fuel boost pump. These documents are distinct since they apply to different airplane models. Although the documents have the watermarked words "advance copy" on each page of the document, these are not advance draft copies but final versions of temporary revisions to the AMM, pending incorporation into the AMM at the next revision.

- GVII-G500 Maintenance Manual 12-13-01 Defueling Procedure—Defuel, dated August 31, 2020;
- GVII-G500 Maintenance Manual 28-26-04 Fuel Boost Pump—Prime, dated August 31, 2020;
- GVII-G600 Maintenance Manual 12-13-01 Defueling Procedure—Defuel, dated August 31, 2020;
- GVII-G600 Maintenance Manual 28-26-04 Fuel Boost Pump—Prime, dated August 31, 2020;
- GVII-G600 Maintenance Manual 28-26-04 Fuel Boost Pump—Removal/Installation, dated August 31, 2020; and
- GVII-G600 Maintenance Manual 28-26-05 Fuel Boost Pump Canister—Removal/Installation, dated August 31, 2020.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

The FAA is issuing this AD because it evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of this same type design.

AD Requirements

This AD requires revising the existing AFM for your airplane by adding new warnings to the Abnormal Procedures and Emergency Procedures sections. Revising the existing AFM for your airplane is not considered a maintenance action and therefore may be performed by the owner/operator (pilot) holding at least a private pilot certificate. The pilot must record compliance in the aircraft maintenance records in accordance with 14 CFR 43.9(a)(1) through (4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417.

This AD also requires revising the existing AMM for your airplane by replacing maintenance procedures pertaining to the fuel boost pump.

Interim Action

The FAA considers this AD an interim action. The design approval holder is currently working on a modification that will address the unsafe condition identified in this AD. Once this modification action is developed, FAA-approved, and available, the FAA will consider additional rulemaking.

Justification For Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment

procedures for rules when the agency, for "good cause," finds that those procedures are "impracticable, unnecessary, or contrary to the public interest." Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies foregoing notice and comment prior to adoption of this rule because misassembled fuel boost pump components could generate heat or sparks leading to a potential fuel tank explosion. If an operator or maintenance personnel were to run fuel boost pump dry, it could result in fuel tank fire or explosion. The FAA determined that the actions necessary to correct this condition must be accomplished within 14 days. Therefore, the FAA finds good cause that notice and opportunity for prior public comment are impracticable pursuant to 5 U.S.C. 553(b)(3)(B).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. The FAA invites you to send any written relevant data, views, or arguments about this final rule. Send your comments to an address listed under **ADDRESSES**. Include Docket No. FAA-2020-0898 and Project Identifier AD-2020-01284-T at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain

the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Jared Meyer, Aerospace Engineer, Atlanta ACO Branch, FAA, 107 Charles W. Grant Pkwy, Atlanta, GA 30354. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Costs of Compliance

The FAA estimates that this AD affects 80 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Revise the AMM	1 work-hour × \$85 per hour = \$85	Not applicable	\$85	\$6,800
Revise the AFM	1 work-hour × \$85 per hour = \$85	Not applicable	85	6,800

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII:

Aviation Programs describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section

44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds

necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2020-23-04 Gulfstream Aerospace Corporation: Amendment 39-21320; Docket No. FAA-2020-0898; Project Identifier AD-2020-01284-T.

(a) Effective Date

This airworthiness directive (AD) is effective November 24, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Gulfstream Aerospace Corporation Model GVII-G500 airplanes, serial numbers 72001 through 72064, and Model GVII-G600 airplanes, serial numbers 73001 through 73043, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 2822, Fuel Boost Pump.

(e) Unsafe Condition

This AD was prompted by a report of misassembled impellers onto the shaft of the fuel boost pump during production. The FAA is issuing this AD to prevent the ignition of flammable vapors in the fuel tank as a result of frictional heating or sparks caused by a dislodged woodruff key inside the fuel boost pump. This unsafe condition, if not addressed, could result in a potential source of ignition in the fuel tank and consequent fire or explosion.

(f) Compliance

You must comply with this AD within 14 days after the effective date of this AD, unless already done.

(g) Required Actions

(1) Revise your existing airplane maintenance manual (AMM) by replacing the procedures listed in paragraphs (g)(1)(i) through (vi) of this AD, as applicable for your model airplane.

(i) GVII-G500 Maintenance Manual 12-13-01 Defueling Procedure—Defuel, dated August 31, 2020;

(ii) GVII-G500 Maintenance Manual 28-26-04 Fuel Boost Pump—Prime, dated August 31, 2020;

(iii) GVII-G600 Maintenance Manual 12-13-01 Defueling Procedure—Defuel, dated August 31, 2020;

(iv) GVII-G600 Maintenance Manual 28-26-04 Fuel Boost Pump—Prime, dated August 31, 2020;

(v) GVII-G600 Maintenance Manual 28-26-04 Fuel Boost Pump—Removal/Installation, dated August 31, 2020; and

(vi) GVII-G600 Maintenance Manual 28-26-05 Fuel Boost Pump Canister—Removal/Installation, dated August 31, 2020.

(2) Revise your existing airplane flight manual (AFM) by including in the AFM the airplane flight manual supplement (AFMS) listed in paragraph (g)(2)(i), (ii) or (iii) of this AD that is applicable to your model airplane. Using a later AFM revision with information identical to that contained in the AFMS specified for your airplane is acceptable for compliance with the requirement of this paragraph.

(i) Gulfstream Aerospace GVII-G500 Airplane Flight Manual Supplement No. GVII-G500 (Issue 1)—2020-05, dated September 8, 2020;

(ii) Gulfstream Aerospace GVII-G500 Airplane Flight Manual Supplement No. GVII-G500—2020-06, dated September 8, 2020; or

(iii) Gulfstream Aerospace GVII-G600 Airplane Flight Manual Supplement No. GVII-G600—2020-06, dated September 8, 2020.

(3) The action required by paragraph (g)(2) of this AD may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR 43.9(a)(1) through (4), and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.439.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Atlanta ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact Jared Meyer, Aerospace Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, Georgia 30337; phone: (404) 474-5534; fax: (404) 474-5605; email: jared.meyer@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Gulfstream Aerospace GVII-G500 Airplane Flight Manual Supplement No. GVII-G500 (Issue 1)—2020-05, dated September 8, 2020.

(ii) Gulfstream Aerospace GVII-G500 Airplane Flight Manual Supplement No. GVII-G500—2020-06, dated September 8, 2020.

(iii) Gulfstream Aerospace GVII-G600 Airplane Flight Manual Supplement No. GVII-G600—2020-06, dated September 8, 2020.

(iv) GVII-G500 Maintenance Manual 12-13-01 Defueling Procedure—Defuel, dated August 31, 2020.

Note 1 to paragraph (j)(2)(iv): Although the documents in paragraphs (j)(2)(iv) through (ix) have the watermarked words “advance copy” on each page of the document, these are not advance draft copies but final versions of temporary revisions to the AMM, pending incorporation into the AMM at the next revision.

(v) GVII-G500 Maintenance Manual 28-26-04 Fuel Boost Pump—Prime, dated August 31, 2020.

(vi) GVII-G600 Maintenance Manual 12-13-01 Defueling Procedure—Defuel, dated August 31, 2020.

(vii) GVII-G600 Maintenance Manual 28-26-04 Fuel Boost Pump—Prime, dated August 31, 2020.

(viii) GVII-G600 Maintenance Manual 28-26-04 Fuel Boost Pump—Removal/Installation dated August 31, 2020.

(ix) GVII-G600 Maintenance Manual 28-26-05 Fuel Boost Pump Canister—Removal/Installation, dated August 31, 2020.

(3) For Gulfstream Aerospace Corporation service information identified in this AD, contact Gulfstream Aerospace Corporation, Technical Publications Dept., P.O. Box 2206, Savannah, GA 31402; phone: (800) 810-4853; email: pubs@gulfstream.com; website: <https://www.gulfstream.com/en/customer-support/>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 27, 2020.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-24808 Filed 11-6-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0378; Product Identifier 2018-SW-060-AD; Amendment 39-21316; AD 2020-22-20]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Airbus Helicopters Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters. This AD requires visually inspecting each main rotor gearbox (MGB) suspension bar attachment bracket bolt for missing bolt heads. Depending on the outcome of the visual inspection, measuring the tightening torque, removing certain parts, sending photos and reporting information to Airbus

Helicopters, and completing an FAA-approved repair is required. This AD was prompted by a report of a missing MGB suspension bar attachment bolt head. The actions of this AD are intended to address an unsafe condition on these products.

DATES: This AD is effective December 14, 2020.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of December 14, 2020.

ADDRESSES: For service information identified in this final rule, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972-641-0000 or 800-232-0323; fax 972-641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view this referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0378.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0378; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD, any service information that is incorporated by reference, any comments received, and other information. The street address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Kristi Bradley, Aerospace Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email kristin.bradley@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to Airbus Helicopters Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350C, AS350D, AS350D1, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and

EC130T2 helicopters. The NPRM published in the **Federal Register** on April 13, 2020, (85 FR 20447). The NPRM proposed to require visually inspecting each MGB suspension bar attachment bracket for missing bolt heads. If one bolt head is missing, the proposed AD would require performing actions specified in the service information including measuring the tightening torque of the remaining bolts of that bracket, removing the attachment bracket bolts, washers, and nuts of that bracket, and sending photos and reporting certain information to Airbus Helicopters. The proposed AD would also require repairs in accordance with an FAA-approved method if two or more bolt heads are missing. The proposed requirements were intended to prevent failure of the MGB suspension bar attachment bolts due to fatigue.

The NPRM was prompted by EASA AD No. 2018-0152, dated July 18, 2018 (EASA AD 2018-0152), issued by EASA, which is the Technical Agent for the Member States of the European Union, to correct an unsafe condition for Airbus Helicopters (formerly Eurocopter, Eurocopter France) Model AS 350 B, AS 350 D, AS 350 B1, AS 350 B2, AS 350 BA, AS 350 BB, AS 350 B3, EC 130 B4, EC 130 T2, AS 355 E, AS355 F, AS355 F1, AS 355 F2, AS 355 N, and AS355 NP helicopters. EASA advises of a reported occurrence of a missing MGB suspension bar attachment bolt head.

EASA advises that investigations are ongoing to determine the root cause of this event. According to Airbus Helicopters, the missing MGB suspension bar attachment bolt head was discovered during scheduled maintenance of a Model EC 130 T2 helicopter. EASA states this condition could lead to fatigue failure of other affected bolts of the same MGB bracket, possibly resulting in loss of the MGB suspension bar and consequently loss of helicopter control. As an interim measure to address this potential unsafe condition, the EASA AD also includes Model AS 350 B, AS 350 D, AS 350 B1, AS 350 B2, AS 350 BA, AS 350 BB, AS 350 B3, EC 130 B4, AS 355 E, AS355 F, AS355 F1, AS355 F2, AS355 N, and AS355 NP helicopters in its applicability.

Accordingly, EASA AD 2018-0152 requires a one-time visual inspection to check that all MGB suspension bar attachment bracket bolt heads are present and depending on the outcome, measuring the tightening torque values of the bolts, removing and sending bolts, washers, and nuts to Airbus Helicopters, installing new bolts, washers, and nuts, sending photos and reporting certain information to Airbus Helicopters, and