

issuing this AD to address broken and bent attachment bolts of the MR hub scissors assembly, which could lead to detachment of a MR hub scissors attachment bolt, possibly resulting in complete loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021–0046.

(h) Exceptions to EASA AD 2021–0046

(1) Where EASA AD 2021–0046 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where EASA AD 2021–0046 refers to September 05, 2018 (the effective date of EASA AD 2018–0186), this AD requires using May 7, 2021 (the effective date of AD 2021–04–21).

(3) This AD does not mandate compliance with the “Remarks” section of EASA AD 2021–0046.

(4) Where the service information referenced in EASA AD 2021–0046 specifies to discard certain parts, this AD requires removing those parts from service.

(5) Where EASA AD 2021–0046 refers to flight hours (FH), this AD requires using hours time-in-service.

(6) Paragraphs (3) and (4) of EASA AD 2021–0046 refer to “discrepancies.” For this AD, discrepancies include corrosion, fretting, wear, cracking, bolt play, twist, shearing, rupture, and bolt tightening torque.

(7) Where EASA AD 2021–0046 specifies to contact the manufacturer for repair instructions, this AD requires the repair to be done in accordance with a method approved by the Manager, General Aviation and Rotorcraft Section, International Validation Branch, FAA; or EASA; or Airbus Helicopter’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(8) Paragraph (5) of EASA AD 2021–0046 specifies to report inspection results to Airbus Helicopters within a certain compliance time. For this AD, report inspection results at the applicable time specified in paragraph (h)(8)(i) or (ii) of this AD.

(i) If the inspection was done on or after May 7, 2021 (the effective date of AD 2021–04–21): Submit the report within 30 days after the inspection.

(ii) If the inspection was done before May 7, 2021 (the effective date of AD 2021–04–21): Submit the report within 30 days after May 7, 2021.

(i) Special Flight Permit

Special flight permits, as described in 14 CFR 21.197 and 21.199, are not allowed.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve

AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Hal Jensen, Aerospace Engineer, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 950 L’Enfant Plaza N SW, Washington, DC 20024; phone: (202) 267–9167; email: hal.jensen@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021–0046, dated February 12, 2021.

(ii) [Reserved]

(3) For EASA AD 2021–0046, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; Internet: www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0829.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 15, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–26680 Filed 12–9–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0826; Project Identifier MCAI–2021–00300–R; Amendment 39–21826; AD 2021–24–05]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters Deutschland GmbH Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Helicopters Deutschland GmbH Model EC135P2+, EC135P3, EC135T2+, and EC135T3 helicopters. This AD was prompted by reports that certain aft and forward fitting assemblies, which are not approved for installation on certain helicopters, were installed on those helicopters as part of the outboard load system. Operators of those helicopters might not be aware of the applicable overhaul or life limits for those fitting assemblies. This AD requires inspecting the aft and forward fitting assemblies of the outboard load system to determine the part number, re-identifying the part if necessary, inspecting each affected part for damage (which may be indicated by signs of corrosion, mechanical damage, loose rivets, or cracks) and, depending on the findings, corrective actions, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 14, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 14, 2022.

ADDRESSES: For EASA material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110. It is also available in the AD docket at <https://www.regulations.gov>.

www.regulations.gov by searching for and locating Docket No. FAA–2021–0826.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0826; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the EASA AD, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Darren Gassetto, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228–7323; email Darren.Gassetto@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021–0066, dated March 8, 2021 (EASA AD 2021–0066), to correct an unsafe condition for Airbus Helicopters Deutschland GmbH (formerly Eurocopter Deutschland GmbH and Eurocopter España S.A.) Model EC135 P2+, EC135 P3, EC135 T2+, EC135 T3, EC635 P2+, EC635 P3, EC635 T1, EC635 T2+, and EC635 T3 helicopters, serial numbers (S/Ns) 0866 to 1166 inclusive, except S/Ns 1007, 1102, and 1145, and except helicopters on which Airbus Helicopters Service Bulletin EC135–85–063 has been embodied in service. Model EC635 P2+, EC635 P3, EC635 T1, EC635 T2+, and

EC635 T3 helicopters are not certificated by the FAA and are not included on the U.S. type certificate data sheet, except where the U.S. type certificate data sheet explains that the Model EC635T2+ helicopter having serial number 0858 was converted from Model EC635T2+ to Model EC135T2+. This AD, therefore, does not include Model EC635 P2+, EC635 P3, EC635 T1, EC635 T2+, and EC635 T3 helicopters in the applicability.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus Helicopters Deutschland GmbH Model EC135P2+, EC135P3, EC135T2+, and EC135T3 helicopters. The NPRM published in the **Federal Register** on September 23, 2021 (86 FR 52851). The NPRM was prompted by reports that aft and forward fitting assemblies, having part number L851M2810103, were installed as part of the outboard load system on helicopters having S/Ns 0886 and up. The affected fitting assemblies are not approved for installation on helicopters having those serial numbers. Operators of those helicopters might not be aware of the applicable overhaul or life limits for those fitting assemblies. The NPRM proposed to require inspecting the aft and forward fitting assemblies of the outboard load system to determine the part number, re-identifying the part if necessary, inspecting each affected part for damage (which may be indicated by signs of corrosion, mechanical damage, loose rivets, or cracks) and, depending on the findings, corrective actions, as specified in EASA AD 2021–0066.

The FAA is issuing this AD to address failure of affected aft and forward fitting assemblies and consequent loss of external cargo, resulting in personal injury or injury to persons on the ground. See EASA AD 2021–0066 for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these helicopters. Except for minor editorial changes, this AD is adopted as proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

EASA AD 2021–0066 requires a onetime inspection of each aft and forward fitting assembly of the outboard load system to identify the part number, re-identifying the part number if necessary, a one-time inspection of an affected fitting assembly for damage, and corrective action. The corrective action includes replacing any damaged fitting.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 69 helicopters of U.S. Registry. The FAA estimates the following costs to comply with this AD.

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection to determine fitting assembly part number.	0.50 work-hour × \$85 per hour = \$42.50	\$0	\$42.50	\$2,932.50

The FAA estimates the following costs to do any necessary actions that would be required based on the results

of the inspection. The agency has no way of determining the number of

helicopters that might need these actions:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Re-identification of affected fitting assembly with part number.	0.25 work-hour × \$85 per hour = \$21.25	\$0	\$21.25

ON-CONDITION COSTS—Continued

Action	Labor cost	Parts cost	Cost per product
Detailed inspection of affected fitting assembly	1.75 work-hours × \$85 per hour = \$148.75	0	148.75
Replacement of damaged affected fitting assembly	1.50 work-hours × \$85 per hour = \$127.50	1,363	1,490.50

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021–24–05 Airbus Helicopters

Deutschland GmbH: Amendment 39–21826; Docket No. FAA–2021–0826; Project Identifier MCAI–2021–00300–R.

(a) Effective Date

This airworthiness directive (AD) is effective January 14, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Deutschland GmbH Model EC135P2+, EC135P3, EC135T2+, and EC135T3 helicopters, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2021–0066, dated March 8, 2021 (EASA AD 2021–0066).

(d) Subject

Joint Aircraft Service Component (JASC) Code: 2550, Cargo Compartments.

(e) Unsafe Condition

This AD was prompted by reports that certain aft and forward fitting assemblies, which are not approved for installation on certain helicopters, were installed on those helicopters as part of the outboard load system. Operators of those helicopters might not be aware of the applicable overhaul or life limits for those fitting assemblies. The FAA is issuing this AD to address failure of affected aft and forward fitting assemblies and consequent loss of external cargo, resulting in personal injury or injury to persons on the ground.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2021–0066.

(h) Exceptions to EASA AD 2021–0066

- (1) Where EASA AD 2021–0066 requires compliance in terms of flight hours, this AD requires using hours time-in-service.

(2) Where EASA AD 2021–0066 refers to its effective date, this AD requires using the effective date of this AD.

(3) Where paragraph (4) of, and the service information referenced in, EASA AD 2021–0066, specify contacting Airbus Helicopters Deutschland GmbH for applicable instructions if any damage (which may be indicated by signs of corrosion, mechanical damage, loose rivets, or cracks) is found, the corrective action must be accomplished using a method approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; or EASA; or Airbus Helicopters Deutschland GmbH EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(4) Where the service information referenced in EASA AD 2021–0066 specifies to discard certain parts, this AD requires removing those parts from service.

(5) This AD does not mandate compliance with the "Remarks" section of EASA AD 2021–0066.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2021–0066 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the helicopter can be inspected (if the operator elects to do so), provided the outboard load system is not used until the applicable corrective actions required by paragraph (4) of EASA AD 2021–0066 are completed.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Darren Gassetto, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7323; email Darren.Gassetto@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0066, dated March 8, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0066, dated March 8, 2021, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0826.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on November 10, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-26679 Filed 12-9-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2021-0606; Project Identifier 2019-SW-070-AD; Amendment 39-21832; AD 2021-24-11]

RIN 2120-AA64

Airworthiness Directives; Leonardo S.p.a. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Leonardo S.p.a. Model A109E, A109S, and AW109SP helicopters. This AD was prompted by reports of main landing gear (MLG) wheel assembly failure. This AD requires repetitive inspections of each affected MLG strut assembly and, depending on the findings, replacement of an affected MLG strut assembly with a serviceable assembly, or application of corrosion preventive compound, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 14, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 14, 2022.

ADDRESSES: For EASA material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0606.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0606; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the EASA AD, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Darren Gassetto, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; telephone (516) 228-7323; email Darren.Gassetto@faa.gov.

SUPPLEMENTARY INFORMATION:**Background**

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019-0182, dated July 26, 2019 (EASA AD 2019-0182), to correct an unsafe condition for Leonardo S.p.A. Helicopters, formerly Finmeccanica S.p.A. Helicopter Division, AgustaWestland S.p.A., Agusta S.p.A., Model A109E, A109LUH, A109S, and AW109SP helicopters, all serial numbers. Model A109LUH helicopters are not certificated by the FAA and are not included on the U.S. type certificate data sheet; this AD therefore does not include those helicopters in the applicability. Although EASA AD 2019-0182 applies to Model A109E, A109S and AW109SP helicopters, all manufacturer serial numbers, this AD applies to helicopters with an affected assembly installed.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to Leonardo S.p.a. Model A109E, A109S, and AW109SP helicopters, certificated in any category, with an affected assembly as identified in EASA AD 2019-0182. The NPRM published in the **Federal Register** on July 30, 2021 (86 FR 40964). The NPRM was prompted by reports of MLG wheel assembly failure on Model A109E helicopters. Subsequent investigations identified stress corrosion and hydrogen embrittlement on the threaded end of the MLG strut, where lack of cadmium plating was observed, and determined that a certain batch of "enhanced" MLGs may be affected. Due to design similarity Model A109S and AW109SP helicopters are also affected. The NPRM proposed to require repetitive inspections of each affected MLG strut assembly and, depending on the findings, replacement of an affected MLG strut assembly with a serviceable assembly, or application of corrosion preventive compound, as specified in EASA AD 2019-0182.

The FAA is issuing this AD to address stress corrosion and hydrogen embrittlement on the threaded end of the MLG strut in the MLG wheel assembly. This condition, if not addressed, could lead to cracks on the affected MLG assembly, resulting in damage or failure of the MLG and consequent damage to the helicopter and injury to occupants. See EASA AD 2019-0182 for additional background information.