

(1) Is not a “significant regulatory action” under Executive Order 12866,

(2) Will not affect intrastate aviation in Alaska, and

(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022–03–11 Bombardier, Inc.: Amendment 39–21928; Docket No. FAA–2021–1014; Project Identifier MCAI–2021–00428–T.

(a) Effective Date

This airworthiness directive (AD) is effective March 17, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Bombardier, Inc., Model BD–100–1A10 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight controls.

(e) Unsafe Condition

This AD was prompted by a report that the design of the spoiler control system causes certain engine indication and crew alerting system (EICAS) messages to be posted intermittently and repetitively during flight and on the ground, and flightcrews must action the appropriate checklist each time these messages appear. The FAA is issuing this AD to address intermittent and repetitive messaging, which increases overall workload and introduces a risk that flightcrews could become desensitized over time to the messages. This could result in the required checklist not being carried out or completed, and could adversely affect the airplane’s continued safe flight and landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of the Airplane Flight Manual (AFM)

Within 60 days after the effective date of this AD: Revise the existing AFM to incorporate the information specified in Section 05–23, Flight Controls, of Chapter 05, Non-Normal Procedures, of the AFM revisions specified in paragraphs (g)(1) and (2) of this AD, as applicable.

(1) Bombardier Challenger 300 (Imperial Version) Airplane Flight Manual, Publication No. CSP 100–1, Revision 61, dated September 25, 2020.

Note 1 to paragraph (g)(1): For obtaining this section of the Bombardier Challenger 300 (Imperial Version) Airplane Flight Manual, Publication No. CSP 100–1, use Document Identification No. CH 300 AFM–I.

(2) Bombardier Challenger 350 Airplane Flight Manual, Publication No. CH 350 AFM, Revision 27, dated September 25, 2020.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.’s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) TCCA AD CF–2021–14, dated April 7, 2021, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–1014.

(2) For more information about this AD, contact Thomas Niczky, Aerospace Engineer, Avionics and Electrical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7347; fax 516–794–5531; email 9-avs-nyaco-cos@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Section 05–23, Flight Controls, of Chapter 05, Non-Normal Procedures, of the Bombardier Challenger 300 (Imperial Version) Airplane Flight Manual, Publication No. CSP 100–1, Revision 61, dated September 25, 2020.

(ii) Section 05–23, Flight Controls, of Chapter 05, Non-Normal Procedures, of the Bombardier Challenger 350 Airplane Flight Manual, Publication No. CH 350 AFM, Revision 27, dated September 25, 2020.

(3) For service information identified in this AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–2999; email ac.yul@aero.bombardier.com; internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on January 21, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–02755 Filed 2–9–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0886; Project Identifier MCAI–2021–00341–R; Amendment 39–21903; AD 2022–02–06]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus Helicopters Model EC120B helicopters. This AD was prompted by a report of geometrical non-conformities in the tail rotor blade (TRB) root section discovered during an accident investigation of a Model EC130B helicopter. Due to the similarity of design and production requirements, certain TRBs for the Model EC120B helicopters were inspected and

geometrical non-conformities were also found. This AD requires an inspection (dimensional check) to verify conformity, and replacement of certain TRBs if necessary, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 17, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 17, 2022.

ADDRESSES: For EASA material incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; internet: www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0886.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0886; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the EASA AD, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building

Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; phone: (516) 228-7330; email: andrea.jimenez@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021-0079, dated March 17, 2021 (EASA AD 2021-0079), to correct an unsafe condition for all Airbus Helicopters Model EC120B helicopters.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Helicopters Model EC120B helicopters. The NPRM published in the **Federal Register** on October 28, 2021 (86 FR 59653). The NPRM was prompted by a report of geometrical non-conformities in the TRB root section discovered during an accident investigation of a Model EC130B helicopter. Due to the similarity of design and production requirements, certain TRBs for the Model EC120B helicopters were inspected and geometrical non-conformities were also found. The NPRM proposed to require an inspection (dimensional check) to verify conformity, and replacement of certain TRBs if necessary, as specified in EASA AD 2021-0079.

The FAA is issuing this AD to detect and correct geometrical non-conformities of the TRB root section. The unsafe condition, if not addressed, could result in crack initiation and TRB failure, and possibly result in loss of control of the helicopter. See EASA AD

2021-0079 for additional background information.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these helicopters. Except for minor editorial changes, this AD is adopted as proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

EASA AD 2021-0079 requires an inspection (dimensional check) to verify TRB conformity, and replacement of certain TRBs if necessary. EASA AD 2021-0079 also prohibits rework, repair, or modification of affected parts in the critical section (affected area of the TRB assembly root).

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 89 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this AD.

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	4 work-hours × \$85 per hour = \$340	\$0	\$340	\$30,260

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the required inspection. The agency has no way of determining the

number of aircraft that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Blade Replacement	10 work-hours × \$85 per hour = \$850	\$4,000	\$4,850

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022-02-06 Airbus Helicopters:

Amendment 39-21903; Docket No. FAA-2021-0886; Project Identifier MCAI-2021-00341-R.

(a) Effective Date

This airworthiness directive (AD) is effective March 17, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus Helicopters Model EC120B helicopters, certificated in any category.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6410, Tail Rotor Blades.

(e) Unsafe Condition

This AD was prompted by a report of geometrical non-conformities in the tail rotor blade (TRB) root section discovered during an accident investigation of a Model EC130B helicopter. Due to the similarity of design and production requirements, certain TRBs for the Model EC120B helicopters were inspected and geometrical non-conformities were also found. The FAA is issuing this AD to detect and correct geometrical non-conformities of the TRB root section. The unsafe condition, if not addressed, could result in crack initiation and TRB failure, and possibly result in loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021-0079, dated March 17, 2021 (EASA AD 2021-0079).

(h) Exceptions to EASA AD 2021-0079

- (1) Where EASA AD 2021-0079 requires compliance in terms of flight hours, this AD requires using hours time-in-service.
- (2) Where EASA AD 2021-0079 refers to its effective date, this AD requires using the effective date of this AD.
- (3) Where the service information referenced in EASA AD 2021-0079 specifies discarding a part, this AD requires removing that part from service.
- (4) This AD does not mandate compliance with the "Remarks" section of EASA AD 2021-0079.
- (5) Where the service information referenced in EASA AD 2021-0079 specifies to measure using the Smartphone application, the PowerPoint method, or "Contacting customer support with a specific

procedure," this AD requires determining the specified measurements but those methods of measurement are not required by this AD.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2021-0079 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the actions of this AD can be performed, provided no passengers are onboard.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Andrea Jimenez, Aerospace Engineer, COS Program Management Section, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 1600 Stewart Ave., Suite 410, Westbury, NY 11590; phone: (516) 228-7330; email: andrea.jimenez@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2021-0079, dated March 17, 2021.

(ii) [Reserved]

(3) For EASA AD 2021-0079, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; internet: www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket

at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0886.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on January 7, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–02748 Filed 2–9–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0952; Project Identifier 2019–CE–039–AD; Amendment 39–21918; AD 2022–03–01]

RIN 2120–AA64

Airworthiness Directives; Diamond Aircraft Industries GmbH Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Diamond Aircraft Industries GmbH (DAI) Model DA 42, DA 42 M–NG, and DA 42 NG airplanes. This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as dissolved or detached fuel tank hose material entering the main fuel tank chambers, which could result in restricted fuel flow with consequent fuel starvation. This AD requires removing the fuel tank connection hoses from service and inspecting the fuel tank connection hoses for damage and detached rubber material. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 17, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 17, 2022.

ADDRESSES: For service information identified in this final rule, contact Diamond Aircraft Industries GmbH, N.A. Otto-Straße 5, A–2700 Wiener Neustadt, Austria; phone: +43 2622 26700; fax: +43 2622 26780; email:

office@diamond-air.at; website: <https://www.diamondaircraft.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0952.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0952; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the MCAI, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Penelope Trease, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 26805 E. 68th Avenue, Denver, CO 80249; phone: (303) 342–1094; fax: (303) 342–1088; email: penelope.trease@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to DAI Model DA 42, DA 42 M–NG, and DA 42 NG airplanes with a certain fuel tank connection hose installed. The NPRM published in the **Federal Register** on November 3, 2021 (86 FR 60600). The NPRM was prompted by MCAI originated by the European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union. EASA issued EASA AD 2019–0218, dated September 3, 2019 (referred to after this as “the MCAI”), to address an unsafe condition on certain DAI Model DA 42, DA 42M, DA 42 M–NG, and DA 42 NG airplanes. The MCAI states:

Reports were received of dissolved fuel tank connections hoses. Rubber parts were found within the fuel tank. The investigation results showed that the affected parts are limited to 2 isolated batches, some of which were installed on the production line. Other affected parts have been supplied as spare for in-service replacement.

This condition, if not corrected, could lead to restricted fuel flow from the tank, possibly

resulting in fuel starvation and consequent reduced control of the aeroplane.

To address this potential unsafe condition, DAI issued the applicable MSB [Mandatory Service Bulletin], providing instructions to identify and replace the affected parts. The applicable MSB identifies the MSN [manufacturer serial numbers] of the aeroplanes on which affected parts were installed during aeroplane production. The applicable MSB also indicates that any other aeroplane may be affected, if an affected part supplied as spare was installed.

For the reason described above, this [EASA] AD requires removal and replacement of the affected parts, and, if a removed affected part is found damaged, inspection of the fuel tank chambers and removal of any detached rubber material. This [EASA] AD also prohibits (re)installation of any affected parts.

You may examine the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0952.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. This AD is adopted as proposed in the NPRM, except for an editorial correction to the Applicability section. Paragraph (c)(1) states the AD applies to the airplanes in paragraph (c)(1) “or” paragraph (c)(2) when it should state the AD applies to airplanes identified in both paragraphs.

Related Service Information Under 14 CFR Part 51

The FAA reviewed Diamond Aircraft Mandatory Service Bulletin MSB 42–138/MSB 42NG–080, dated July 1, 2019 (issued as one document) published with Diamond Aircraft Work Instruction WI MSB 42–138/WI–MSB 42NG–080, Revision 0, dated July 1, 2019 (issued as one document) attached. This service information identifies the list of affected fuel tank connection hoses and also contains procedures for replacing the