

Proposed Rules

Federal Register

Vol. 86, No. 237

Tuesday, December 14, 2021

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-1070; Project Identifier 2020-CE-004-AD]

RIN 2120-AA64

Airworthiness Directives; Diamond Aircraft Industries GmbH Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Diamond Aircraft Industries GmbH (DAI) Model DA 42, DA 42 NG, and DA 42 M-NG airplanes. This proposed AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a loose rudder T-yoke axle nut. This proposed AD would require replacing the rudder T-yoke axle with an improved rudder T-yoke axle. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 28, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and

5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Diamond Aircraft Industries GmbH, N.A. Otto-Straße 5, A-2700 Wiener Neustadt, Austria; phone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; website: <https://www.diamondaircraft.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

Examining the AD Docket
You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1070; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the MCAI, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Penelope Trease, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 26805 E 68th Avenue, Denver, CO 80249; phone: (303) 342-1094; fax: (303) 342-1088; email: penelope.trease@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2021-1070; Project Identifier 2020-CE-004-AD" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The

agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Penelope Trease, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 26805 E 68th Avenue, Denver, CO 80249. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019-0302, dated December 13, 2019 (referred to after this as "the MCAI"), to address an unsafe condition on DAI Model DA 42, DA 42 M, DA 42 M-NG, and DA 42 NG airplanes. The MCAI states:

Occurrences were reported of finding a loose rudder T-yoke axle nut on DA 42 aeroplanes.

This condition, if not detected and corrected, could lead to vertical movement of the axle, possibly resulting in reduced rudder control of the aeroplane.

To address this potential unsafe condition, DAI issued the applicable MSB [Mandatory Service Bulletin], providing instructions to inspect for correct installation of the self-locking nut to the affected part.

For the reason described above, this [EASA] AD requires repetitive inspections for correct installation of the self-locking nut to the affected part and, depending on findings, accomplishment of applicable corrective action(s) and replacement of the self-locking

nut. This [EASA] AD also provides an optional terminating action for the repetitive inspections.

You may examine the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–1070.

Related Service Information Under 14 CFR Part 51

The FAA reviewed Diamond Aircraft Recommended Service Bulletin DAI RSB 42–139 and DAI RSB 42NG–081, dated October 21, 2019 (issued as one document), published with DAI Work Instruction WI–RSB 42–139 and WI–RSB 42NG–081, Revision 1, dated October 24, 2019 (issued as one document) attached. The service bulletin specifies complying with the work instruction, which contains procedures for replacing the rudder T-yoke axle with an improved (additional retaining pin) rudder T-yoke axle. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

FAA's Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is issuing this NPRM after determining the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require replacing the rudder T-yoke axle with an improved rudder T-yoke axle.

Differences Between This Proposed AD and the MCAI

The MCAI applies to the Model DA 42 M airplane and this proposed AD would not because it does not have an FAA type certificate.

The MCAI requires repetitively inspecting the self-locking nut until the rudder T-yoke axle is replaced with improved part number (P/N) D60–5320–00–32. This proposed AD would require installing rudder T-yoke axle P/N D60–5320–00–32 and would not have an inspection requirement.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 193 airplanes of U.S. registry. The FAA estimates that it would take about 6 work-hours to replace the rudder T-yoke axle and require parts costing \$166. The average labor rate is \$85 per work-hour. Based on these figures, the FAA estimates the cost of this proposed AD on U.S. operators to be \$130,468 or \$676 per airplane.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Diamond Aircraft Industries GmbH: Docket No. FAA–2021–1070; Project Identifier 2020–CE–004–AD.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by January 28, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Diamond Aircraft Industries GmbH Model DA 42, DA 42 NG, and DA 42 M–NG airplanes, serial numbers 42.004 through 42.391, 42.394 through 42.396, 42.399 through 42.402, 42.405 through 42.416, 42.427, 42.AC001 through 42.AC135, 42.AC137 through 42.AC145, 42.AC148, 42.AC150 through 42.AC152, 42.MN001 through 42.MN034, 42.MN037 through 42.MN042, 42.MN050 through 42.MN055, 42.MN057, 42.MN058, 42.MN100 through 42.MN103, 42.N001 through 42.N067, 42.N100 through 42.N250, 42.N300 through 42.N381, 42.N391, 42.NC001 through 42.NC004, and 42.NC006 through 42.NC008, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 5320, Fuselage Miscellaneous Structure.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a loose rudder T-yoke axle nut. The FAA is issuing this AD to prevent movement of the T-yoke axle. The unsafe condition, if not addressed, could result in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

- (1) Within 100 hours time-in-service after the effective date of this AD or 12 months after the effective date of this AD, whichever occurs first, replace rudder T-yoke axle part number (P/N) LN 9037–M6x90 with rudder T-yoke axle P/N D60–5320–00–32 in accordance with the Instructions, section III,

in Diamond Aircraft Work Instruction WI-RSB 42-139 and WI-RSB 42NG-081, Revision 1, dated October 24, 2019 (issued as one document) attached to Diamond Aircraft Recommended Service Bulletin DAI RSB 42-139 and DAI RSB 42NG-081, dated October 21, 2019.

(2) As of the effective date of this AD, do not install rudder T-yoke axle P/N LN 9037-M6x90 on any airplane.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Penelope Trease, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 26805 E 68th Avenue, Denver, CO 80249; phone: (303) 342-1094; fax: (303) 342-1088; email: Penelope.Trease@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2019-0302, dated December 13, 2019, for more information. You may examine the EASA AD in the AD docket at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2021-1070.

(3) For service information identified in this AD, contact Diamond Aircraft Industries GmbH, N.A. Otto-Straße 5, A-2700 Wiener Neustadt, Austria; phone: +43 2622 26700; fax: +43 2622 26780; email: office@diamond-air.at; website: <https://www.diamondaircraft.com>. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

Issued on December 8, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-26976 Filed 12-13-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2021-1031; Airspace Docket No. 21-ASO-14]

RIN 2120-AA66

Proposed Amendment and Removal of VOR Federal Airways V-18, V-115, V-222, V-241, V-245, V-311, V-321, V-325, V-333, V-415, V-417, and V-463 in the Southeastern United States

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to modify 7 VHF Omnidirectional Range (VOR) Federal Airways, (V-18, V-115, V-222, V-241, V-245, V-321, and V-333) and remove 5 VOR Federal Airways, (V-311, V-325, V-415, V-417, and V-463) in association with the Atlanta VOR Minimum Operation Network (MON) project in the southeastern United States. This action is necessary due to the planned decommissioning of the following five ground-based navigational aids (NAVAIDs): Dyersburg, TN, (DYR) VOR and Tactical Air Navigational System (VORTAC); Crimson, AL, (LDK) VORTAC; Malden, MO, (MAW) VORTAC; Monticello, AR, (MON) VOR/DME; and the Muscle Shoals, AL, (MSL) VOR/Distance Measuring Equipment (DME). This proposal would provide for the safe and efficient use of navigable airspace within the National Airspace System (NAS) while reducing NAVAID dependencies throughout the NAS as part of the FAA VOR MON program.

DATES: Comments must be received on or before January 28, 2022.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE, West Building Ground Floor, Room W12-140, Washington, DC 20590; telephone: 1 (800) 647-5527 or (202) 366-9826. You must identify FAA Docket No. FAA-2021-1031; Airspace Docket No. 21-ASO-14 at the beginning of your comments. You may also submit comments through the internet at <https://www.regulations.gov>. FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Rules and Regulations Group, Federal Aviation

Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. FAA Order JO 7400.11F is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order JO 7400.11F at NARA, email: fr.inspection@nara.gov or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would modify the VOR Federal airway route structure in the eastern United States to maintain the efficient flow of air traffic.

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal.

Communications should identify both docket numbers (FAA Docket No. FAA-2021-1031; Airspace Docket No. 21-ASO-14) and be submitted in triplicate to the Docket Management Facility (see **ADDRESSES** section for address and phone number). You may also submit comments through the internet at <https://www.regulations.gov>.

Commenters wishing the FAA to acknowledge receipt of their comments on this action must submit with those comments a self-addressed, stamped