

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus SAS: Docket No. FAA–2022–0382; Project Identifier MCAI–2021–01452–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by May 16, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS Model A350–941 and –1041 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Unsafe Condition

This AD was prompted by reports that passenger door stop screws were found with missing screw heads. The FAA is issuing this AD to address the missing door stop screw heads, which could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2021–0291, dated December 22, 2021 (EASA AD 2021–0291).

(h) Exceptions to EASA AD 2021–0291

(1) Where EASA AD 2021–0291 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Remarks” section of EASA AD 2021–0291 does not apply to this AD.

(3) Paragraph (4) of EASA AD 2021–0291 specifies to report results of the initial inspection to Airbus within a certain compliance time. For this AD, report inspection results of the initial inspection at the applicable time specified in paragraph (h)(3)(i) or (ii) of this AD.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(4) Where Note 2 of paragraph (2) of EASA AD 2021–0291 specifies using “the instructions from an applicable Airbus Repair Design Approval Form (RDAF)” is acceptable for compliance with the corrective actions, this AD requires using corrective actions approved using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(5) Where paragraph (2) of EASA AD 2021–0291 refers to passenger door stop screws that are “damaged, as defined in the SB” this AD defines damage as broken passenger door stop screws.

(6) Where service information referenced in EASA AD 2021–0291 specifies “a general visual inspection of the adjacent door stop area and surrounding structure (no lining removal required),” for this AD do a general visual inspection for any damage (e.g., broken passenger door stop screws), and repair any damage before further flight using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(i) Return of Parts

Although the service information referenced in EASA AD 2021–0291 specifies to send broken screws to Airbus, this AD does not include that requirement.

(j) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the airplane to a location where the actions of this AD can be performed (if the operator elects to do so), provided no passengers are onboard.

(k) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section,

International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (k)(2) of this AD, if any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(l) Related Information

(1) For EASA AD 2021–0291, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADS@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2022–0382.

(2) For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone and fax 206–231–3225; email dan.rodina@faa.gov.

Issued on March 24, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–06601 Filed 3–30–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2022–0387; Project Identifier AD–2021–01225–R]

RIN 2120–AA64

Airworthiness Directives; Bell Textron Inc., Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for

certain Bell Textron Inc., Model 212, 412, 412CF, and 412EP helicopters. This proposed AD was prompted by a report of a cracked check valve. This proposed AD would require inspecting certain engine oil and fuel check valves, and depending on the results, repetitively inspecting and removing the check valve from service. This proposed AD would also prohibit installing affected engine oil and fuel check valves on any helicopter. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by May 16, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bell Textron, Inc., P.O. Box 482, Fort Worth, TX 76101; telephone 1-450-437-2862 or 1-800-363-8023; fax 1-450-433-0272; email productsupport@bellflight.com; or at <https://www.bellflight.com/support/contact-support>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0387; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Kueth Harmon, Safety Management Program Manager, Certification & Program Management Section, DSCO Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5198; email kuethe.harmon@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2022-0387; Project Identifier AD-2021-01225-R” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Kueth Harmon, Safety Management Program Manager, Certification & Program Management Section, DSCO Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5198; email kuethe.harmon@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA proposes to adopt a new AD for Bell Textron Inc., Model 212, 412, 412CF, and 412EP helicopters with an engine oil check valve part number (P/

N) 209-062-520-001 or fuel check valve P/N 209-062-607-001 manufactured by Circor Aerospace that is marked “Circle Seal” and “CORONA CA,” and has a manufacturing date code of, or prior to, “9/11” (September 2011), or does not have a manufacturing date code, installed. This proposed AD would not apply to check valves marked with “TQL.” This proposed AD was prompted by a report of a cracked check valve manufactured in 2009 by Circor Aerospace. An incorrect torque value applied on the threaded fitting at the check valve inlet end during the assembly process resulted in the crack. Indication of this condition may also include an enlarged outside diameter (O.D.) measurement of the check valve housing at the inlet end where the threaded fitting is installed or a leak. These check valves may be installed as engine oil check valve P/N 209-062-520-001 and fuel check valve P/N 209-062-607-001 on Bell Textron Inc., Model 212, 412, 412CF, and 412EP helicopters.

The FAA previously issued AD 2019-09-02, Amendment 39-19636 (84 FR 22695, May 20, 2019), which applies to the same model helicopters with the same part-numbered check valves installed, except it is only for check valves marked “Circle Seal” and with a manufacturing date code of “10/11” (October 2011) through “03/15” (March 2015).

This condition, if not addressed, could result in loss of lubrication or fuel to the engine, failure of the engine or a fire, and subsequent loss of control of the helicopter.

FAA’s Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type designs.

Related Service Information

The FAA reviewed Bell Alert Service Bulletin (ASB) 212-20-163, Revision B, dated April 6, 2021 (ASB 212-20-163), Bell ASB 212-20-164, Revision B, dated April 6, 2021 (ASB 212-20-164), Bell ASB 412-20-182, Revision B, dated April 6, 2021 (ASB 412-20-182), and Bell ASB 412-20-183, Revision C, dated April 6, 2021 (ASB 412-20-183). ASB 212-20-163 and ASB 412-20-182 specify procedures for inspecting and replacing engine oil check valve P/N 209-062-520-001. ASB 212-20-164 and ASB 412-20-183 specify procedures for inspecting and replacing fuel check valve P/N 209-062-607-001.

Proposed AD Requirements in This NPRM

This proposed AD would require measuring the O.D. of an affected (engine oil or fuel) check valve housing at the center and at the inlet end where the threaded fitting is installed. If the dimension measured at the inlet end is greater than 0.003 inch (0.0762 mm) compared to the measurement at the center, this proposed AD would require repetitively inspecting the check valve for a crack and leak, and depending on the results, removing the check valve from service. This proposed AD would also require removing the check valve from service at a longer compliance time, which would terminate the repetitive inspections. Lastly, this proposed AD would prohibit installing affected check valves on any helicopter.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 169 helicopters of U.S. registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this proposed AD.

Measuring up to four check valves (two engine oil and two fuel) would take up to about 1 work-hour for an estimated cost of up to \$85 per helicopter and \$14,365 for the U.S. fleet. Inspecting up to four check valves (two engine oil and two fuel) would take up to about 2 work-hours for an estimated cost of up to \$170 per helicopter and \$28,730 for the U.S. fleet, per inspection cycle as applicable. Replacing up to four valves (two engine oil and two fuel) would take up to about 4 work-hours and parts would cost up to about \$340, for an estimated cost of up to \$680 per helicopter and \$114,920 for the U.S. fleet.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of

that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Bell Textron Inc.: Docket No. FAA-2022-0387; Project Identifier AD-2021-01225-R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by May 16, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bell Textron Inc., Model 212, 412, 412CF, and 412EP helicopters, certificated in any category, with an engine oil check valve part number (P/N) 209-062-520-001 or fuel check valve P/N 209-062-607-001 manufactured by Circor Aerospace that:

(1) Is marked "Circle Seal" and "CORONA CA," except not a check valve marked with "TQL," and

(2) Has a manufacturing date code of, or prior to, "9/11" (September 2011), or does not have a manufacturing date code, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 2800 Aircraft Fuel System and 7900 Engine Oil System (Airframe).

(e) Unsafe Condition

This AD was prompted by a report of a cracked check valve. The FAA is issuing this AD to detect a cracked check valve. The unsafe condition, if not addressed, could result in loss of lubrication or fuel to the engine, failure of the engine or a fire, and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within 25 hours time-in-service (TIS) or 30 days, whichever occurs first after the effective date of this AD, using a caliper or equivalent, measure the outside diameter (O.D.) of the check valve housing at the center, and the O.D. of the check valve housing at the inlet end where the threaded fitting is installed. If the dimension measured at the inlet end is greater than 0.003 inch (0.0762 mm) compared to the measurement at the center, do the following:

(i) Before further flight, and thereafter at intervals not to exceed 25 hours TIS or 30 days, whichever occurs first, using a flashlight, visually inspect the check valve for a crack and leak, paying particular attention to the area at the inlet end where the threaded fitting is installed. If there is a crack or leak, before further flight, remove the check valve from service. Removing the check valve from service terminates the repetitive inspections required by this AD for that check valve.

(ii) Within 600 hours TIS or 12 months, whichever occurs first, remove the check valve from service. Removing the check valve from service terminates the repetitive inspections required by this AD for that check valve.

(2) As of the effective date of this AD, do not install an engine oil or fuel check valve identified in paragraph (c) of this AD on any helicopter.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, DSCO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD. Information may be emailed to: 9-ASW-190-COS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact Kuethe Harmon, Safety Management Program Manager, Certification & Program Management Section, DSCO Branch, Compliance & Airworthiness Division, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5198; email kuethe.harmon@faa.gov.

Issued on March 25, 2022.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-06756 Filed 3-30-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HEALTH AND HUMAN SERVICES

Food and Drug Administration

21 CFR Part 15

[Docket No. FDA-2021-N-1326]

Scientific Data and Information Related to the Residue of Carcinogenic Concern for the New Animal Drug Carbadox; Public Hearing; Request for Comments; Extension of Comment Period

AGENCY: Food and Drug Administration, HHS.

ACTION: Notice of public hearing; request for comments; extension of comment period.

SUMMARY: The Food and Drug Administration (FDA, we, or Agency) is extending the comment period for the notice of public hearing that appeared in the **Federal Register** of January 13, 2022. In the notice, FDA requested comments on scientific data and information related to the residue of carcinogenic concern for the new animal drug carbadox. The Agency is taking this action in response to a request for an extension to allow interested persons additional time to submit comments.

DATES: FDA is extending the comment period on the notice published January 13, 2022 (87 FR 2093). Submit either electronic or written comments by June 10, 2022.

ADDRESSES: You may submit comments as follows. Please note that late, untimely filed comments will not be considered. Electronic comments must be submitted on or before June 10, 2022.

The <https://www.regulations.gov> electronic filing system will accept comments until 11:59 p.m. Eastern Time at the end of June 10, 2022. Comments received by mail/hand delivery/courier (for written/paper submissions) will be considered timely if they are postmarked or the delivery service acceptance receipt is on or before that date.

Electronic Submissions

Submit electronic comments in the following way:

- **Federal eRulemaking Portal:** <https://www.regulations.gov>. Follow the instructions for submitting comments. Comments submitted electronically, including attachments, to <https://www.regulations.gov> will be posted to the docket unchanged. Because your comment will be made public, you are solely responsible for ensuring that your comment does not include any confidential information that you or a third party may not wish to be posted, such as medical information, your or anyone else's Social Security number, or confidential business information, such as a manufacturing process. Please note that if you include your name, contact information, or other information that identifies you in the body of your comments, that information will be posted on <https://www.regulations.gov>.

- If you want to submit a comment with confidential information that you do not wish to be made available to the public, submit the comment as a written/paper submission and in the manner detailed (see "Written/Paper Submissions" and "Instructions").

Written/Paper Submissions

Submit written/paper submissions as follows:

- **Mail/Hand Delivery/Courier (for written/paper submissions):** Dockets Management Staff (HFA-305), Food and Drug Administration, 5630 Fishers Lane, Rm. 1061, Rockville, MD 20852.
- For written/paper comments submitted to the Dockets Management Staff, FDA will post your comment, as well as any attachments, except for information submitted, marked and identified, as confidential, if submitted as detailed in "Instructions."

Instructions: All submissions received must include the Docket No. FDA-2021-N-1326 for "Scientific Data and Information Related to the Residue of Carcinogenic Concern for the New Animal Drug Carbadox." Received comments, those filed in a timely manner (see **ADDRESSES**), will be placed in the docket and, except for those submitted as "Confidential Submissions," publicly viewable at

<https://www.regulations.gov> or at the Dockets Management Staff between 9 a.m. and 4 p.m., Monday through Friday, 240-402-7500.

- **Confidential Submissions**—To submit a comment with confidential information that you do not wish to be made publicly available, submit your comments only as a written/paper submission. You should submit two copies total. One copy will include the information you claim to be confidential with a heading or cover note that states "THIS DOCUMENT CONTAINS CONFIDENTIAL INFORMATION." The Agency will review this copy, including the claimed confidential information, in its consideration of comments. The second copy, which will have the claimed confidential information redacted/blacked out, will be available for public viewing and posted on <https://www.regulations.gov>. Submit both copies to the Dockets Management Staff. If you do not wish your name and contact information to be made publicly available, you can provide this information on the cover sheet and not in the body of your comments and you must identify this information as "confidential." Any information marked as "confidential" will not be disclosed except in accordance with 21 CFR 10.20 and other applicable disclosure law. For more information about FDA's posting of comments to public dockets, see 80 FR 56469, September 18, 2015, or access the information at: <https://www.govinfo.gov/content/pkg/FR-2015-09-18/pdf/2015-23389.pdf>.

Docket: For access to the docket to read background documents or the electronic and written/paper comments received, go to <https://www.regulations.gov> and insert the docket number, found in brackets in the heading of this document, into the "Search" box and follow the prompts and/or go to the Dockets Management Staff, 5630 Fishers Lane, Rm. 1061, Rockville, MD 20852, 240-402-7500.

FOR FURTHER INFORMATION CONTACT: Kelly Covington, Center for Veterinary Medicine (HFV-6), Food and Drug Administration, 7500 Standish Pl., Rockville, MD 20855, CarbadoxPublicHearing2022@fda.hhs.gov, 240-402-5661.

SUPPLEMENTARY INFORMATION: In the **Federal Register** of January 13, 2022, FDA published a notice announcing a public hearing on scientific data and information related to the residue of carcinogenic concern for the new animal drug carbadox, a carcinogenic new animal drug used in swine feed, with a 90-day comment period.