

05 Static Structures—Life Limits (TASK 05–11–05–200–801), of GE CF34–8C EM GEK105091, Rev 51, dated April 1, 2022 (GE CF34–8C EM GEK105091); and

(ii) Add TASK 05–21–03–200–801, dated April 1, 2019, from ESM 05–21–03 Airworthiness Limitations—Mandatory Inspection 001 (TASK 05–21–03–200–801), of GE CF34–8C EM GEK105091. Where the notes to Tables 801, 802, 803, 804, and 805, included in TASK 05–21–03–200–801 of GE CF34–8C EM GEK105091, specify to perform the inspection within 2,200 cycles from the issuance date of the TR, this AD requires performing the inspection within 2,200 cycles from the effective date of this AD.

(3) For combustion chamber assemblies with P/Ns 4145T11G08, 4145T11G10, 4180T27G02, 4180T27G04, or 4923T82G02 installed on GE CF34–8C5B1/B, CF34–8C5/B, CF34–8C5A1/B, or CF34–8C5A2/B model turbofan engines:

(i) Replace Table 801 (for/B –8C5) Static Structures—Life Limits with the revised Table 801 in TASK 05–11–25–200–801, of GE CF34–8C EM GEK105091; and

(ii) Add TASK–05–21–03–200–801, of GE CF34–8C EM GEK105091. Where the notes to Tables 801, 802, 803, 804, and 805, included in TASK 05–21–03–200–801 of GE CF34–8C EM GEK105091, specify to perform the inspection within 2,200 cycles from the issuance date of the TR, this AD requires performing the inspection within 2,200 cycles from the effective date of this AD.

(4) After performing the actions required by paragraphs (g)(1) through (3) of this AD, except as provided in paragraph (i) of this AD, no alternative life limits may be approved.

(h) Credit for Previous Actions

You may take credit for revising the ALS of the existing EM and the operator's existing approved maintenance or inspection program, as applicable, required by paragraphs (g)(1) through (3) of this AD if the actions were completed before the effective date of this AD using GE CF34–8E EM TR 05–0085, dated February 21, 2019; GE CF34–8C TR 05–0141, dated February 21, 2019; GE CF34–8C TR 05–0143, dated February 13, 2019; GE CF34–8E TR 05–0086, dated February 13, 2019; or GE CF34–8C TR 05–0142, dated February 13, 2019.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD and email it to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

For more information about this AD, contact Scott Stevenson, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7132; email: Scott.M.Stevenson@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) TASK 05–11–05–200–801, dated March 4, 2021, from ESM 05–11–05 Static Structures—Life Limits, of GE CF34–8C EM GEK105091, Rev 51, dated April 1, 2022.

(ii) TASK 05–11–05–200–801, dated March 4, 2021, from ESM 05–11–05 Static Structures—Life Limits, of GE CF34–8E EM GEK112031, Rev 43, dated April 1, 2022.

(iii) TASK 05–11–25–200–801, dated November 3, 2020, from ESM 05–11–25 Static Structures—BJ Life Limits, of GE CF34–8C EM GEK105091, Rev 51, dated April 1, 2022.

(iv) TASK 05–21–03–200–801, dated April 1, 2019, from ESM 05–21–03 Airworthiness Limitations—Mandatory Inspection 001, of GE CF34–8C EM GEK105091, Rev 51, dated April 1, 2022.

(v) TASK 05–21–03–200–801, dated April 1, 2019, from ESM 05–21–03 Airworthiness Limitations—Mandatory Inspection 001, of GE CF34–8E EM GEK112031, Rev 43, dated April 1, 2022.

(3) For GE service information identified in this AD, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215; phone: (513) 552–3272; email: aviation.fleetsupport@ge.com; website: ge.com.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on January 19, 2023.

Ross Landes,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–02512 Filed 2–6–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2022–0812; Project Identifier MCAI–2022–00445–T; Amendment 39–22208; AD 2022–21–09]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A300 B4–600, B4–600R, and F4–600R series airplanes, and Model A300 C4–605R Variant F airplanes (collectively called Model A300–600 series airplanes), and A310 series airplanes. This AD was prompted by a determination that a new airworthiness limitation is necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate a new airworthiness limitation, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 14, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publications listed in this AD as of March 14, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2022–0812; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADS@easa.europa.eu; website easa.europa.eu. You may find this IBR material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Airworthiness Products Section,

Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at *regulations.gov* under Docket No. FAA-2022-0812.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone 206-231-3225; email dan.rodina@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus SAS Model A300-600 and A310 series airplanes. The NPRM published in the **Federal Register** on July 8, 2022 (87 FR 40752). The NPRM was prompted by AD 2022-0060, dated April 1, 2022, issued by EASA, which is the Technical Agent for the Member States of the European Union (referred to after this as the MCAI). The MCAI states that a new airworthiness limitation is necessary. The FAA is issuing this AD to address safety-significant latent failures that would, in combination with one or more other specific failures or events, result in a hazardous or catastrophic failure condition of hydraulic systems.

In the NPRM, the FAA proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate a new airworthiness limitation, as specified in EASA AD 2022-0060.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2022-0812.

Discussion of Final Airworthiness Directive

Comments

The FAA received a comment from the Air Line Pilots Association, International, which supported the NPRM without change.

Conclusion

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered the comment received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is

issuing this AD to address the unsafe condition on this product. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Related Service Information Under 1 CFR Part 51

EASA AD 2022-0060 specifies procedures for a new airworthiness limitation for airplane hydraulic systems: Certification Maintenance Requirement (CMR) task 291000-00004-1-C "Main and Auxiliary (Hydraulic Power)—Functional Check of the 3 Hydraulic Reservoirs for Air Leakage."

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD would affect 120 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

The FAA has determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, the agency estimates the average total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2022-21-09 Airbus SAS: Amendment 39-22208; Docket No. FAA-2022-0812; Project Identifier MCAI-2022-00445-T.

(a) Effective Date

This airworthiness directive (AD) is effective March 14, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS airplanes identified in paragraphs (c)(1) through (5) of this AD, certificated in any category.

(1) Model A300 B4-601, B4-603, B4-620, and B4-622 airplanes.

(2) Model A300 B4-605R and B4-622R airplanes.

(3) Model A300 C4-605R Variant F airplanes.

(4) Model A300 F4-605R and F4-622R airplanes.

(5) Model A310-203, -204, -221, -222, -304, -322, -324, and -325 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Unsafe Condition

This AD was prompted by a determination that a new airworthiness limitation is necessary. The FAA is issuing this AD to address safety-significant latent failures that would, in combination with one or more other specific failures or events, result in a hazardous or catastrophic failure condition of hydraulic systems.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022-0060, dated April 1, 2022 (EASA AD 2022-0060).

(h) Exceptions to EASA AD 2022-0060

(1) The requirements specified in paragraphs (1) and (2) of EASA AD 2022-0060 do not apply to this AD.

(2) Paragraph (3) of EASA AD 2022-0060 specifies revising "the approved AMP" within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA AD 2022-0060 is at the applicable "threshold" as incorporated by the requirements of paragraph (3) of EASA AD 2022-0060, or within 90 days after the effective date of this AD, whichever occurs later.

(4) The provisions specified in paragraph (4) of EASA AD 2022-0060 do not apply to this AD.

(5) The "Remarks" section of EASA AD 2022-0060 does not apply to this AD.

(i) Provisions for Alternative Actions and Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (*e.g.*, inspections) and intervals are allowed unless they are approved as specified in the provisions of the "Ref. Publications" section of EASA AD 2022-0060.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft

Section, International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Additional Information

For more information about this AD, contact Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone and fax 206-231-3225; email dan.rodina@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2022-0060, dated April 1, 2022.

(ii) [Reserved]

(3) For EASA AD 2022-0060, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADS@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on October 3, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

Editorial Note: This document was received for publication by the Office of the Federal Register on February 2, 2023.

[FR Doc. 2023-02530 Filed 2-6-23; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2022-1412; Project Identifier MCAI-2022-00805-T; Amendment 39-22314; AD 2023-02-07]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A300 B2K-3C, B2-203, B4-2C, and B4-203 airplanes. This AD was prompted by a determination that internal system pollution can occur, most likely due to corroded unions in the pressurization lines, with an associated risk of contamination of the check valves. This AD requires repetitive inspections (functional checks) of the pressurization of the hydraulic system reservoirs, and corrective actions if necessary, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective March 14, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of March 14, 2023.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2022-1412; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADS@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Airworthiness Products Section,