

Proposed Rules

Federal Register

Vol. 87, No. 134

Thursday, July 14, 2022

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0875; Project Identifier MCAI-2022-00640-R]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters Deutschland GmbH (AHD) Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus Helicopters Deutschland GmbH (AHD) Model MBB-BK 117 C-2 helicopters. This proposed AD was prompted by reports of excessively worn bolts that connect the cardan-pivot joint with the piston rod of the tail rotor actuator (TRA) assembly. This proposed AD would require repetitively inspecting certain TRA assemblies, and depending on the results, replacing or repairing parts, or accomplishing additional inspections. This proposed AD would also prohibit installing an affected TRA assembly unless it passes required inspections. Lastly, this proposed AD would provide terminating actions for certain inspections, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD August 29, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For EASA material that is proposed for IBR in this NPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>. For Airbus Helicopters service information identified in this NPRM, contact Airbus Helicopters, 2701 North Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. The EASA material is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0875.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0875; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the EASA AD, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Hal Jensen, Aerospace Engineer, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 950 L'Enfant Plaza N SW, Washington, DC 20024; telephone (202) 267-9167; email hal.jensen@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed

under **ADDRESSES**. Include "Docket No. FAA-2022-0875; Project Identifier MCAI-2022-00640-R" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Hal Jensen, Aerospace Engineer, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 950 L'Enfant Plaza N SW, Washington, DC 20024; telephone (202) 267-9167; email hal.jensen@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued a series of EASA ADs, with the most recent being EASA AD 2022-0086, dated May 13, 2022 (EASA AD 2022-0086), to correct an unsafe condition for Airbus Helicopters

Deutschland GmbH (AHD), formerly Eurocopter Deutschland GmbH; and Airbus Helicopters Inc., formerly American Eurocopter LLC, Model MBB-BK117 C-2 helicopters. EASA issued EASA AD 2022-0086 to supersede EASA AD 2019-0313, dated December 20, 2019.

This proposed AD was prompted by reports of excessively worn bolts that connect the cardan-pivot joint with the piston rod of the TRA assembly. According to Airbus Helicopters, manufacturer investigations of affected TRAs have revealed improperly assembled cardan-pivot joints as the main cause of the excessively worn bolts. Additionally, incorrect washers as well as improperly shimmed laminated washers contribute to axial play and increased wear of the bolt. The FAA is proposing this AD to detect and prevent worn bolts. The unsafe condition, if not addressed, could result in helicopter oscillations on the yaw axis during flight, failure of a bolt resulting in loss of control of the tail rotor, and subsequent loss of control of the helicopter. See EASA AD 2022-0086 for additional background information.

Related Service Information Under 1 CFR Part 51

EASA AD 2022-0086 requires, for certain TRAs with a steel or aluminum cardan-pivot joint, repetitively measuring the minimum diameter of the cardan-pivot joint assembly bolt. Depending on the results, EASA AD 2022-0086 requires replacing the bolt and laminated washers of the affected TRA or repetitively measuring the minimum diameter of the cardan-pivot joint assembly bolt at a reduced compliance time; or contacting AHD for approved repair instructions and compliance time or measuring the maximum diameter of the TRA piston rod bore hole. Depending on the results of measuring the maximum diameter of the TRA piston rod bore hole, EASA AD 2022-0086 requires replacing the bolt and laminated washers of the affected TRA; or contacting AHD for approved repair instructions and compliance time or repetitively measuring the maximum diameter of the TRA piston rod bore hole at a reduced compliance time. EASA AD 2022-0086 also prohibits installing an affected TRA assembly unless it passes its required inspections. Lastly, EASA AD 2022-0086 specifies certain terminating actions for repetitively measuring the minimum diameter of the cardan-pivot joint assembly bolt.

This material is reasonably available because the interested parties have access to it through their normal course

of business or by the means identified in the **ADDRESSES** section.

Other Related Service Information

The FAA reviewed Airbus Helicopters Alert Service Bulletin MBB-BK117 C-2-67A-027, Revision 2, dated December 15, 2021. This service information specifies, for TRAs with a steel or aluminum cardan-pivot joint, procedures for measuring the minimum diameter of the cardan-pivot joint assembly bolt, measuring the maximum diameter of the TRA piston rod bore hole, replacing the bolt and laminated washers, and reassembling the TRA.

FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the European Union, EASA has notified the FAA about the unsafe condition described in its AD. The FAA is proposing this AD after evaluating all known relevant information and determining that the unsafe condition described previously is likely to exist or develop on other helicopters of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2022-0086, described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this proposed AD and except as discussed under "Differences Between this Proposed AD and the EASA AD."

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2022-0086 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2022-0086 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2022-0086 does not mean that operators need comply only with

that section. For example, where the AD requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in EASA AD 2022-0086. Service information referenced in EASA AD 2022-0086 for compliance will be available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0875 after the FAA final rule is published.

Differences Between This Proposed AD and the EASA AD

EASA AD 2022-0086 requires discarding certain parts, whereas this proposed AD would require removing those parts from service instead. EASA AD 2022-0086 requires maintaining a removed bolt for possible investigation purposes for four weeks, whereas this proposed AD would not require that action. EASA AD 2022-0086 requires contacting AHD for approved repair instructions and accomplishing those instructions within the compliance time specified therein, whereas this proposed AD would require accomplishing a repair in accordance with certain approved methods before further flight.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 142 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this proposed AD.

Measuring the cardan-pivot joint assembly bolt would take about 2 work-hours and have a nominal parts cost for an estimated cost of \$170 per helicopter and \$24,140 for the U.S. fleet, per inspection cycle. If required, measuring the TRA piston rod bore hole following the cardan-pivot joint assembly bolt inspection would take about an additional 0.5 work-hour for an estimated cost of \$43 per helicopter, per inspection cycle. Replacing a bolt and the laminated washers following an inspection would take about an additional 0.25 work-hour and parts would cost about \$586 for an estimated cost of \$607 per replacement.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus Helicopters Deutschland GmbH

(AHD): Docket No. FAA–2022–0875;
Project Identifier MCAI–2022–00640–R.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by August 29, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus Helicopters Deutschland GmbH (AHD) Model MBB–BK 117 C–2 helicopters, certificated in any category.

Note 1 to paragraph (c): Helicopters with an MBB–BK 117 C–2(e) designation are Model MBB–BK 117 C–2 helicopters.

(d) Subject

Joint Aircraft Service Component (JASC) Code: 6720, Tail Rotor Control System.

(e) Unsafe Condition

This AD was prompted by reports of excessively worn bolts that connect the cardan-pivot joint with the piston rod of the tail rotor actuator assembly. The FAA is issuing this AD to detect and prevent worn bolts. The unsafe condition, if not addressed, could result in helicopter oscillations on the yaw axis during flight, failure of a bolt resulting in loss of control of the tail rotor, and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2022–0086, dated May 13, 2022 (EASA AD 2022–0086).

(h) Exceptions to EASA AD 2022–0086

- (1) Where EASA AD 2022–0086 requires compliance in terms of flight hours, this AD requires using hours time-in-service (TIS).
- (2) Where EASA AD 2022–0086 refers to its effective date, this AD requires using the effective date of this AD.
- (3) Where Note 1 of EASA AD 2022–0086 allows a non-cumulative tolerance of 10% to the repetitive inspection intervals specified in its paragraphs (1), (2.2), and (5.2), this AD requires the repetitive inspection intervals specified in paragraphs (h)(3)(i) through (iii) of this AD.

(i) For the repetitive inspection interval specified in paragraph (1) of EASA AD 2022–0086, within intervals not to exceed 330 hours TIS.

(ii) For the repetitive inspection interval specified in paragraph (2.2) of EASA AD 2022–0086, within intervals not to exceed 165 hours TIS.

(iii) For the repetitive inspection interval specified in paragraph (5.2) of EASA AD 2022–0086, within intervals not to exceed 55 hours TIS.

(4) Where the service information referenced in EASA AD 2022–0086 specifies discarding parts, this AD requires removing those parts from service.

(5) Where the service information referenced in EASA AD 2022–0086 specifies maintaining a removed bolt for possible

investigation purposes for four weeks, this AD does not require that action.

(6) Where paragraphs (3.1) and (5.1) of EASA AD 2022–0086 specify contacting AHD for approved repair instructions and accomplishing those instructions within the compliance time specified therein, this AD requires, before further flight, repair done in accordance with a method approved by the Manager, General Aviation & Rotorcraft Section, International Validation Branch, FAA; EASA; or Airbus Helicopters Deutschland GmbH EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(7) This AD does not mandate compliance with the “Remarks” section of EASA AD 2022–0086.

(i) No Reporting Requirement

Although the service information referenced in EASA AD 2022–0086 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Special Flight Permit

A special flight permit may be issued in accordance with 14 CFR 21.197 and 21.199, provided that there are no passengers onboard.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For EASA AD 2022–0086, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find the EASA material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110. This material may be found in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2022–0875.

(2) For more information about this AD, contact Hal Jensen, Aerospace Engineer, Operational Safety Branch, Compliance & Airworthiness Division, FAA, 950 L’Enfant Plaza N SW, Washington, DC 20024; telephone (202) 267–9167; email hal.jensen@faa.gov.

Issued on July 8, 2022.

Christina Underwood,

*Acting Director, Compliance & Airworthiness
Division, Aircraft Certification Service.*

[FR Doc. 2022-15024 Filed 7-13-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Parts 91, 121, 125, and 135

[Docket No. FAA-2022-0912; Notice No. 22-04]

RIN 2120-AL36

Updating Manual Requirements To Accommodate Technology

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to update its manual requirements to reflect industry use of electronic and paper manuals. The amendments would apply to fractional ownership operations; domestic, flag, and supplemental operations; rules governing the operations of U.S.-registered civil airplanes which have a seating configuration of 20 or more passengers or a maximum payload capacity of 6,000 pounds or more when common carriage is not involved; and commuter and on-demand operations. The proposed action would require manuals accessed in paper format to display the date of last revision on each page, and require manuals accessed in electronic format to display the date of last revision in a manner in which a person can immediately ascertain it. This action would also revise the requirement for program managers or certificate holders to carry appropriate parts of the manual aboard airplanes during operations. This proposed rule would instead require program managers or certificate holders ensure the appropriate parts of the manual are accessible to flight, ground, and maintenance personnel when such personnel are performing their assigned duties. Lastly, the proposed rule would update outdated language that refers to accessing information in manuals kept in microfiche. The FAA proposes to remove this outdated language and simply require that all manual information and instructions be displayed clearly and be retrievable in the English language.

DATES: Send comments on or before September 12, 2022.

ADDRESSES: Send comments identified by docket number FAA-2022-0912 using any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov> and follow the online instructions for sending your comments electronically.

- **Mail:** Send comments to Docket Operations, M-30; U.S. Department of Transportation (DOT), 1200 New Jersey Avenue SE, Room W12-140, West Building Ground Floor, Washington, DC 20590-0001.

- **Hand Delivery or Courier:** Take comments to Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- **Fax:** Fax comments to Docket Operations at (202) 493-2251.

Privacy: In accordance with 5 U.S.C. 553(c), DOT solicits comments from the public to better inform its rulemaking process. DOT posts these comments, without edit, including any personal information the commenter provides, to www.regulations.gov, as described in the system of records notice (DOT/ALL-14 FDMS), which can be reviewed at www.dot.gov/privacy.

Docket: Background documents or comments received may be read at <https://www.regulations.gov> at any time. Follow the online instructions for accessing the docket or go to the Docket Operations in Room W12-140 of the West Building Ground Floor at 1200 New Jersey Avenue SE, Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

FOR FURTHER INFORMATION CONTACT: Sandra Ray, Voluntary Programs and Rulemaking Section, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591, telephone (412) 329-3088; email sandra.ray@faa.gov.

SUPPLEMENTARY INFORMATION:

I. Executive Summary

This rulemaking proposes several amendments in title 14, Code of Federal Regulations (14 CFR), parts 91 subpart K (part 91K), 121, 125, and 135 that would remove certain prescriptive manual requirements for certificate holders. First, this proposed rulemaking would amend §§ 91.1025, 121.135, 125.73, and 135.23 to remove the requirement to have the date of last revision on each page concerned as it applies to operators using electronic manuals. Further, this proposed rule would add a separate requirement to allow certificate holders using electronic manuals flexibility in

displaying the date of last revision, while maintaining the existing requirement for certificate holders with paper manuals.

In addition, this rulemaking proposes clarifying in §§ 91.1023, 121.139, and 135.21 that appropriate parts of the manual must be accessible on each aircraft when away from their principal base of operations, in lieu of indicating that manuals must exist in any particular format. This rulemaking would provide certificate holders flexibility regarding how their flight, ground, and maintenance personnel access electronic manuals, and to obtain information in a manner that reflects current technological capabilities.¹

Lastly, this rulemaking proposes amendments in §§ 91.1023, 121.139, 125.71, and 135.21 to update language that requires certificate holders accessing manuals in “other than printed form,” ensure there is a “compatible reading device available to those persons that provides a legible image” or “a system that is able to retrieve the maintenance information and instructions in the English language.” The FAA proposes to replace this outdated language with a requirement that all manual information and instructions be displayed clearly and be retrievable in the English language.

II. Authority for This Rulemaking

The FAA’s authority to issue rules on aviation safety is found in title 49 of the United States Code (U.S.C.). Subtitle I, section 106 describes the authority of the FAA Administrator. Section 106(f) vests final authority in the Administrator for carrying out all functions, powers, and duties of the Administrator relating to the promulgation of regulations and rules.

Subtitle VII, Aviation Programs, describes in detail the scope of the Agency’s authority. Section 44701(a)(5) requires the Administrator to promulgate regulations and minimum standards for other practices, methods, and procedures necessary for safety in air commerce and national security. In addition, 49 U.S.C. 44701(d)(1)(A) specifically states the Administrator, when prescribing safety regulations, must consider the duty of an air carrier to provide service with the highest possible degree of safety in the public interest. Such authority applies to the oversight the FAA exercises to ensure safety of aviation operations, including

¹ Other regulations, such as 14 CFR 91.9, contain language that does not preclude referring to or carrying manuals that exist in an electronic format. This proposed rule does not address such regulations.