

Sikorsky Aircraft Corporation

6900 Main Street P.O. Box 9729 Stratford, Connecticut 06615-9129 (203) 386-4000

S-92[®] HELICOPTER

ALERT SERVICE

BULLETIN

NOTICE TO ALL PERSONS RECEIVING THIS DOCUMENT:

WARNING: THIS DOCUMENT, OR AN EMBODIMENT OF IT IN ANY MEDIA, DISCLOSES INFORMATION WHICH IS PROPRIETARY, IS THE PROPERTY OF LOCKHEED MARTIN CORPORATION AND/OR ITS SUBSIDIARIES, IS AN UNPUBLISHED WORK PROTECTED UNDER APPLICABLE COPYRIGHT LAWS, AND IS DELIVERED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED, DISCLOSED, REPRODUCED, IN WHOLE OR IN PART (INCLIDING REPRODUCTION AS A DERIVATIVE WORK), OR USED FOR MANUFACTURE FOR ANYONE OTHER THAN LOCKHEED MARTIN CORPORATION AND/OR ITS SUBSIDIARIES WITHOUT ITS WRITTEN CONSENT, AND THAT NO RIGHT IS GRANTED TO DISCLOSE OR SO USE ANY INFORMATION CONTAINED HEREIN. ALL RIGHTS RESERVED. ANY ACT IN VIOLATION OF APPLICABLE LAW MAY RESULT IN CIVIL AND CRIMINAL PENALTIES.

S-92® IS A REGISTERED TRADEMARK OF SIKORSKY AIRCRAFT CORPORATION.

ASB 92-62-009

Basic Issue - February 6/19

SUBJECT: ROTORS – Main Rotor (MR) Swashplate Assembly – One-Time Visual Inspection of MR Stationary Swashplate Assembly for Cracks

Section 1. PLANNING INFORMATION

- A. Effectivity All MR stationary swashplate assemblies (92104-15011-042 or -043) with more than 1600 hours Time Since New (TSN), including spares.
- B. Purpose To provide instructions for a one-time inspection of MR stationary swashplate assembly for cracks.
- C. Background An occurrence of an in-service crack was reported on MR stationary swashplate assembly inner ring during a recurring inspection. An inspection has been developed to determine if cracks are present. If cracks are found, the swashplate assembly, uniball bearing, trunnions, and all attachment hardware shall be returned to Sikorsky for further investigation.
- D. Description Helicopter is prepared for inspection. Visual inspection of MR stationary swashplate assembly is performed. If cracks are found, swashplate assembly is removed and replaced and Sikorsky Customer Service Engineering is contacted. If any other damage is found, Sikorsky Customer Service Engineering is contacted with damage information. Helicopter is returned to service.
- E. Compliance Compliance is essential. The inspection outlined herein shall be accomplished within 50 flight hours or no later than February 13, 2019, whichever occurs first.

S-92 ALERT SERVICE BULLETIN

Section 1. PLANNING INFORMATION (Continued)

- F. Approval Inspection item.
- G. Manpower (Estimated)

<u>Task</u>	No. of Men	No. of Hours	Man-Hours*
Visual Inspection of MR Stationary Swashplate Assembly	1	0.5	<u>0.5</u>
Total Man-Hours			0.5
*Estimate de se met include time e required te			

*Estimate does not include time required to prepare helicopter or return it to flight status.

H. Tooling

None.

I. Weight and Balance

Not affected.

J. Electrical Load Data

Not affected.

K. Software Load Data

Not changed.

L. References

Maintenance Manual SA S92A-AMM-000, Tasks 62-31-01-900-001/-002.

- M. Publications Affected
 - (1) Temporary Revision 62-39 against Maintenance Manual, SA S92A-AMM-000, Task 62-31-00-215-001 will be released at a later date.
 - (2) Temporary Revision 62-40 against Maintenance Manual, SA S92A-AMM-000, Task 62-31-01-210-001 will be released at a later date.
- N. Attachment

None.

Section 2. MATERIAL INFORMATION

A. Basis for Material Data

Per helicopter.

B. Bill of Material

None.

C. Consumable Material

None.

Section 3. ACCOMPLISHMENT INSTRUCTIONS

A. Prepare helicopter for inspection:



TO PREVENT ELECTRICAL SHOCK OF PERSONNEL OR POSSIBLE DAMAGE TO HELICOPTER COMPONENTS, MAKE SURE TO TURN OFF ALL ELECTRICAL POWER.

- (1) Turn off all helicopter electrical and hydraulic power.
- (2) Engage rotor brake.

<u>NOTE:</u> Disassembly of swashplate assembly is not required. All visual inspections shall be conducted with trunnions and hardware in place.

- B. Visually inspect MR stationary swashplate assembly as follows:
 - (1) If necessary, disengage rotor brake, rotate MR to improve accessibility, and reengage rotor brake.
 - (2) Inspect around entire circumference of upper and lower surfaces of MR stationary swashplate assembly inner ring and upper and lower surfaces of trunnion attachment areas for cracks. (Refer to Figure 1).
 - (a) If cracks are found, remove swashplate assembly from service and install serviceable swashplate assembly. (Refer to Maintenance Manual SA S92A-AMM-000, Tasks 62-31-01-900-001/-002). Contact Sikorsky Customer Service Engineering at 1-800-WINGED-S or e-mail: wcs_cust_service_eng.grsik@lmco.com and proceed to step C.
 - (b) If nicks, dents, scratches, and/or any other damage is found, contact Sikorsky Customer Service Engineering at 1-800-WINGED-S or e-mail: wcs_cust_service_eng.gr-sik@Imco.com and provide location, size (length, width, and depth) and photos of damage for disposition. After performing disposition, proceed to step C.
 - (c) If no cracks, nicks, dents or any other damage is found, proceed to step C.




S-92 ALERT SERVICE BULLETIN

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)


- C. Record Alert Service Bulletin (ASB) inspection on component log card for swashplate assembly (92104-15000-043/-044).
- D. Return helicopter to service.

Page 4	ATA 62-31-01	ONE-TIME INSPECTION









SECTION A-A INNER RING INSPECTION LOCATION (TRUNNION NOT SHOWN FOR CLARITY)

TD4825

MR STATIONARY SWASHPLATE ASSEMBLY INSPECTION LOCATIONS FIGURE 1



This file contains export controlled information. See WARNING on first page.

S-92 ALERT SERVICE BULLETIN

Section 3. ACCOMPLISHMENT INSTRUCTIONS (Continued)

- E. Record of compliance:
 - (1) Make helicopter logbook entries to show compliance with this ASB as follows:
 - (a) Make helicopter level logbook entry on form SA7343-15 (Aircraft ASB Release Signoff).
 - (b) When ASB modifies a component that can be removed from this helicopter:
 - 1. Make component log card entries on forms SA7343-22 (Aircraft Component Log Cards) and SA7343-21 (Component Log Cards), as applicable.
 - 2. If a component modified by this ASB does not have a log card and the ASB does not create one, then annotate compliance on the next higher assembly that the component belongs to which does have a log card.
 - <u>NOTE:</u> If access to <u>www.Sikorsky360.com</u> is unavailable, complete attached ALERT SERVICE BULLETIN COMPLIANCE RECORD CARD and return it to Sikorsky Aircraft Corporation.
 - (2) Make an appropriate electronic compliance entry in the E-Notification section at <u>www.Sikorsky360.com</u>. Refer to User Guide located on the www.Sikorsky360.com/E-Notification Search page.

This file contains export controlled information. See WARNING on first page.

(Fold over and tape closed)

SIKORSKY AIRCRAFT CORPORATION

FACSIMILE NUMBER (817) 762-6715

EMAIL ADDRESS: product_safety.gr-sik@lmco.com

ATTENTION: Gr-SIK, Product_Safety SIKORSKY AIRCRAFT CORPORATION

-		,	y requests your cooperation y MAIL, FAX, or scan &
proper records doc	umenting the config	uration of your airc	he page, so we may maintain raft. This information is usefu es affecting fielded aircraft.
-		-	ar customers receive the latest ar aircraft. Thank you.
ALERT SERVICE	BULLETIN:	No. 92-62-009	Compliance Record Card
TITLE: <u>ROTORS</u>	Main Rotor (MR) Swa	ashplate Assembly – C	One-Time Visual Inspection
<u>of MR Sta</u>	ionary Swashplate As	sembly for Cracks	
OWNER/OPERAT	OR:		
SUBMITTED BY:		DATI	E:
FOLLOWIN	G SERIAL NUMBEI	RS ARE <u>NOT</u> AFFE	CTED BY THIS ASB
ASB <u>HAS BE</u>	<u>EN COMPLIED</u> WI	TH ON HELICOPT	ER SERIAL NUMBERS:

This file contains export controlled information. See WARNING on first page.



No Postage Necessary

BUSINESS REPLY MAIL FIRST-CLASS MAIL PERMIT NO. 432 BRIDGEPORT CT

POSTAGE WILL BE PAID BY ADDRESSEE

SIKORSKY AIRCRAFT CORPORATION

Commercial Systems and Services Mailstop K100 124 QUARRY ROAD TRUMBULL, CT 06611 U.S.A. ATTENTION: Gr-SIK, Product_Safety

Please complete the form on the reverse side and FAX to FACSIMILE NUMBER (817) 762-6715

Or scan and email to: EMAIL ADDRESS: product_safety.gr-sik@lmco.com or fold and return ENTIRE form to Sikorsky Aircraft Corporation