Moines, WA 98198; phone 206–231–3986; email Courtney.K.Tuck@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 767–25–0539, Revision 2, dated January 27, 2023.

(ii) Boeing Special Attention Service Bulletin 767–25–0549, Revision 2, dated January 27, 2023.

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Boulevard, MC 110–SK57, Seal Beach, CA 90740–5600; phone 562–797–1717; website myboeingfleet.com.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on August 26, 2024.

Suzanne Masterson,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2024-20160 Filed 9-6-24; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2024-1896; Project Identifier MCAI-2023-00978-T]

RIN 2120-AA64

Airworthiness Directives; MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier Inc.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking

(NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain MHI RJ Aviation ULC Model CL–600–2B19 (Regional Jet Series 100 and 440), CL–600–2C10 (Regional Jet Series 700, 701, and 702), CL–600–2C11 (Regional Jet Series 550), CL–600–2D15 (Regional Jet Series 705), CL–600–2D24

(Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000) airplanes. AD 2023-10-02 was prompted by the determination that radio altimeters cannot be relied on to perform their intended function if they experience interference from wireless broadband operations in the 3.7–3.98 GHz frequency band (5G C-Band). This AD was prompted by the determination that this interference can also result in certain failure messages being inhibited longer than intended. This proposed AD would require installing a new radio frequency (RF) bandpass filter on the coaxial line between the radio altimeter and the receive antenna in the aft equipment compartment. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by October 24, 2024

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.
 - Fax: 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M— 30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2024–1896; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For MHI RJ material identified in this proposed AD, contact MHI RJ Aviation Group, Customer Response Center, 3655 Ave. des Grandes-Tourelles, Suite 110, Boisbriand, Québec J7H 0E2 Canada; North America toll-free telephone 833–990–7272 or direct-dial telephone 450–990–7272; fax 514–855–8501; email thd.crj@mhirj.com; website mhirj.com.
- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

FOR FURTHER INFORMATION CONTACT:

Steven Dzierzynski, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email *9-avs-nyaco-cos@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under ADDRESSES. Include "Docket No. FAA-2024-1896; Project Identifier MCAI-2023-00978-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Steven Dzierzynski, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email 9-avs-nyaco-cos@faa.gov. Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2023-10-02, Amendment 39-22438 (88 FR 34065, May 26, 2023) (AD 2023-10-02) to address the effect of interference from wireless broadband operations in the 5G C-Band on all transport and commuter category airplanes equipped with a radio altimeter. AD 2023-10-02 was prompted by a determination that radio altimeters cannot be relied upon to perform their intended function if they experience interference from wireless broadband operations in the 5G C-Band. AD 2023-10-02 requires revising the limitations section of the existing airplane flight manual to incorporate limitations prohibiting transport and commuter category airplanes from performing certain low-visibility landing operations at any airport unless they have upgraded their radio altimeters. Transport Canada, which is the aviation authority for Canada, issued corresponding Transport Canada AD CF-2023-46, dated June 30, 2023, to require similar limitations on flight operations requiring radio altimeter data in U.S. airspace affected by 5G C-Band wireless signals.

Additionally, Transport Canada has issued Transport Canada AD CF-2023-62R1, dated November 21, 2023 (referred to as "the MCAI"), for certain serial-numbered MHI RJ Aviation ULC Model CL-600-2B19 (Regional Jet Series 100 and 440), CL-600-2C10 (Regional Jet Series 700, 701, and 702), CL-600-2C11 (Regional Jet Series 550), CL-600-2D15 (Regional Jet Series 705), CL-600-2D24 (Regional Jet Series 900), and CL-600-2E25 (Regional Jet Series 1000) airplanes. The MCAI states that, in addition to the effects of 5G C-Band broadband interference identified in FAA AD 2023-10-02, MHI RJ has determined that 5G C-Band broadband interference can result in certain failure messages and aural alerts being inhibited longer than intended. Specifically, this can result in the inhibition of hydraulic system #3 and wing anti-ice overheat failure messages such that flightcrew are unable to perform appropriate airplane flight

manual (AFM) procedures in the time needed to prevent loss of elevator control due to hydraulic system overheat and wing structural damage due to wing anti-ice system overheat. This condition, if not corrected, could result in delayed flightcrew response leading to loss of continued safe flight and landing.

and landing.
The MCAI requires the installation of a new RF bandpass filter on the coaxial line between the radio altimeter and the receive antenna in the aft equipment compartment. For airplanes with a dual radio altimeter configuration, the MCAI requires a filter to be installed on both systems or on one system provided the second system is deactivated. When the airplane is modified as specified in the MCAI, the configuration with the RF bandpass filter installed has been determined to be "radio altimeter tolerant." The actions of the MCAI apply only to airplanes operating within the contiguous U.S. airspace.

The FAA is proposing this AD because radio altimeter anomalies can result in the inhibition of certain failure messages such that the flightcrew are unable to perform appropriate AFM procedures in the time needed to prevent loss of elevator control due to hydraulic system overheat and wing structural damage due to wing anti-ice system overheat, possibly resulting in delayed flightcrew response leading to loss of continued safe flight and landing.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2024–1896.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed MHI RJ Service Bulletins 601R–34–152, Revision D, dated May 11, 2023, and 670BA–34–054, dated February 20, 2023. This material specifies procedures for installing a new RF bandpass filter on the coaxial line between the radio altimeter and the receive antenna in the aft equipment compartment. These documents are distinct since they apply to different airplane models. This material is reasonably available because

the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA's Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the material referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in the material already described. This AD would not apply to airplanes that have been modified to be a radio altimeter tolerant airplane under the requirements of AD 2023–10–02.

Differences Between the MCAI and This NPRM

Although the actions of the MCAI apply only to Canadian-registered airplanes operating within the contiguous U.S. airspace, this proposed AD would apply to U.S.-registered airplanes operating in any airspace. The FAA has determined that the expansion of 5G C-band has occurred in other countries, such as Canada and Brazil, in which 5G C-band interference is expected.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect up to 873 airplanes of U.S. registry. However, many of these airplanes may already have a bandpass filter installed in compliance with AD 2023–10–02 and would not have any costs because of this proposed AD. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
58 work-hours × \$85 per hour = \$4,930	\$53,647	\$58,577	Up to \$51,137,721.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

MHI RJ Aviation ULC (Type Certificate Previously Held by Bombardier Inc.): Docket No. FAA–2024–1896; Project Identifier MCAI–2023–00978–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by October 24, 2024

(b) Affected ADs

None.

(c) Applicability

This AD applies to the MHI RJ Aviation ULC (Type Certificate previously held by Bombardier Inc.) airplanes identified in paragraphs (c)(1) through (6) of this AD, certificated in any category, that are equipped with a radio altimeter and not determined to be a radio altimeter tolerant airplane as defined in paragraph (g) of this AD

- (1) Model CL–600–2B19 (Regional Jet Series 100 and 440) airplanes, serial number (S/N) 7002 through 8113.
- (2) Model CL–600–2C10 (Regional Jet Series 700, 701, and 702) airplanes, S/N 10002 through 10999.
- (3) Model CL–600–2C11 (Regional Jet Series 550) airplanes, S/N 10002 through 10999.
- (4) Model CL–600–2D15 (Regional Jet Series 705) airplanes, S/N 15001 through 15990.
- (5) Model CL–600–2D24 (Regional Jet Series 900) airplanes, S/N 15001 through 15000

(6) Model CL-600-2E25 (Regional Jet Series 1000) airplanes, S/N 19013 through 19990.

(d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

(e) Unsafe Condition

This AD was prompted by the determination that radio altimeters cannot be relied upon to perform their intended function if they experience interference from wireless broadband operations in the 3.7-3.98 GHz frequency band (5G C-Band). The FAA is issuing this AD because radio altimeter anomalies can result in the inhibition of certain failure messages such that the flightcrew are unable to perform appropriate airplane flight manual procedures in the time needed to prevent loss of elevator control due to hydraulic system overheat and wing structural damage due to wing anti-ice system overheat, possibly resulting in delayed flightcrew response leading to loss of continued safe flight and landing.

(f) Compliance


Comply with this AD within the compliance times specified, unless already done.

(g) Definitions

For purposes of this AD, a "radio altimeter tolerant airplane" is one for which the radio altimeter, as installed, demonstrates the tolerances specified in paragraphs (g)(1) and (2) of this AD, using a method approved by the FAA. No actions are required by this AD for radio altimeter tolerant airplanes.

(1) Tolerance to radio altimeter interference, for the fundamental emissions (3.7–3.98 GHz), at or above the power spectral density (PSD) curve threshold specified in figure 1 to paragraph (g)(1) of this AD.

Figure 1 to Paragraph (g)(1)—Fundamental Effective Isotropic PSD at Outside Interface of Airplane Antenna




Effective Isotropic PSD (dBm/MHz)
-5
-5
-10
-17
-22
-33
-47

(2) Tolerance to radio altimeter interference, for the spurious emissions (4.2–4.4 GHz), at or above the PSD curve threshold

specified in figure 2 to paragraph (g)(2) of this AD.

Figure 2 to Paragraph (g)(2)—Spurious Effective Isotropic PSD at Outside Interface of Airplane Antenna



Airplane Altitude (ft AGL)	Effective Isotropic PSD (dBm/MHz)		
1	-116.50		
400	-116.50		
500	-126.00		
1000	-139.00		
2000	-147.00		
3000	-151.00		
5000	-156.00		

(h) Filter Installation: Model CL-600-2B19

For Model CL–600–2B19 airplanes: Within 2,300 flight hours or 12 months after the effective date of this AD, whichever occurs first, install a radio frequency (RF) bandpass filter on each radio altimeter in accordance with the applicable parts of the Accomplishment Instructions in MHI RJ Service Bulletin 601R–34–152, Revision D, dated May 11, 2023. Alternatively, airplanes with a dual radio altimeter configuration may comply with this paragraph by installing an RF bandpass filter on one radio altimeter and deactivating the second radio altimeter in accordance with the applicable parts of the Accomplishment Instructions in MHI RJ

Service Bulletin 601R–34–152, Revision D, dated May 11, 2023.

(i) Filter Installation: Model CL-600–2C10, CL-600–2C11, CL-600–2D15, and CL-600–2D24

For Model CL–600–2C10, CL–600–2C11, CL–600–2D15, and CL–600–2D24 airplanes: Within 2,100 flight hours or 12 months after the effective date of this AD, whichever occurs first, install an RF bandpass filter on each radio altimeter in accordance with the applicable parts of the Accomplishment Instructions in MHI RJ Service Bulletin 670BA–34–054, dated February 20, 2023. Alternatively, airplanes with a dual radio altimeter configuration may comply with this

paragraph by installing an RF bandpass filter on one radio altimeter and deactivating the second radio altimeter in accordance with the applicable parts of the Accomplishment Instructions in MHI RJ Service Bulletin 670BA–34–054, dated February 20, 2023.

(j) Filter Installation: Model CL-600-2E25

For Model CL–600–2E25 airplanes: Before the next flight in the contiguous U.S. airspace after the effective date of this AD, install an RF bandpass filter on each radio altimeter in accordance with the applicable parts of the Accomplishment Instructions in MHI RJ Service Bulletin 670BA–34–054, dated February 20, 2023.

(k) Credit for Previous Actions

For Model CL–600–2B19 airplanes: This paragraph provides credit for the actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD using the material in paragraphs (k)(1) through (4) of this AD, provided the electrical idents for coax cables are installed using Part G of the Accomplishment Instructions in MHI RJ Service Bulletin 601R-34-152, Revision D, dated May 11, 2023, within the compliance time specified in paragraph (h) of this AD.

- (1) MHI RJ Service Bulletin 601R-34-152, dated February 14, 2023.
- (2) MHI RJ Service Bulletin 601R-34-152, Revision A, dated February 28, 2023.
- (3) MHI RJ Service Bulletin 601R-34-152, Revision B, dated March 28, 2023.
- (4) MHI RJ Service Bulletin 601R-34-152, Revision C, dated April 20, 2023.

(I) Additional AD Provisions

The following provisions also apply to this

- (1) Alternative Methods of Compliance (AMOCs): The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (m) of this AD. Information may be emailed to: 9-AVS-NYACO-COS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.
- (2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or MHI RJ Aviation ULC's Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(m) Additional Information

For more information about this AD, contact Steven Dzierzynski, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; email 9-avs-nyaco-cos@faa.gov.

(n) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (i) MHI RJ Service Bulletin 601R-34-152, Revision D, dated May 11, 2023.
- (ii) MHI RJ Service Bulletin 670BA-34-054, dated February 20, 2023.
- (3) For MHI RJ material identified in this AD, contact MHI RJ Aviation Group, Customer Response Center, 3655 Ave. des Grandes-Tourelles, Suite 110, Boisbriand,

Québec J7H 0E2 Canada; North America tollfree telephone 833–990–7272 or direct-dial telephone 450-990-7272; fax 514-855-8501; email thd.crj@mhirj.com; website mhirj.com.

- (4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.
- (5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ ibr-locationsoremailfr.inspection@nara.gov.

Issued on August 28, 2024.

Victor Wicklund.

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2024-20244 Filed 9-5-24: 11:15 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2024-2137; Project Identifier AD-2023-00297-T]

RIN 2120-AA64

Airworthiness Directives; The Boeing **Company Airplanes**

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking

(NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2019-22-02, which applies to all The Boeing Company Model 747–200B, 747– 200C, 747-200F, 747-300, 747-400, 747-400D, 747-400F, 747-8F, and 747-8 series airplanes. AD 2019–22–02 was prompted by reports of uncommanded fore and aft movement of the Captain's and First Officer's seats. AD 2019–22–02 requires identifying the part number, and the serial number if applicable, of the Captain's and First Officer's seats, and applicable on-condition actions for affected seats. AD 2019–22–02 also requires a one-time detailed inspection and repetitive checks of the horizontal movement system (HMS) of the Captain's and First Officer's seats, and applicable on-condition actions. AD 2019-22-02 also provides an optional terminating action for the repetitive actions for certain seats. Since the FAA issued AD 2019-22-02, the FAA has determined that additional seats are affected by the unsafe condition. This proposed AD would retain the actions required by AD 2019-22-02 and adds an inspection of previously omitted part

numbers. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by October 24,

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.
 - Fax: 202–493–2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2024-2137; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference: For Boeing material identified in

this proposed AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminster Boulevard, MC 110-SK57, Seal Beach, CA 90740-5600; phone 562-797-1717; website myboeingfleet.com.

 You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at regulations.gov by searching for and locating Docket No. FAA-2024-2137.

FOR FURTHER INFORMATION CONTACT:

Courtney Tuck, Aviation Safety Engineer, FAA, 2200 South 216th Street, Des Moines, WA 98198; phone 206-231–3986; email Courtney.K.Tuck@ faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed $under \ \textbf{ADDRESSES}. \ Include \ ``Docket \ No.$ FAA-2024-2137; Project Identifier AD-2023-00297-T" at the beginning of your comments. The most helpful comments