

Issued on April 1, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025–05852 Filed 4–1–25; 4:15 pm]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2024–2419; Project Identifier MCAI–2023–00366–R; Amendment 39–22992; AD 2025–06–04]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus Helicopters (Airbus) Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters. This AD was prompted by a manufacturer assessment that determined additional actions are necessary to improve particle detection for main gearboxes (MGBs) with certain planet gear bearings installed. This AD requires repetitively inspecting the MGB bevel wheel and the MGB magnetic plug for particles and prohibits installing an affected MGB unless certain requirements are met. These actions are specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective May 9, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 9, 2025.

ADDRESSES:

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2024–2419; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the EASA AD, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2024–2419.

FOR FURTHER INFORMATION CONTACT: Dan McCully, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (404) 474–5548; email: william.mccully@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters. The NPRM published in the **Federal Register** on November 5, 2024 (89 FR 87821). The NPRM was prompted by EASA AD 2023–0044, dated February 28, 2023, (EASA AD 2023–0044), issued by EASA, which is the Technical Agent for the Member States of the European Union. EASA advises that after a fleet design review for detection of particles in the MGB, it was determined that additional maintenance actions are necessary to improve detection of particles in the MGB.

In the NPRM, the FAA proposed to require repetitively inspecting the MGB bevel wheel for the presence of particles, repetitively inspecting the MGB magnetic plug for particles, close monitoring of the MGB magnetic plug if it has particles, and replacing the epicyclic module if necessary. The NPRM also proposed to prohibit installing an affected MGB unless certain requirements are met. The FAA is issuing this AD to detect and correct the presence of particles in the MGB, which if not addressed, could result in reduced or loss of control of the helicopter.

You may examine EASA AD 2023–0044 in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2024–2419.

Discussion of Final Airworthiness Directive

Comments

The FAA received no comments on the NPRM or on the determination of the costs.

Conclusion

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the EASA AD referenced above. The FAA reviewed the relevant data and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Material Incorporated by Reference Under 1 CFR Part 51

EASA AD 2023–0044 requires repetitive borescope visual inspections of the bevel wheel of the affected MGB for particles, collecting and analyzing any found particles, and depending on the results, further actions, accomplishing corrective action in accordance with the ASB defined within, or contacting AH [Airbus Helicopters] for further corrective action. EASA AD 2023–0044 also requires accomplishing a borescope visual inspection of the bevel wheel of the affected MGB for particles following the detection of any particles at the MGB magnetic plug during accomplishment of certain maintenance tasks and depending on the results, taking corrective action. Lastly, EASA AD 2023–0044 prohibits installing an affected MGB on any helicopter unless it is a serviceable part as defined within and certain requirements are met.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Differences Between this AD and EASA AD 2023–0044

EASA AD 2023–0044 applies to Model AS350BB helicopters, whereas this AD does not because that model is not FAA-type certificated.

Where Note 1 in the material referenced in EASA AD 2023–0044 specifies the option of 1 mechanical technician and 1 crew member, for this

AD, the pilot is only permitted to turn the tail rotor (b) because the other actions specified in the note must be accomplished by persons authorized under 14 CFR 43.3. Therefore, for the purpose of this AD, the owner/operator (pilot) may turn the tail rotor (b) and must enter compliance with the applicable paragraph of this AD in the helicopter maintenance records in accordance with 14 CFR 43.9(a) and 91.417(a)(2)(v). The pilot may perform this action because it only involves turning the tail rotor (b). This action can be performed equally well by a pilot or a mechanic. This action is an exception to the FAA's standard maintenance regulations.

This AD does not require complying with paragraph (2) of EASA AD 2023–0044. Instead, this AD requires repetitively inspecting the MGB magnetic plug for particles and, if there is any particle, accomplishing a borescope visual inspection, as specified in paragraphs (h)(6)(i) and (ii) of this AD.

Where the material referenced in EASA AD 2023–0044 specifies contacting Airbus Helicopters for a certain action, this AD requires accomplishing action in accordance with a method approved the FAA, EASA, or Airbus Helicopters' EASA Design Organization Approval.

Costs of Compliance

The FAA estimates that this AD affects 522 helicopters of U.S. Registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this AD.

A repetitive visual borescope inspection of the MGB bevel wheel will take 1 work-hour for an estimated cost of \$85 per helicopter and \$44,370 for the U.S. fleet, per inspection cycle.

If necessary, collecting and performing a metallurgical analysis of the detected particles will take 6 work-hours for an estimated cost of \$510 per helicopter, per analysis.

Repetitively inspecting the magnetic plugs of the MGB will take 1 work-hour for an estimated cost of \$85 per helicopter and \$44,370 for the U.S. fleet, per inspection cycle.

If required, close monitoring will take 2 work-hours for an estimated cost of \$170 per helicopter, per close monitoring cycle.

Accomplishing a visual borescope inspection of the MGB bevel wheel as a result of an MGB magnetic plug inspection will take 1 work-hour for an estimated cost of \$85 per helicopter.

If necessary, replacing an epicyclic module will take 56 work-hours and

parts will cost \$50,524 (overhauled) for an estimated cost of \$55,284 per module.

If necessary, replacing a bevel reduction module will take 56 work-hours and parts will cost \$18,500 (overhauled) for an estimated cost of \$23,260 per module.

Certain corrective action could vary significantly from helicopter to helicopter. The FAA has no data to determine the costs to accomplish the corrective action.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025–06–04 Airbus Helicopters:

Amendment 39–22992; Docket No. FAA–2024–2419; Project Identifier MCAI–2023–00366–R.

(a) Effective Date

This airworthiness directive (AD) is effective May 9, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus Helicopters Model AS350B, AS350B1, AS350B2, AS350B3, AS350BA, AS350D, AS355E, AS355F, AS355F1, AS355F2, AS355N, AS355NP, EC130B4, and EC130T2 helicopters, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code: 6320, Main Rotor Gearbox.

(e) Unsafe Condition

This AD was prompted by an assessment performed by the manufacturer which determined that additional actions are necessary to improve particle detection for main gearboxes (MGBs) with certain part-numbered planet gear bearings installed. The FAA is issuing this AD to detect and correct particles in the MGB. The unsafe condition, if not addressed, could result in reduced or loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency AD 2023–0044, dated February 28, 2023 (EASA AD 2023–0044).

(h) Exceptions to EASA AD 2023–0044

(1) Where EASA AD 2023–0044 defines "serviceable MGB" as "An affected MGB which has accumulated less than 330 flight hours (FH) since new (first installation on a helicopter), or since an overhaul, or since an inspection in accordance with the instructions of the ASB," this AD requires replacing that text with "An affected MGB which has accumulated less than 330 total hours time-in-service since new (zero total hours time-in-service), since last overhaul if

an overhaul has been accomplished, or since last inspection and any specified corrective action in accordance with the instructions of the ASB if an inspection and any specified corrective action by following the instructions of the ASB have been accomplished.”

(2) Where EASA AD 2023–0044 requires compliance in terms of flight hours, this AD requires using hours time-in-service (TIS).

(3) Where EASA AD 2023–0044 refers to its effective date, this AD requires using the effective date of this AD.

(4) Where Note 1 in the material referenced in paragraph (1) of EASA AD 2023–0044 specifies the option of 1 mechanical technician and 1 crew member, for this AD, the pilot is only permitted to turn the tail rotor (b). The owner/operator (pilot) holding at least a private pilot certificate may turn the

tail rotor (b) and must enter compliance with paragraph (g) of this AD in the helicopter maintenance records in accordance with 14 CFR 43.9(a) and 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.43. All other actions specified in Note 1 in the material referenced in paragraph (1) of EASA AD 2023–0044 must be accomplished by persons authorized under 14 CFR 43.3.

(5) Where Note 2 in the material referenced in paragraph (1) of EASA AD 2023–0044 specifies contacting Airbus Helicopters for further instructions if the bottom of the radius (a6) of the bevel wheel (a3) or head screws (a4) (see Figure 2) are not clearly visible, this AD requires, before further flight, accomplishing action in accordance with a method approved by the FAA, EASA, or Airbus Helicopters’ EASA Design

Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(6) Instead of complying with paragraph (2) of EASA AD 2023–0044, comply with the actions required by paragraphs (h)(6)(i) and (ii) of this AD.

(i) After the effective date of this AD, and within the compliance time intervals specified table 1 to paragraph (h)(6)(i) of this AD, visually inspect the MGB magnetic plug for particles.

Note 1 to paragraph (h)(6)(i): Aircraft Maintenance Manual (AMM) task 60–00–00, 6–2A, or AMM task 60–00–00, 6–2, or work card 60–00–00–602, as applicable, provides information regarding inspecting the MGB magnetic plug.

TABLE 1 TO PARAGRAPH (h)(6)(i)—MGB MAGNETIC PLUG INSPECTIONS

Helicopter model(s)	Initial compliance times (after the effective date of this AD) (hours TIS)	Interval compliance times (thereafter) (hours TIS)
AS350B, AS350B1, AS350BA, and AS350D	5	30
AS355E, AS355F, AS355F1, AS355F2, AS355N, and AS355NP	5	30
AS350B2 and AS350B3	10	100
EC130B4	5	150
EC130T2	5	150

(ii) If there is any particle as a result of any MGB magnetic plug inspection required by paragraph (h)(6)(i) of this AD, before further flight, borescope inspect the bevel wheel of the affected MGB for particles as required by paragraph (1) of EASA AD 2023–0044. If there is any particle as a result of the borescope inspection of the bevel wheel, before further flight, collect and analyze the particles as required by paragraph (3) of EASA AD 2023–0044.

(7) Where paragraph (3) of EASA AD 2023–0044 specifies “If, during any inspection as required by paragraph (1) or (2) of this AD,” this AD requires replacing that text with “If, during any inspection as required by paragraph (1) of this AD.”

(8) Where the material referenced in paragraph (3) of EASA AD 2023–0044 specifies performing a metallurgical analysis and contacting Airbus Helicopters if collected particles cannot be characterized with Work Card 20–08–01–601, this AD does not require contacting Airbus Helicopter but does require performing the metallurgical analysis.

(9) This AD does not allow the ferry flight provision specified in the material referenced in paragraph (3) of EASA AD 2023–0044; for this AD, refer to paragraph (j) of this AD.

(10) Where the material referenced in paragraph (3) of EASA AD 2023–0044 specifies contacting Airbus Helicopters if the damaged module cannot be identified, this AD requires, before further flight, accomplishing action in accordance with a method approved by the FAA, EASA, or Airbus Helicopters’ EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(11) Where paragraph (5) of EASA AD 2023–0044 states “to contact AH for

corrective action(s) instructions, and within the compliance time specified therein, to accomplish those instructions accordingly,” this AD requires replacing that text with “accomplishing corrective actions in accordance with a method approved by the FAA, EASA, or Airbus Helicopters’ EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.”

(12) Where paragraph (7) of EASA AD 2023–0044 states “since new (first installation a helicopter), or since an overhaul, or since an inspection in accordance with the instructions of the ASB, as applicable, and, thereafter, as required by this AD,” this AD requires replacing that text with “since new (zero total hours time-in-service), or since last overhaul if an overhaul has been accomplished, or since last inspection and any specified corrective action in accordance with the instructions of the ASB if an inspection and any specified corrective action by following the instructions of the ASB have been accomplished, and thereafter as required by this AD.”

(13) This AD does not adopt the “Remarks” section of EASA AD 2023–0044.

(i) No Reporting Requirement

Although the material referenced in EASA AD 2023–0044 specifies to submit certain information to the manufacturer, this AD does not require that action.

(j) Special Flight Permits

A special flight permit may be issued in accordance with 14 CFR 21.197 and 21.199 to permit a one-time, non-revenue flight to a location where the actions required by this AD can be accomplished. This flight must be performed with only essential flight crew.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local Flight Standards District Office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Dan McCully, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (404) 474–5548; email: william.mccully@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2023–0044, dated February 28, 2023.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3,

50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find the EASA material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on March 28, 2025.

Paul R. Bernado,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025-05781 Filed 4-3-25; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 117

[Docket No. USCG-2024-0628]

RIN 1625-AA09

Drawbridge Operation Regulation; Gulf Intracoastal Waterway, Osprey, FL

AGENCY: Coast Guard, DHS.

ACTION: Final rule.

SUMMARY: The Coast Guard is changing the operating schedule that governs the Blackburn Point Bridge across the Gulf Intracoastal Waterway (GICW), mile 63.1, at Osprey, FL. The Case Key Association has requested the Coast Guard consider changing the operating schedule to reduce drawbridge openings during the weekday peak traffic periods to assist with alleviating roadway congestion.

DATES: This rule is effective May 5, 2025.

ADDRESSES: To view documents mentioned in this preamble as being available in the docket, go to <https://www.regulations.gov>. Type the docket number (USCG-2024-0628) in the “SEARCH” box and click “SEARCH”. In the Document Type column, select “Supporting & Related Material.”

FOR FURTHER INFORMATION CONTACT: If you have questions on this rule, call or email mail Ms. Jennifer Zercher, Bridge Management Specialist, Seventh Coast Guard District; telephone 571-607-5951, email Jennifer.N.Zercher@uscg.mil.

SUPPLEMENTARY INFORMATION:

I. Table of Abbreviations

CFR Code of Federal Regulations
DHS Department of Homeland Security
FR Federal Register
OMB Office of Management and Budget
NPRM Notice of proposed rulemaking (advance, supplemental)
§ Section
U.S.C. United States Code
TD Temporary deviation
FL Florida
GICW Gulf Intracoastal Waterway

II. Background Information and Regulatory History

On August 6, 2024, the Coast Guard published a temporary deviation entitled “Drawbridge Operation Regulation; Gulf Intracoastal Waterway, Osprey, FL” in the **Federal Register** (89 FR 63815). The temporary deviation, effective from 7 a.m. on August 12, 2024, through 7 p.m. on January 31, 2025, allowed the Blackburn Point Bridge to operate with restricted, scheduled openings at peak traffic times during weekdays and operate on demand at all other times. The temporary deviation was authorized to test the impact of restricted opening on vessels and roadway traffic. The comment period for the temporary deviation ended September 20, 2024, with three comments received. Those comments were addressed in the notice of proposed rulemaking (NPRM) discussed next.

On January 8, 2025, the Coast Guard published an NPRM entitled “Drawbridge Operation Regulation; Gulf Intracoastal Waterway, Osprey, FL” in the **Federal Register** (90 FR 1402). There we stated why we issued the NPRM and invited comments on our proposed regulatory action related to this regulatory change. During the comment period that ended February 7, 2025, we received one comment, and that comment is discussed in section IV of this final rule.

III. Legal Authority and Need for Rule

The Coast Guard is issuing this rule under authority 33 U.S.C. 499.

Blackburn Point Bridge across the GICW, mile 63.1, at Osprey, FL, is a swing bridge with a 9-foot vertical clearance above mean high water when in the closed position. The existing general drawbridge regulation requires the bridge to open on demand any time a vessel requests an opening. The general drawbridge opening regulation can be found in 33 CFR 117.5.

The Coast Guard received a request from the Casey Key Association to consider changing the operating schedule for the Blackburn Point Bridge

by allowing the drawbridge scheduled openings instead of on demand openings. This request was made to assist with vehicle congestion during the weekday daylight hours.

IV. Discussion of Comments, Changes and the Final Rule

The Coast Guard provided a comment period of 30 days, and one comment was received. The comment received stated that bridges in general, should not impede navigation any time. The default operating regulation for moveable bridges across navigable waters of the United States is to open on demand. Coast Guard policy is to minimize the impact of drawbridge operations on waterway traffic, while considering the needs of other modes of transportation. The test deviation has determined that by allowing the bridge to open at designated times has provided vehicle congestion relief while not having an unreasonable impact on navigation.

The current operating schedule allows the Blackburn Point Bridge to open on demand for marine traffic. Under this rule, the swing bridge will open at the top of the hour, 20 minutes past the hour and 40 minutes past the hour, Monday through Friday between the hours of 7 a.m. and 7 p.m. if a vessel request an opening for safe navigation. At all other times the swing bridge will open on demand. Vessels that can pass beneath the bridge without an opening may do so at any time. Emergency vessels and tugs with tows can still request an opening at any time.

This rule adds one new special requirement to § 117.287 for the Gulf Intracoastal Waterway, the Blackburn Point Bridge at Osprey, FL. Additionally, this rule will republish § 117.287 to reorganize the paragraph structure to follow current regulatory drafting requirements.

V. Regulatory Analyses

We developed this rule after considering numerous statutes and Executive orders related to rulemaking. Below we summarize our analyses based on a number of these statutes and Executive orders.

A. Regulatory Planning and Review

Executive Orders 12866 and 13563 direct agencies to assess the costs and benefits of available regulatory alternatives and, if regulation is necessary, to select regulatory approaches that maximize net benefits. This rule has not been designated a “significant regulatory action,” under section 3(f) of Executive Order 12866. Accordingly, it has not been reviewed