words "egg/meat-type game bird, egg/meat-type waterfowl" in their place in the first sentence.

§146.6 [Amended]

- 28. Amend § 146.6 as follows:
- a. In paragraph (a), by removing the words "commercial upland game bird, commercial waterfowl" and adding the words "meat-type game bird, meat-type waterfowl" in their place; and
- b. In paragraph (b), by removing the words "commercial upland game bird and commercial waterfowl" and adding the words "meat-type game bird and meat-type waterfowl" in their place.

§146.9 [Amended]

- 29. Amend § 146.9, in paragraph (a), by removing the text "and (b)".
- 30. Amend Subpart E, consisting of §§ 146.51 to 146.53, by revising the subpart heading to read as follows:

Subpart E—Special Provisions for Egg/ Meat-Type Game Birds, Egg/Meat-Type Waterfowl, Meat-Type Game Bird Slaughter Plants, and Meat-Type **Waterfowl Slaughter Plants**

PART 147—AUXILIARY PROVISIONS ON NATIONAL POULTRY IMPROVEMENT PLAN

■ 31. The authority citation for part 147 continues to read as follows:

Authority: 7 U.S.C. 8301-8317; 7 CFR 2.22, 2.80, and 371.4.

■ 32. In § 147.46, revise paragraph (a)(9) to read as follows:

§ 147.46 Committee consideration of proposed changes.

(a) * * *

(9) Egg/meat-type game birds and waterfowl.

■ 33. In § 147.52, revise paragraph (f)(2) to read as follows:

§ 147.52 Authorized laboratories.

* * *

(f) * * *

(2) All Salmonella Pullorum and Mycoplasma Plan disease infected flocks as confirmed by testing in accordance with § 145.14 must be reported to the Official State Agency within 48 hours.

Done in Washington, DC, this 26th day of September 2025.

Michael Watson,

Administrator, Animal and Plant Health Inspection Service.

[FR Doc. 2025-19017 Filed 9-29-25; 8:45 am]

BILLING CODE 3410-34-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-1108; Project Identifier AD-2025-00428-R; Amendment 39-23140; AD 2025-18-13]

RIN 2120-AA64

Airworthiness Directives; Airbus **Helicopters**

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule; correction.

SUMMARY: The FAA is correcting an airworthiness directive (AD) that published in the **Federal Register**. That AD applies to certain Airbus Helicopters Model AS350B3, EC130B4, and EC130T2 helicopters. As published, a reference to a measurement in the regulatory text is incorrect. This document corrects that error. In all other respects, the original document remains the same.

DATES: This correction is effective October 23, 2025. The effective date of AD 2025-18-13 remains October 23,

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 23, 2025 (90 FR 44962, September 18, 2025).

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2025-1108, or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA. Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: *ADs@easa.europa.eu*; website: easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.
- You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N-321, Fort Worth, TX 76177. For information on the

availability of this material at the FAA, call (817) 222-5110. It is also available at regulations.gov under Docket No. FAA-2025-1108.

FOR FURTHER INFORMATION CONTACT: Zain Jamal, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (847) 294-7264; email: zain.jamal@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

Airworthiness Directive 2025-18-13, Amendment 39-23140 (90 FR 44962, September 18, 2025) (AD 2025-18-13), retains the actions required by AD 2020-24-07 and mandates an additional modification, which would constitute terminating action for the repetitive inspections for certain Airbus Helicopters Model AS350B3, EC130B4, and EC130T2 helicopters. This AD also expands the helicopter applicability, provides additional requirements for certain helicopters, and prohibits installing affected microswitches or an affected twist grip with the affected microswitch.

Need for the Correction

As published, a reference to a measurement specified in the regulatory text of AD 2025-18-13 is incorrect. Paragraph (h)(8) of AD 2025-18-13 defines a discrepancy as a "nut torque that is outside allowable torque limits, or clearance between the support plate assembly and the washers that is not within 01.mm to 0.3 mm", whereas it should state "nut torque that is outside allowable torque limits, or clearance between the support plate assembly and the washers that is not within 0.1 mm to 0.3 mm".

No other part of the preamble or regulatory information has been changed; for convenience, the entire rule is being republished.

The effective date of this AD remains October 23, 2025.

Material Incorporated by Reference **Under 1 CFR Part 51**

The FAA reviewed EASA AD 2023-0187R1, which specifies procedures for modifying the twist grip operational logic on helicopters with MOD 074263 installed. EASA AD 2023-0187R1 also specifies procedures for repetitively inspecting for no marks, residue, or corrosion and testing the "IDLE" and "FLIGHT" controls on the pilot's and copilot's twist grips on helicopters with MOD 074699 installed. Additionally, EASA AD 2023–0187R1 specifies procedures for installing MOD 074782 on helicopters if an affected microswitch is installed, which would constitute terminating action for the

repetitive inspections. For those helicopters with MOD 074782 installed, EASA AD 2023–0187R1 specifies accomplishing a one-time inspection of the installation of the microswitch assembly of the engine power control. EASA AD 2023–0187R1 also prohibits installing a microswitch having a part number (P/N) T3933–3 or a twist grip containing a microswitch having P/N T3933–3 on any helicopter.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) by correcting 90 FR 44962, September 18, 2025, beginning at page 44962, column 1 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Corrected]

■ 2. The FAA corrects § 39.13 by correcting the following airworthiness directive to read:

2025-18-13 Airbus Helicopters:

Amendment 39–23140; Docket No. FAA–2025–1108; Project Identifier MCAI–2025–00428–R.

(a) Effective Date

This airworthiness directive (AD) is effective October 23, 2025.

(b) Affected ADs

This AD replaces AD 2020–24–07, Amendment 39–21337 (85 FR 78954, December 8, 2020) (AD 2020–24–07).

(c) Applicability

This AD applies to Airbus Helicopters Model AS350B3, EC130B4, and EC130T2 helicopters, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 7600, Engine Controls.

(e) Unsafe Condition

This AD was prompted by reports of the of the engine remaining in idle when the throttle twist grip was turned from the "IDLE" mode to the "FLIGHT" mode. The FAA is issuing this AD to correct the failure of one of the microswitches, 53Ka, 53Kb, or 65K which can prevent the pilot from switching from "IDLE" mode to "FLIGHT" mode during autorotation training making it impossible to recover from a practice autorotation and compelling the pilot to continue the autorotation to the ground. This condition could result in unintended touchdown to the ground at a flight-idle power setting during a practice autorotation, damage to the helicopter, and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency AD 2023–0187R1, dated March 20, 2025 (EASA AD 2023–0187R1).

(h) Exceptions to EASA AD 2023-0187R1

- (1) Where EASA AD 2023–0187R1 refers to the effective dates identified in paragraphs (h)(1)(i) through (iii) of this AD, this AD requires using the effective date of this AD.
- (i) March 27, 2025 (the effective date of EASA AD 2023–0187R1).
- (ii) November 10, 2023 (the effective date of EASA AD 2023–0187, dated October 27, 2023).
- (iii) July 19, 2023 (the effective date of EASA AD 2023–0133, dated July 5, 2023).
- (2) Where EASA AD 2023–0187R1 refers to April 13, 2017 (the effective date of EASA AD 2017–0059, dated April 6, 2017), this AD requires using January 30, 2019 (the effective date of AD 2018–26–02, Amendment 39–19532 (83 FR 66093, December 26, 2018)).
- (3) Where EASA AD 2023–0187R1 refers to flight hours (FH), this AD requires using hours time-in-service.
- (4) This AD does not adopt paragraphs (1) and (2) of EASA AD 2023–0187R1.
- (5) Instead of complying with the compliance times in Table 1 in paragraph (3) of EASA AD 2023–0187R1, this AD requires the helicopters identified under the Helicopters in Pre-MOD 074699 Configuration column to accomplish the actions required by paragraph (3) of EASA AD 2023–0187R1 before the next practice autorotation, within 100 hours time-inservice, or 6 months after January 12, 2021 (the effective date of AD 2020–24–07), whichever occurs first.
- (6) Where Table 2 in paragraph (4), Table 3 in paragraph (7), and Table 4 in paragraph (9) of EASA AD 2023–0187R1 state "For helicopters which operate or have operated in salt-laden atmospheric conditions", this AD requires replacing that text with "For helicopters which operate or have operated in salt-laden atmospheric conditions, or if it cannot be determined if a helicopter has been operated in salt-laden atmospheric conditions".
- (7) Where paragraph (6) of EASA AD 2023–0187R1 states "discrepancies are detected", this AD requires replacing that text with "marks, residue, corrosion, flaky varnish are detected; the values of the insulation test are

- less than 10 megaOhms; the microswitch closes in the "IDLE" position and does not open as soon as the twist grip is turned to the "FLIGHT" position; or the microswitch is open in the "FLIGHT" position and does not close as soon as the twist grip is turned to the "IDLE" position".
- (8) Where paragraph (9) of EASA AD 2023–0187R1 states "any discrepancy," for purposes of this AD, discrepancy is defined as a nut torque that is outside allowable torque limits, or clearance between the support plate assembly and the washers that is not within 0.1 mm to 0.3 mm.
- (9) This AD does not adopt the "Remarks" section of EASA AD 2023–0187R1.

(i) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to: AMOC@faa.gov.
- (2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Additional Information

For more information about this AD, contact Zain Jamal, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (847) 294–7264; email: zain.jamal@faa.gov.

(k) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.
- (i) European Union Aviation Safety Agency (EASA) AD 2023–0187R1, dated March 20, 2025.
 - (ii) [Reserved]
- (3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADs@easa.europa.eu; website: easa.europa.eu. You may find this EASA material on the EASA website at ad.easa.europa.eu.
- (4) You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Parkway, Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222–5110.
- (5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on September 26, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025–19079 Filed 9–29–25; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2024-2099; Airspace Docket No. 24-AWP-105]

RIN 2120-AA66

Modification of Class E Airspace; Battle Mountain Airport, Battle Mountain, NV

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action modifies the Class E airspace area designated as a surface area, modifies the Class E airspace area designated as an extension to a Class E surface area, and modifies the Class E airspace areas extending upward from 700 feet or more above the surface of the earth at Battle Mountain Airport, Battle Mountain, NV. This action also updates the administrative portions of the airport's legal descriptions. These actions support the safety and management of instrument flight rules (IFR) operations at the airport.

DATES: Effective date 0901 UTC, January 22, 2026. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: A copy of the notice of proposed rulemaking (NPRM), supplemental notice of proposed rulemaking (SNPRM), all comments received, this final rule, and all background material may be viewed online at www.regulations.gov using the FAA Docket number. Electronic retrieval help and guidelines are available on the website. It is available 24 hours each day, 365 days each year. An electronic copy of this document may also be downloaded from www.federalregister.gov.

FAA Order JO 7400.11K, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at www.faa.gov/air_traffic/publications/.

FOR FURTHER INFORMATION CONTACT: Nathan A. Chaffman, Federal Aviation

Administration, Western Service Center, Operations Support Group, 2200 S 216th Street, Des Moines, WA 98198; telephone (206) 231–3460.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it modifies Class E airspace to support IFR operations at Battle Mountain Airport, Battle Mountain, NV.

History

The FAA published an NPRM for Docket No. FAA–2024–2099 in the **Federal Register** (90 FR 1050; January 7, 2025), proposing to establish and modify Class E airspace at Battle Mountain Airport, Battle Mountain, NV. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

After publication of the NPRM, it was discovered that the Class E airspace designated as an extension to a Class E surface area at Battle Mountain Airport, Battle Mountain, NV, had previously been established within the final rule of Docket No. FAA-2019-0786 in the Federal Register (85 FR 18870; April 3, 2020). As a result, the FAA published an SNPRM (90 FR 21249; May 19, 2025), revising the proposed action to be a modification rather than establishment of new Class E airspace, and reinitiating the public comment phase of rulemaking. The SNPRM also corrected the airspace docket number to read "24-AWP-105." Interested parties were again invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Differences From the SNPRM

The FAA has since identified an error within the SNPRM (90 FR 21249; May 19, 2025) concerning the proposed legal description for Battle Mountain's Class E airspace designated as an extension to a Class E surface area. The legal

description excluded "that airspace within the Battle Mountain Airport Class E2." FAA Order JO 7400.2R, Procedures for Handling Airspace Matters, does not allow for Class E airspace to be excluded from other airspace areas, so the exclusionary language was removed. Additionally, the same legal description required the term "airports" be added for clarity. Proposed or actual lateral boundaries are not affected by this difference. The FAA has determined that good cause exists that recirculating the proposal for public notice and comment is unnecessary as these corrections are ministerial in nature and do not impose additional operating requirements on regulated parties.

Incorporation by Reference

Class E2, E4, and E5 airspace areas are published in paragraphs 6002, 6004, and 6005, respectively, of FAA Order JO 7400.11, Airspace Designations and Reporting Points, which is incorporated by reference in 14 CFR 71.1 on an annual basis. This document amends the current version of that order, FAA Order JO 7400.11K, dated August 4, 2025, and effective September 15, 2025. These amendments will be published in the next update to FAA Order JO 7400.11. FAA Order JO 7400.11K, which lists Class A, B, C, D, and E airspace areas, air traffic service routes. and reporting points, is publicly available as listed in the ADDRESSES section of this document.

The Rule

The FAA is amending 14 CFR part 71 by modifying the Class E airspace area designated as surface area, modifying the Class E airspace area designated as an extension to a Class E surface area, modifying the Class E airspace extending upward from 700 feet above the surface of the earth, and removing the Class E airspace extending upward from 1,200 feet above the surface at Battle Mountain Airport, Battle Mountain, NV.

The Class E airspace area designated as surface area is expanded from a 4.2-mile radius to a 4.4-mile radius and a 0.1-mile extension is added to the southwest of the airport to more appropriately contain departing IFR aircraft executing the Runway (RWY) 22 obstacle departure procedure while between the surface and the base of adjacent controlled airspace.

Class E airspace designated as an extension to a Class E surface area is realigned to the 221° bearing and expanded to contain arriving IFR aircraft on the very high frequency omnidirectional range (VOR) RWY 4