

(ii) [Reserved]

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website [myboeingfleet.com](http://myboeingfleet.com).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [fr.inspection@nara.gov](mailto:fr.inspection@nara.gov).

Issued on July 3, 2025.

**Lona C. Saccomando,**

*Acting Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.*

[FR Doc. 2025-12677 Filed 7-7-25; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2025-1357; Project Identifier AD-2025-00618-T]

RIN 2120-AA64

### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all The Boeing Company (Boeing) Model 757-200, -200PF, and -200CB series airplanes. This proposed AD was prompted by a report of improper grinding of the inner diameter of the main landing gear (MLG) outer cylinders, resulting in possible heat damage to the outer cylinders. This proposed AD would require a records check or inspection to determine if an affected outer cylinder is installed and replacing all affected outer cylinders. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by August 22, 2025.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](http://regulations.gov). Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

*AD Docket:* You may examine the AD docket at [regulations.gov](http://regulations.gov) under Docket No. FAA-2025-1357; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

*Material Incorporated by Reference:*

- For Boeing material identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website [myboeingfleet.com](http://myboeingfleet.com).

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](http://regulations.gov) under Docket No. FAA-2025-1357.

**FOR FURTHER INFORMATION CONTACT:**

Stefanie Roesli, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3964; email: [stefanie.n.roesli@faa.gov](mailto:stefanie.n.roesli@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments using a method listed under the **ADDRESSES** section. Include “Docket No. FAA-2025-1357; Project Identifier AD-2025-00618-T” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR

11.35, the FAA will post all comments received, without change, to [regulations.gov](http://regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

**Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Stefanie Roesli, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3964; email: [stefanie.n.roesli@faa.gov](mailto:stefanie.n.roesli@faa.gov). Any commentary that the FAA receives that is not specifically designated as CBI will be placed in the public docket for this rulemaking.

**Background**

The FAA has received a report of an MLG collapse on a Boeing Model 767 airplane that was last overhauled at a maintenance, repair, and operations (MRO) facility. An investigation by the MRO facility indicated that a grinder used to machine the inner diameter of the MLG outer cylinders was operating outside of its input parameters, which may have caused heat damage to the outer cylinders. The MRO facility identified 20 Boeing Model 757 MLG outer cylinders that had inner diameter machining performed with the suspect grinder. This condition, if not addressed, could cause failure of a principal structural element to sustain its limit load, which could result in loss of control of the airplane. Heat damage could also lead to collapse of the MLG, which could result in a runway departure, or to fracture of an outer cylinder, which could deviate from the intended breakaway sequence, impact the fuel tank, and spill fuel, consequently creating a fire hazard.

**FAA’s Determination**

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

**Material Incorporated by Reference Under 1 CFR Part 51**

The FAA reviewed Boeing Alert Requirements Bulletin 757–32A0216 RB, dated January 26, 2024. This material specifies procedures for performing a maintenance records check

or an inspection of the left and right MLG outer cylinders to determine if any affected part numbers and serial numbers are installed and replacing any affected outer cylinder. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**Proposed AD Requirements in This NPRM**

This proposed AD would require accomplishing the actions specified in

the service information already described, except for any differences identified as exceptions in the regulatory text of this proposed AD. For information on the procedures and compliance times, see this material at *regulations.gov* under Docket No. FAA–2025–1357.

**Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 399 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection or maintenance records check for affected parts.	3 work-hours × \$85 per hour = \$255 .....	\$0	\$255	\$101,745

The FAA estimates the following costs to do any replacement that would be required based on the results of the

proposed inspection or maintenance records check. The agency has no way

of determining the number of airplanes that might need this replacement:

**ON-CONDITION COSTS**

Action	Labor cost	Parts cost	Cost per product
Replacement of MLG outer cylinder (20 affected parts).	137 work-hours × \$85 per hour = \$11,645 .....	\$325,000	\$336,645 per MLG outer cylinder.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the

States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**The Boeing Company:** Docket No. FAA–2025–1357; Project Identifier AD–2025–00618–T.

**(a) Comments Due Date**

The FAA must receive comments on this airworthiness directive (AD) by August 22, 2025.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 757–200, –200PF, and –200CB series airplanes, certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 32, Landing Gear.

**(e) Unsafe Condition**

This AD was prompted by a report of improper grinding of the inner diameter of the main landing gear (MLG) outer cylinders, resulting in possible heat damage to the outer cylinders. The FAA is issuing this AD to address heat damage to the MLG outer cylinders. The unsafe condition, if not addressed, could cause failure of a principal structural element to sustain its limit load or collapse of the MLG, which could result in loss of control of the airplane or runway departure.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Except as specified by paragraph (h) of this AD: At the applicable times specified in the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757-32A0216 RB, dated January 26, 2024, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 757-32A0216 RB, dated January 26, 2024.

**Note 1 to paragraph (g):** Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 757-32A0216, dated January 26, 2024, which is referred to in Boeing Alert Requirements Bulletin 757-32A0216 RB, dated January 26, 2024.

**(h) Exceptions to Requirements Bulletin Specifications**

Where the "Boeing Recommended Compliance Time" column in the table under the "Compliance" paragraph of Boeing Alert Requirements Bulletin 757-32A0216 RB, dated January 26, 2024, refers to the original issue date of Boeing Alert Requirements Bulletin 757-32A0216 RB, this AD requires using the effective date of this AD.

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, AIR-520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: [AMOC@faa.gov](mailto:AMOC@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR-520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration

deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**(j) Related Information**

(1) For more information about this AD, contact Stefanie Roesli, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3964; email: [stefanie.n.roesli@faa.gov](mailto:stefanie.n.roesli@faa.gov).

(2) Material identified in this AD that is not incorporated by reference is available at the address specified in paragraph (k)(3) this AD.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 757-32A0216 RB, dated January 26, 2024.

(ii) [Reserved]

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website [myboeingfleet.com](http://myboeingfleet.com).

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit [www.archives.gov/federal-register/cfr/ibr-locations](http://www.archives.gov/federal-register/cfr/ibr-locations) or email [ibr.inspection@nara.gov](mailto:ibr.inspection@nara.gov).

Issued on July 3, 2025.

**Lona C. Saccomando,**

Acting Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2025-12671 Filed 7-7-25; 8:45 am]

**BILLING CODE 4910-13-P**

**FEDERAL COMMUNICATIONS COMMISSION****47 CFR Part 73**

**[MB Docket No. 17-318; DA 25-530; FR ID 300811]**

**National Television Multiple Ownership Rule**

**AGENCY:** Federal Communications Commission.

**ACTION:** Proposed rule; reopening of comment period.

**SUMMARY:** In this document, the Media Bureau of the Federal Communications Commission seeks to update the record in the National Television Multiple Ownership Rule proceeding, in which the Commission has sought comment

whether to modify, retain, or eliminate the 39% national audience reach cap and/or the UHF discount.

**DATES:** The comment period for the proposed rule published January 26, 2018 (83 FR 3661), is reopened.

Comments are due: August 4, 2025. Reply comments are due: August 22, 2025.

**ADDRESSES:** All filings must be submitted in MB Docket No. 17-318. Pursuant to §§ 1.415 and 1.419 of the Commission's rules, 47 CFR 1.415, 1.419, interested parties may file comments and reply comments on or before the dates indicated on the first page of this document. Comments may be filed using the Commission's Electronic Comment Filing System (ECFS).

- *Electronic Filers:* Comments may be filed electronically using the internet by accessing the ECFS: <https://www.fcc.gov/ecfs>.

- *Paper Filers:* Parties who choose to file by paper must file an original and one copy of each filing.

- Filings can be sent by hand or messenger delivery, by commercial courier, or by the U.S. Postal Service. All filings must be addressed to the Secretary, Federal Communications Commission.

- Hand-delivered or messenger-delivered paper filings for the Commission's Secretary are accepted between 8:00 a.m. and 4:00 p.m. by the FCC's mailing contractor at 9050 Junction Drive, Annapolis Junction, MD 20701. All hand deliveries must be held together with rubber bands or fasteners. Any envelopes and boxes must be disposed of before entering the building.
- Commercial courier deliveries (any deliveries not by the U.S. Postal Service) must be sent to 9050 Junction Drive, Annapolis Junction, MD 20701.

- Filings sent by U.S. Postal Service First-Class Mail, Priority Mail, and Priority Mail Express must be sent to 45 L Street NE, Washington, DC 20554.

*People with Disabilities.* To request materials in accessible formats for people with disabilities (braille, large print, electronic files, audio format), send an email to [fcc504@fcc.gov](mailto:fcc504@fcc.gov) or call the Consumer & Governmental Affairs Bureau at 202-418-0530 (voice).

**FOR FURTHER INFORMATION CONTACT:** Ty Bream, [Ty.Bream@fcc.gov](mailto:Ty.Bream@fcc.gov), of the Industry Analysis Division, Media Bureau, (202) 418-0644.

**SUPPLEMENTARY INFORMATION:** This is a summary of the Media Bureau's Public Notice in MB Docket No. 17-318, DA 25-530, that was released June 18, 2025. The full text of this document is available for public inspection online at