

less than 15 degrees). The pilot's controls may be in the neutral position after reaching V_C/M_C and before recovery is initiated. Recovery may be initiated three seconds after operation of the high-speed warning device or immediately upon reaching V_C/M_C (whichever is higher) by application of a load factor of 1.5 g (0.5 g acceleration increment), or such greater load factor that is automatically applied by the system with the pilot's pitch control neutral; power may be reduced simultaneously if not already automatically reduced by the high-speed protection system. All other means of decelerating the airplane, the use of which are authorized up to the highest speed reached in the maneuver, may be used. The interval between successive pilot actions must not be less than one second.

(2) Any failure of the high-speed protection system that would affect the speed margin determined by paragraph (1) must be improbable (occur at a rate less than 10⁻⁵ per flight hour).

(3) Failures of the system must be annunciated to the pilots, and flight manual instructions must be provided to reduce the maximum operating speeds, V_{MO}/M_{MO} . The operating speed must be reduced to a value that maintains a speed margin between the reduced V_{MO}/M_{MO} and the lesser of V_{DF}/M_{DF} or V_D/M_D that is consistent with the margin determined from paragraph (1)(a) and § 25.335(b)(2) without the benefit of the high-speed protection system.

(4) Master minimum equipment list (MMEL) relief for the high-speed protection system may be considered by the FAA Flight Operations Evaluation Board (FOEB) provided that the flight manual instructions indicate reduced maximum operating speeds as described in paragraph (3), and that no additional hazards are introduced with the high-speed protection system inoperative. In addition, the cockpit display of the reduced operating speeds, as well as the overspeed warning for exceeding those speeds, must be equivalent to that of the normal airplane with the high-speed protection system operative.

Issued in in Kansas City, Missouri, on August 21, 2025.

Patrick R. Mullen,

Manager, Technical Policy Branch, Policy and Standards Division, Aircraft Certification Service.

[FR Doc. 2025-16358 Filed 8-26-25; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-2267; Project Identifier MCAI-2025-00819-T; Amendment 39-23125; AD 2025-17-15]

RIN 2120-AA64

Airworthiness Directives; ATR—GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain ATR—GIE Avions de Transport Régional Model ATR42-500 and ATR72-212A airplanes. This AD was prompted by a finding that dispatch with a failed main hydraulic pump under the provisions of a certain master minimum equipment list (MMEL) item, combined with failure of the DC EMER BUS, could lead to failure of multiple system losses. This AD requires revising the existing minimum equipment list (MEL) to incorporate new provisions to ensure appropriate actions are taken when the airplane is dispatched with one inoperative main hydraulic pump. The FAA is issuing this AD to address the unsafe condition on these products. **DATES:** This AD is effective September 11, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of September 11, 2025.

The FAA must receive comments on this AD by October 14, 2025.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-2267; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except

Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-2267.

FOR FURTHER INFORMATION CONTACT: John A. Massey, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7320; email: 9-AVS-AIR-BACO-COS@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments using a method listed under the **ADDRESSES** section. Include "Docket No. FAA-2025-2267; Project Identifier MCAI-2025-00819-T" at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information

that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to John A. Massey, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7320; email: 9-AVS-AIR-BACO-COS@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2025-0103, dated May 5, 2025 (EASA AD 2025-0103) (also referred to as the MCAI), to correct an unsafe condition for ATR—GIE Avions de Transport Régional Model ATR42-500 and ATR72-212A airplanes with the new avionics suite (glass flightdeck) installed by modification 05948. The MCAI states that a review of the MMEL identified that, under the provisions of MMEL item 29-11-01 for dispatch with a failed main hydraulic (HYD) pump, specifically the GREEN HYD Pump, a failure of the DC EMER BUS could lead to multiple system losses, including loss of control of the BLUE HYD Pump (electrically controlled by the DC EMER BUS), loss of nose wheel steering (powered by the DC EMER BUS), and complete loss of control of the rudder travel limitation unit (TLU) in both auto and manual modes. These failures could result in reduced airplane controllability on the ground during landing.

The FAA is issuing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-2267.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA AD 2025-0103, which specifies procedures for revising the existing MEL by providing instructions to ensure appropriate actions are taken when the airplane is dispatched with an inoperative main hydraulic pump. This material is reasonably available because the interested parties have access to it through their normal course of business

or by the means identified in the ADDRESSES section.

FAA's Determination

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Requirements of This AD

This AD requires accomplishing the actions specified in EASA AD 2025-0103 described previously, except for any differences identified as exceptions in the regulatory text of this AD.

Compliance With MEL Revisions

EASA AD 2025-0103 requires operators to "inform all flight crews" of revisions to the MEL, and thereafter to "operate the aeroplane accordingly." However, this AD does not specifically require those actions as those actions are already required by FAA regulations. FAA regulations (14 CFR 121.628(a)(2)) require operators to provide pilots with access to all the information contained in the operator's MEL. Furthermore, § 121.628(a)(5) requires airplanes to be operated under all applicable conditions and limitations contained in the operator's MEL. Therefore, including a requirement in this AD to operate the airplane according to the revised MEL would be redundant and unnecessary.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, EASA AD 2025-0103 is incorporated by reference in this AD. This AD requires compliance with EASA AD 2025-0103 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in EASA AD 2025-0103 does not mean that operators need comply only with that section. For example, where the AD

requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in EASA AD 2025-0103. Material required by EASA AD 2025-0103 for compliance will be available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2025-2267 after this AD is published.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for "good cause," finds that those procedures are "impracticable, unnecessary, or contrary to the public interest." Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies forgoing notice and comment prior to adoption of this rule because dispatch with an inoperative main hydraulic pump (GREEN HYD Pump (A)), in combination with a failed emergency bus, could lead to complete loss of control of the only remaining hydraulic pump (BLUE HYD Pump (B)), nose wheel steering, and rudder TLU, which could result in reduced controllability of the airplane on the ground during landing. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 22 airplanes of U.S. registry. The

FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hours × \$85 per hour = \$170	None	\$85	\$1,870

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025–17–15 ATR—GIE Avions de Transport Régional: Amendment 39–23125; Docket No. FAA–2025–2267; Project Identifier MCAI–2025–00819–T.

(a) Effective Date

This airworthiness directive (AD) is effective September 11, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to ATR—GIE Avions de Transport Régional Model ATR42–500 and ATR72–212A airplanes, certificated in any category, as identified in European Union Aviation Safety Agency (EASA) AD 2025–0103, dated May 5, 2025 (EASA AD 2025–0103).

(d) Subject

Air Transport Association (ATA) of America Code 29, Hydraulic Power.

(e) Unsafe Condition

This AD was prompted by a finding that dispatch with a failed main hydraulic pump under the provisions of a certain master minimum equipment list (MMEL) item, combined with failure of the emergency bus, could lead to multiple system losses, including loss of the only remaining hydraulic pump and nose wheel steering and complete loss of control of the rudder travel limitation unit (TLU). The FAA is issuing this AD to address these multiple system losses, which could result in reduced controllability of the airplane on the ground during landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2025–0103.

(h) Exceptions to EASA AD 2025–0103

- (1) Where EASA AD 2025–0103 refers to its effective date, this AD requires using the effective date of this AD.
- (2) Where paragraph (1) of EASA AD 2025–0103 specifies to “implement the instructions of the MMEL items”, this AD requires replacing that text with “revise the operator’s existing FAA-approved MEL by incorporating the information identified in “The MMEL items””.
- (3) Where paragraph (1) of EASA AD 2025–0103 specifies to “inform all flight crews, and thereafter, operate the aeroplane accordingly,” this AD does not require those actions as those actions are already required by existing FAA operating regulations (see 14 CFR 121.628(a)(2) and (5)).
- (4) This AD does not adopt paragraph (2) of EASA AD 2025–0103.
- (5) This AD does not adopt the “Remarks” section of EASA AD 2025–0103.

(i) Additional AD Provisions

The following provisions also apply to this AD:

- (1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.
- (2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or ATR—GIE Avions de Transport Régional’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Additional Information

For more information about this AD, contact John A. Massey, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516–228–7320; email: 9-AVS-AIR-BACO-COS@faa.gov.

(k) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference of

the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2025-0103, dated May 5, 2025.

(ii) [Reserved]

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on August 20, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025-16401 Filed 8-25-25; 4:15 pm]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-0925; Project Identifier MCAI-2024-00671-T; Amendment 39-23116; AD 2025-17-06]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2022-18-01, which applied to certain Airbus SAS Model A330-200 series airplanes, A330-200 Freighter series airplanes, A330-300 series airplanes, Model A330-800 series airplanes, and A330-900 series airplanes. AD 2022-18-01 required revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. Since the FAA issued AD 2022-18-01, the FAA has determined that new or more restrictive airworthiness limitations are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more

restrictive airworthiness limitations. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective October 1, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 1, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of October 11, 2022 (87 FR 54355, September 6, 2022).

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2025-0925; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at regulations.gov under Docket No. FAA-2025-0925.

FOR FURTHER INFORMATION CONTACT:

Emma Copeland, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 847-294-8068; email: emma.m.copeland@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2022-18-01, Amendment 39-22152 (87 FR 54355, September 6, 2022) (AD 2022-18-01). AD 2022-18-01 applied to certain Airbus SAS Model A330-200 series airplanes, A330-200 Freighter series airplanes, A330-300 series airplanes, A330-800 series airplanes, and A330-900 series airplanes. AD 2022-18-01 required revising the existing

maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA issued AD 2022-18-01 to address fatigue cracking, accidental damage, or corrosion in principal structural elements, and possible failure of certain life-limited parts, which could result in reduced structural integrity of the airplane.

The NPRM was published in the **Federal Register** on June 16, 2025 (90 FR 25163). The NPRM was prompted by AD 2024-0213, dated November 14, 2024, issued by EASA, which is the Technical Agent for the Member States of the European Union (EASA AD 2024-0213) (also referred to as the MCAI). The MCAI states that new or more restrictive airworthiness limitations have been developed.

In the NPRM, the FAA proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in EASA AD 2024-0213. The FAA is issuing this AD to address fatigue cracking, accidental damage, or corrosion in principal structural elements, and possible failure of certain life-limited parts. The unsafe condition, if not addressed, could result in reduced structural integrity of the airplane.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA-2025-0925.

Discussion of Final Airworthiness Directive

Comments

The FAA received comments from Air Line Pilots Association, International (ALPA), and an anonymous commenter who supported the NPRM without change.

Conclusion

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.