

under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025–19–12 The Boeing Company:
Amendment 39–23152; Docket No. FAA–2025–1358; Project Identifier AD–2025–00620–T.

(a) Effective Date

This airworthiness directive (AD) is effective November 6, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 737–600, –700, –700C, –800, –900, and –900ER series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing Gear.

(e) Unsafe Condition

This AD was prompted by a report of improper grinding of the inner diameter of the main landing gear (MLG) outer cylinders, resulting in possible heat damage to the outer cylinder. The FAA is issuing this AD to address heat damage to the MLG outer cylinders. The unsafe condition, if not addressed, could cause failure of a principal structural element to sustain its limit load or collapse of the MLG, which could result in loss of control of the airplane or runway departure.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737–32A1585 RB, dated January 15, 2024, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing

Alert Requirements Bulletin 737–32A1585 RB, dated January 15, 2024.

Note 1 to paragraph (g): Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 737–32A1585, dated January 15, 2024, which is referred to in Boeing Alert Requirements Bulletin 737–32A1585 RB, dated January 15, 2024.

(h) Exception to Requirements Bulletin Specifications

Where the “Boeing Recommended Compliance Time” column in the table under the “Compliance” paragraph of Boeing Alert Requirements Bulletin 737–32A1585 RB, dated January 15, 2024, refers to the original issue date of Boeing Alert Requirements Bulletin 737–32A1585 RB, this AD requires using the effective date of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, AIR–520, Continued Operational Safety Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, AIR–520, Continued Operational Safety Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

(1) For more information about this AD, contact Stefanie Roesli, Aviation Safety Engineer, FAA, 2200 South 216th St., Des Moines, WA 98198; phone: 206–231–3964; email: stefanie.n.roesli@faa.gov.

(2) Material identified in this AD that is not incorporated by reference is available at the address specified in paragraph (k)(3) this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737–32A1585 RB, dated January 15, 2024.

(ii) [Reserved]

(3) For Boeing material identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services

(C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; website myboeingfleet.com.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on September 19, 2025.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2025–19392 Filed 10–1–25; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2025–3421; Project Identifier MCAI–2025–01202–G; Amendment 39–23160; AD 2025–20–07]

RIN 2120–AA64

Airworthiness Directives; Fiberglass-Technik Rudolf Lindner GmbH & Co. KG (Type Certificate Previously Held by GROB Aircraft AG, Grob Aerospace GmbH i.L., Grob Aerospace GmbH, Burkhart Grob Luft- und Raumfahrt GmbH & Co. KG) Gliders

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Fiberglass-Technik Rudolf Lindner GmbH & Co. KG Model G103 TWIN II, G103A TWIN II ACRO, G103C TWIN III ACRO, and G 103 C TWIN III SL gliders. This AD was prompted by a report of corrosion on the inner sides of the welded steel rudder drive plate. This AD requires repetitive inspections and a one-time detailed inspection of the rudder drive plate for corrosion and water entry and a modification of the rudder drive plate to improve corrosion protection, as applicable. This AD also requires replacement of the rudder if corrosion is found during the inspections that exceed light surface rust. This AD also requires applying additional sealing to the rudder drive plate, which constitutes terminating action for the repetitive inspections. The

FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective October 17, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 17, 2025.

The FAA must receive comments on this AD by November 17, 2025.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *regulations.gov*. Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at *regulations.gov* under Docket No. FAA–2025–3421; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For Fiberglass-Technik Rudolf Lindner material identified in this AD, contact Fiberglass-Technik Rudolf Lindner GmbH & Co. KG, Steige 3 Walpertshofen, Germany; phone: +49 (0) 7353 22 43; email: *info@LTB-Lindner.com*; website: *ltb-lindner.com*.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110. It is also available at *regulations.gov* under Docket No. FAA–2025–3421.

FOR FURTHER INFORMATION CONTACT: Adam Hein, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (316) 946–4116; email: *adam.hein@faa.gov*.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written data, views, or arguments about this final rule. Send your comments using a method listed under the **ADDRESSES** section. Include “Docket No. FAA–2025–3421; Project Identifier

MCAI–2025–01202–G” at the beginning of your comments. The most helpful comments reference a specific portion of the final rule, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this final rule because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this final rule.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Adam Hein, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2025–0140, dated July 7, 2025 (referred to as “the MCAI”), to correct an unsafe condition on all Fiberglass-Technik Rudolf Lindner GmbH & Co. KG Model G103 TWIN II, G103A TWIN II ACRO, G103C TWIN III, G103C TWIN III ACRO, and G 103 C TWIN III SL sailplanes (gliders).

The MCAI states that corrosion was found on the inner sides of the welded drive plate during a teardown inspection of a rudder. This condition, if not detected and corrected, could affect the structural integrity of the rudder drive plate, which could lead to

reduced control or loss of control of the glider. The MCAI requires repetitive inspections of the rudder drive plate for corrosion and possible water entry and a one-time detailed inspection and modification of the rudder drive plate either immediately or at the next service life extension inspection, depending on the results of the inspection. The MCAI also requires replacement of the rudder assembly if corrosion is found during the inspections that exceed light surface rust. The MCAI also requires applying additional sealing to the rudder drive plate, which constitutes terminating action for the repetitive inspections.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA–2025–3421.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed Fiberglass-Technik Rudolf Lindner Service Bulletin SB–G10, Revision 1, dated February 27, 2025. This material specifies procedures for inspecting the rudder drive plate for corrosion and water entry, modifying the rudder drive plate to improve corrosion protection, applying additional sealing, and replacing the rudder. This material contains German to English translation.

The European Union Aviation Safety Agency (EASA) used the English translation in referencing the document. For enforceability purposes, the FAA will refer to the Fiberglass-Technik Rudolf Lindner service material in English as it appears on the document.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

AD Requirements

This AD requires accomplishing the actions specified in the material already described, except as discussed under “Differences Between this AD and the Service Material and MCAI.”

Differences Between This AD and the Service Material and MCAI

While the MCAI applies to Fiberglas-Technik Rudolf Lindner GmbH & Co. KG Model G103C TWIN III gliders, this AD does not because this model does not have an FAA type certificate. Fiberglas-Technik Rudolf Lindner Service Bulletin SB-G10, Revision 1, dated February 27, 2025, requires replacing the rudder or contacting the manufacturer for approved instructions if corrosion exceeding light surface rust is detected. This AD requires replacing the rudder or contacting either the Manager, International Validation Branch, FAA; or EASA; or Fiberglas-Technik Rudolf Lindner GmbH & Co. KG's EASA Design Organization Approval (DOA) for approved instructions if corrosion exceeding light surface rust is detected. If approved by the DOA, the approval must include the DOA-authorized signature.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good

cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules effective in less than thirty days, upon a finding of good cause.

An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies forgoing notice and comment prior to adoption of this rule because corrosion on the inner sides of the welded steel rudder drive plate could affect the structural integrity of the rudder drive plate and lead to reduced control or loss of control of the glider. Additionally, the glider fleet has an average age of 5,400 flight hours, and due to limitations in general aviation reporting, the exact age of each glider is unknown. Based on the fleet's age distribution and an average of 10 hours time-in-service (TIS) per month, it is estimated that certain gliders will require the one-time inspection and modification within 50 hours TIS or 3

months, whichever occurs first, which is shorter than the time necessary for the public to comment and for publication of the final rule. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b).

In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause to forgo notice and comment.

Regulatory Flexibility Act

The requirements of the Regulatory Flexibility Act (RFA) do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without prior notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 68 gliders of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspect rudder drive plate	1 work-hour × \$85 per hour = \$85 per inspection cycle.	\$0	\$85 per inspection cycle	\$5,780 per inspection cycle.
Detailed inspection of rudder drive plate.	4 work-hours × \$85 per hour = \$340.	0	\$340	\$23,120.
Apply sealing	1 work-hour × \$85 per hour = \$85	0	\$85	\$5,780.
Re-install rudder	1 work-hour × \$85 per hour = \$85	0	\$85	\$5,780.

The FAA estimates the following costs to do any necessary modification or replacement of the rudder that would

be required based on the results of the inspection. The agency has no way of determining the number of gliders that

might need the modification or replacement.

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replace rudder	2 work-hours × \$85 per hour = \$170	\$6,582	\$6,752

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2025–20–07 Fiberglas-Technik Rudolf Lindner GmbH & Co. KG (type certificate previously held by GROB Aircraft AG, Grob Aerospace GmbH i.l., Grob Aerospace GmbH, Burkhart Grob Luft- und Raumfahrt GmbH & Co. KG): Amendment 39–23160; Docket No. FAA–2025–3421; Project Identifier MCAI–2025–01202–G.

(a) Effective Date

This airworthiness directive (AD) is effective October 17, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fiberglas-Technik Rudolf Lindner GmbH & Co. KG (type certificate previously held by GROB Aircraft AG, Grob Aerospace GmbH i.l., Grob Aerospace GmbH, Burkhart Grob Luft- und Raumfahrt GmbH & Co. KG) Model G103 TWIN II, G103A TWIN II ACRO, G103C TWIN III ACRO, and G 103 C TWIN III SL gliders, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 2720, Rudder Control System.

(e) Unsafe Condition

This AD was prompted by a report of corrosion on the inner sides of the welded steel rudder drive plate. The FAA is issuing this AD to detect and address corrosion and water entry in the rudder drive plate. The unsafe condition, if not detected and corrected, could affect the structural integrity of the rudder drive plate, which could lead

to reduced control or loss of control of the glider.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Definition

For the purpose of this AD, a “serviceable rudder” is a rudder which has accumulated zero hours time-in-service (TIS), or a rudder that has been inspected and modified, as necessary, in accordance with paragraphs (h)(1) and (2) of this AD and is found to be crack and corrosion free.

(h) Required Actions

(1) Within 50 hours TIS or 3 months, whichever occurs first after the effective date of this AD, and, thereafter, at intervals not to exceed every 12 months, inspect the rudder drive plate for evidence of corrosion or water entry in accordance with the Actions and Instructions, section A, of Fiberglas-Technik Rudolf Lindner Service Bulletin SB–G10, Revision 1, dated February 27, 2025.

(2) Perform a one-time detailed inspection of the rudder drive plate in accordance with the Actions and Instructions, section B, steps 1 and 2 of Fiberglas-Technik Rudolf Lindner Service Bulletin SB–G10, Revision 1, dated February 27, 2025, at whichever compliance time in paragraphs (h)(2)(i) or (ii) of this AD occurs first.

(i) Before further flight if during any inspection as required by paragraph (h)(1) of this AD, evidence of corrosion or water ingress is found; or

(ii) At the next service life extension inspection that occurs after the effective date of this AD.

(3) If, as a result of the inspection required by paragraph (h)(2) of this AD, corrosion of the rudder drive plate is detected that exceeds light surface rust and cannot be removed using steel wool, before further flight, replace the rudder with a serviceable rudder, or contact the Manager, International Validation Branch, FAA; or EASA; or Fiberglas-Technik Rudolf Lindner GmbH & Co. KG EASA Design Organization Approval (DOA) for approved instructions. If approved by the DOA, the approval must include the DOA-authorized signature.

(4) If the rudder is replaced with a serviceable rudder, before further flight, apply additional sealing to the rudder drive plate in accordance with the Actions and Instructions, Section C, of Fiberglas-Technik Rudolf Lindner Service Bulletin SB–G10, Revision 1, dated February 27, 2025.

(5) If, as a result of the inspection required by paragraph (h)(2) of this AD, light surface rust is detected, before further flight, modify the rudder drive plate in accordance with the Actions and Instructions, section B, steps 4 through 7 of Fiberglas-Technik Rudolf Lindner Service Bulletin SB–G10, Revision 1, dated February 27, 2025.

(6) If, as a result of the inspection required by paragraph (h)(2) of this AD, no evidence of corrosion or water ingress is detected, before further flight, modify the rudder drive plate in accordance with the Actions and Instructions, section B, steps 5 through 7 of Fiberglas-Technik Rudolf Lindner Service

Bulletin SB–G10, Revision 1, dated February 27, 2025.

(7) Following completion of the modification of the rudder drive plate required by paragraph (h)(5) or (h)(6) of this AD, before further flight, apply additional sealing to the rudder drive plate in accordance with the Actions and Instructions, Section C, of Fiberglas-Technik Rudolf Lindner Service Bulletin SB–G10, Revision 1, dated February 27, 2025.

(8) Following completion of the sealing application required by paragraph (h)(7) of this AD, re-install the rudder in accordance with the Actions and Instructions, Section D, of Fiberglas-Technik Rudolf Lindner Service Bulletin SB–G10, Revision 1, dated February 27, 2025.

(9) Application of additional sealing to the rudder drive plate, as required by paragraphs (h)(4) and (h)(7) of this AD, constitutes terminating action for the repetitive inspections required by paragraph (h)(1) of this AD for that glider.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Additional Information

For more information about this AD, contact Adam Hein, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (316) 946–4116; email: adam.hein@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Fiberglas-Technik Rudolf Lindner Service Bulletin SB–G10, Revision 1, dated February 27, 2025.

Note 1 to paragraph (k)(2)(i): This material contains German to English translation. The European Union Aviation Safety Agency (EASA) used the English translation in referencing the document. For enforceability purposes, the FAA will refer to the Fiberglas-Technik Rudolf Lindner service material in English as it appears on the document.

(ii) [Reserved]

(3) For Fiberglas-Technik Rudolf Lindner material identified in this AD, contact Fiberglas-Technik Rudolf Lindner GmbH & Co. KG, Steige 3 Walpertshofen, Germany;

phone: +49 (0) 7353 22 43; email: info@LTB-Lindner.com; website: ltb-lindner.com.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on September 30, 2025.

Steven W. Thompson,

Acting Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2025-19355 Filed 9-30-25; 4:15 pm]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2025-1354; Project Identifier MCAI-2025-00012-T; Amendment 39-23154; AD 2025-20-01]

RIN 2120-AA64

Airworthiness Directives; ATR—GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain ATR—GIE Avions de Transport Régional Model ATR42-500 and ATR72 airplanes. This AD was prompted by an investigation indicating that an erroneous monitoring of the travel limitation unit (TLU) could occur when the airplane is flying above a certain speed as a result of the logic input from either air data computer (ADC) 1 or ADC2 input. This AD requires modifying airplanes by installing one or two relays and associated wiring and testing of the TLU monitoring logic. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 6, 2025.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 6, 2025.

ADDRESSES:

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA-2025-1354; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except

Federal holidays. The AD docket contains this final rule, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

- For European Union Aviation Safety Agency (EASA) material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at regulations.gov under Docket No. FAA-2025-1354.

FOR FURTHER INFORMATION CONTACT:

Jonathan Duong, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7362; email: 9-AVS-AIR-BACO-COS@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain ATR—GIE Avions de Transport Régional Model ATR42-500 and ATR72 airplanes. The NPRM was published in the **Federal Register** on July 7, 2025 (90 FR 29802). The NPRM was prompted by AD 2025-0004, dated January 7, 2025 (EASA AD 2025-0004) (also referred to as the MCAI), issued by EASA, which is the Technical Agent for the Member States of the European Union. The MCAI states that an ATR internal review of the TLU new avionics suite design identified an erroneous behavior of core processing module (CPM) 2, hosting the data concentration application (DCA) 2, that might affect the TLU command, monitoring, and indication. Further investigation results indicated that an erroneous monitoring of the TLU could occur when the airplane is flying above a certain speed due to the logic input from either ADC1 or ADC2 input.

In the NPRM, the FAA proposed to require modification of airplanes by installing one or two relays and associated wiring and testing of the TLU monitoring logic, as specified in EASA AD 2025-0004. The FAA is issuing this

AD to address erroneous behavior of CPM 2, hosting the DCA 2, that could affect the TLU command, monitoring, and indication. This condition, if not corrected, could result in the rudder deflection not being limited at high airplane speed, which, if combined with a large rudder pedal input, could lead to the loss of control of the airplane.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA-2025-1354.

Discussion of Final Airworthiness Directive

Comments

The FAA received a comment from the Air Line Pilots Association, International (ALPA) who supported the NPRM without change.

Conclusion

These products have been approved by the civil aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, that authority has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Accordingly, the FAA is issuing this AD to address the unsafe condition on these products. Except for minor editorial changes, this AD is adopted as proposed in the NPRM. None of the changes will increase the economic burden on any operator.

Material Incorporated by Reference Under 1 CFR Part 51

The FAA reviewed EASA AD 2025-0004, which specifies procedures for modifying airplanes by installing one or two relays and associated wiring. EASA AD 2025-0004 also specifies procedures for an operational test of the TLU monitoring logic after the modification, a functional test of the rudder travel limiter unit, and obtaining and following instructions to correct any failed test. For airplanes on which a previous revision of the applicable service information has been accomplished, EASA AD 2025-0004 specifies accomplishing "Additional Work," which consists of a functional test of the rudder travel limiter unit. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.