

Room 100, Wichita, Kansas 67209; telephone: (316) 946-4141; fax: (316) 946-4107; email: tara.shawn@faa.gov or Wichita-COS@faa.gov.

(2) For service information identified in this AD, contact Textron Aviation Customer Service, P.O. Box 7706, Wichita, Kansas 67277, (316) 517-5800; customercare@txtav.com; <https://txtav.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued on May 8, 2020.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-10316 Filed 5-13-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0473; Product Identifier 2018-CE-058-AD]

RIN 2120-AA64

Airworthiness Directives; Polskie Zaklady Lotnicze Sp. z o.o. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Polskie Zaklady Lotnicze Sp. z o.o. Model PZL M28 05 airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as defective thermo-shrinkable tubes installed on the electrical harnesses located in the fuel tanks. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by June 29, 2020.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Polskie Zaklady Lotnicze Sp. z o.o., Wojska Polskiego 3, 39-300 Mielec, Poland, +48 17 743 1901, email: pzl.lm@lmco.com, internet: www.pzlmielec.pl. You may review this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0473; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Standards Branch, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2020-0473; Product Identifier 2018-CE-058-AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. The FAA will consider all comments received by the closing date and may amend this proposed AD because of those comments.

The FAA will post all comments we receive, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No. 2018-0242, dated October 8, 2018 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

During accomplishment of maintenance on an M28 05 military version airplane, torn pieces of thermo-shrinkable tubes were found in the header section of the main fuel tank. These tubes are installed on electrical harnesses located in the fuel tanks and serve as marking and protection devices against mechanical damage during manufacturing and servicing. Pieces of these tubes may travel with the fuel flow and may block the jet pump or reduce its performance, particularly in the centre-wing fuel tank, in which the jet pump is the only way of further transfer of fuel to the engine. Subsequent investigation determined that degradation of the tube material was caused by a manufacturing deficiency, leading to insufficient material resistance against mechanical damage when a tube is located in a fuel.

This condition, if not detected and corrected, could lead to reduced fuel supply to the engines, inability to use all the fuel in fuel tanks and reduced available engine power, resulting in reduced aeroplane performance.

To address this potentially unsafe condition, PZL identified the batch of aeroplanes that are potentially equipped with thermo-shrinkable tubes having this manufacturing defect, and issued the [service bulletin] SB providing inspection and replacement instructions.

For the reasons described above, this [EASA] AD requires a one-time inspection of the electrical harnesses located in the fuel tanks and, depending on findings, replacement of the affected harness.

Polskie Zaklady Lotnicze Sp. z o.o. informed us the potential for damage to the thermo-shrinkable tubes does not progress with time. Therefore, we determined repetitive inspections are not required. You may examine the MCAI on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0473.

Related Service Information Under 14 CFR Part 51

Polskie Zaklady Lotnicze Sp. z o.o. has issued Service Bulletin No. E/12.141/2018, dated May 15, 2018. The service information contains procedures for inspecting the thermo-shrinkable tubes on the electrical harnesses in the center and outer wing fuel tanks for damage and replacing any electrical harness with damaged thermo-shrinkable tubes. This service information is reasonably available

because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information referenced above. The FAA is proposing this AD because it evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

The FAA estimates that this proposed AD would affect 15 products of U.S. registry. The FAA also estimates that it would take about 3 work-hours per product to comply with the basic inspection requirement of this proposed AD. The average labor rate is \$85 per work-hour.

Based on these figures, the FAA estimates the cost of the proposed AD on U.S. operators to be \$3,825, or \$255 per product.

In addition, the FAA estimates that any necessary follow-on replacement action would take about 60 work-hours and require parts costing \$5,000, for a cost of \$10,100 per electrical harness. The FAA has no way of determining the number of products that may need these actions.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Polskie Zakłady Lotnicze Sp. z o.o.: Docket No. FAA-2020-0473; Product Identifier 2018-CE-058-AD.

(a) Comments Due Date

The FAA must receive comments by June 29, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Polskie Zakłady Lotnicze Sp. z o.o. Model PZL M28 05 airplanes, serial numbers AJE00301 through AJE00343, and AJE00345 through AJE00347, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 28: Fuel Tank.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another

country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as defective thermo-shrinkable tubes installed on the electrical harnesses located in the fuel tanks. The FAA is issuing this AD to prevent broken pieces of the thermo-shrinkable tubes from blocking the jet pump, reducing fuel supply to the engines, and resulting in the inability to use all the fuel in the fuel tanks. This condition could lead to reduced engine power and airplane performance.

(f) Actions and Compliance

Unless already done, do the following actions in paragraphs (f)(1) and (2) of this AD:

- (1) Within the next 200 hours time-in-service (TIS) after the effective date of this AD or within the next 8 months after the effective date of this AD, whichever occurs first:

- (i) Inspect each electrical wire harness in the center wing and the left-hand and right-hand outer wing fuel tanks for cracking, tears, and seizing of the thermo-shrinkable tubes in accordance with paragraphs II.1 through 2 a) of the Procedure for Bulletin Execution section in Polskie Zakłady Lotnicze Sp. z o.o. Service Bulletin No. E/12.141/2018, dated May 15, 2018.

- (ii) If there is a tear or any cracking in or any seizing of an electrical wire harness thermo-shrinkable tube, before further flight, replace the harness in accordance with section II. a) Replacement of harness KL8 (KP), II. b) Replacement of Harness KL9 (KP9), or II. c) Replacement of harness KL10 (KP10), as applicable, of the Procedure for Bulletin Execution in Polskie Zakłady Lotnicze Sp. z o.o. Service Bulletin No. E/12.141/2018, dated May 15, 2018.

- (2) As of the effective date of this AD, do not install any electrical wire harness part number 28.14.7205.073.000, 28.14.7205.074.000, 28.14.7205.075.000, 28.14.7205.076.000, 28.14.7205.077.000, or 28.14.7205.078.000, that has more than zero hours TIS on any airplane, unless it has passed the inspection required by paragraph (f)(1)(i) of this AD.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Small Airplane Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Standards Branch, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2018-0242, dated October 8, 2018, for related information. You may examine the MCAI on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0473.

For service information related to this AD, contact Polskie Zakłady Lotnicze Sp. z o.o., Wojska Polskiego 3, 39–300 Mielec, Poland, +48 17 743 1901, email: pzl.lm@lmco.com, internet: www.pzlmielec.pl. You may review this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Issued on May 6, 2020.

Gaetano A. Sciortino,

*Deputy Director for Strategic Initiatives,
Compliance & Airworthiness Division,
Aircraft Certification Service.*

[FR Doc. 2020–10015 Filed 5–13–20; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–0483; Product Identifier 2016–SW–066–AD]

RIN 2120–AA64

Airworthiness Directives; MD Helicopters Inc. (MDHI), Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain MD Helicopters Inc. (MDHI), Model 369A, 369D, 369E, 369FF, 369H, 369HE, 369HM, 369HS, 500N, and 600N helicopters. This proposed AD would require tap inspecting each main rotor (MR) blade leading edge abrasion strip and is prompted by reports of abrasion strips departing the MR blade in-flight. The proposed actions are intended to prevent an unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by July 13, 2020.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <https://www.regulations.gov>. Follow the online instructions for sending your comments electronically.
- *Fax:* 202–493–2251.
- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590–0001.

• *Hand Delivery:* Deliver to the “Mail” address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0483; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed rule, contact Helicopter Technology Company, LLC, address 12902 South Broadway, Los Angeles, CA 90061; telephone (310) 523–2750; email gburdorf@helicoptertech.com; or at <http://www.helicoptertech.com>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N–321, Fort Worth, TX 76177.

FOR FURTHER INFORMATION CONTACT:

Payman Soltani, Aviation Safety Engineer, Los Angeles ACO Branch, FAA, 3960 Paramount Blvd., Lakewood, California 90712; telephone (562) 627–5313; email payman.soltani@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to participate in this rulemaking by submitting written comments, data, or views. The FAA also invites comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

The FAA will file in the docket all comments received, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, the FAA will consider all comments received on or before the closing date for comments. The FAA will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. The FAA may change this proposal in light of the comments received.

Discussion

The FAA proposes to adopt a new AD for MDHI Model 369A, 369D, 369E, 369FF, 369H, 369HE, 369HM, 369HS, 500N, and 600N helicopters with an MR blade part number (P/N) 500P2100–105, P/N 500P2100–305, P/N 500P2300–505, P/N 369D21120–505, P/N 369D21121–505, or P/N 369D21123–505, with a 1.25-inch chord length nickel abrasion strip (abrasion strip) manufactured or installed by Helicopter Technology Company (HTC) or where the manufacturer of the abrasion strip is unknown. This proposed AD would require tap inspecting the abrasion strip within 10 hours time-in-service (TIS) and thereafter before the first flight of each day until the abrasion strip has accumulated 700 hours TIS since installation.

This proposed AD is prompted by reports that leading edge abrasion strips manufactured by HTC are departing the MR blades during flight. An investigation determined that the abrasion strips were manufactured from electroformed nickel, have a chord length of 1.25 inch, and are delaminating from the MR blade before departing from the helicopter. HTC has determined that a repetitive tap inspection of the abrasion strips should be performed on all blades with abrasion strips that have less than 700 hours TIS to detect any voids, including blistering, bubbling, or lifting of the abrasion strip. Identical looking electroformed nickel abrasion strips with a chord length of 1.25 inch manufactured by other repair stations have not departed in flight and therefore are not the subject of this proposed AD. If the manufacturer of the installed abrasion strip is unknown, this proposed AD would apply to the strip.

FAA's Determination

The FAA is proposing this AD because the agency evaluated all known relevant information and determined that an unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs.

Related Service Information Under 14 CFR Part 51

The FAA reviewed HTC Mandatory Service Bulletin Notice No. 2100–8R4, dated June 1, 2017, which specifies a daily tap inspection of the MR blade abrasion strip to detect voids. If there are any voids, the SB specifies repairing or replacing the MR blade, depending on the size, quantity, and location of any damage.

This service information is reasonably available because the interested parties