

or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) The subject of this AD is addressed in Transport Canada AD CF-2019-03, dated January 31, 2019. This Transport Canada AD may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0860.

(2) For more information about this AD, contact Matt Fuller, AD Program Manager, Continued Operational Safety Branch, Airworthiness Products Section, General Aviation and Rotorcraft Unit, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(3) Bell Model 429 Maintenance Planning Information BHT-429-MPI, Chapter 4, Airworthiness Limitations Schedule, DMC-429-A-04-00-00-00A-288A-A, Issue 1, dated January 10, 2019, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD that is not incorporated by reference, contact Bell Textron Canada Limited, 12,800 Rue de l'Avenir, Mirabel, Quebec J7J 1R4; telephone (450) 437-2862 or (800) 363-8023; fax (450) 433-0272; or at <https://www.bellcustomer.com>.

(j) Material Incorporated by Reference

None.

Issued on January 28, 2021.

Gaetano A. Sciortino,

*Deputy Director for Strategic Initiatives,
Compliance & Airworthiness Division,
Aircraft Certification Service.*

[FR Doc. 2021-03659 Filed 2-24-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-1036; Project Identifier MCAI-2020-01430-R; Amendment 39-21409; AD 2021-03-06]

RIN 2120-AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus Helicopters Model SA-365N, SA-365N1, AS-365N2, AS 365 N3, EC 155B, and EC155B1 helicopters. This AD was prompted by the FAA's determination that to improve the process and performance in collecting metal particles in the main gear box

(MGB) certain existing magnetic plugs (electrical and nonelectrical) installed in the MGB pump intake must be replaced with improved non-electrical magnetic plugs. This AD requires replacing the existing magnetic plug with an improved non-electrical magnetic plug, as specified in a European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 1, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 1, 2021.

ADDRESSES: For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817-222-5110. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1036.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-1036; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Mahmood Shah, Aviation Safety Engineer, Fort Worth ACO Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5538; email mahmood.g.shah@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018-0176, dated August 21, 2018

(EASA AD 2018-0176) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for certain Airbus Helicopters Model SA-365N, SA-365N1, AS-365N2, AS 365 N3, EC 155B, and EC155B1 helicopters.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus Helicopters Model SA-365N, SA-365N1, AS-365N2, AS 365 N3, EC 155B, and EC155B1 helicopters. The NPRM published in the **Federal Register** on November 30, 2020 (85 FR 76495). The NPRM was prompted by the FAA's determination that to improve the process and performance in collecting metal particles in the MGB certain existing magnetic plugs (electrical and non-electrical) installed in the MGB pump intake must be replaced with improved non-electrical magnetic plugs. The NPRM proposed to require replacing the existing magnetic plug with an improved non-electrical magnetic plug, as specified in an EASA AD.

The FAA is issuing this AD to address metal particles causing seizure of the MGB, loss of power to the main rotor, and subsequent loss of control of the helicopter. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 14 CFR Part 51

EASA AD 2018-0176 describes procedures for replacing the existing magnetic plug (electrical and non-electrical) installed in the MGB pump intake with an improved non-electrical magnetic plug. This material is reasonably available because the interested parties have access to it through their normal course of business

or by the means identified in the ADDRESSES section.

Interim Action

The FAA considers this AD interim action. If final action is later identified, the FAA might consider further rulemaking then.

Costs of Compliance

The FAA estimates that this AD affects 52 helicopters of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 7.5 work-hours × \$85 per hour = \$637.50	\$55	Up to \$692.50	Up to \$36,010

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

2021-03-06 Airbus Helicopters:

Amendment 39-21409; Docket No. FAA-2020-1036; Project Identifier MCAI-2020-01430-R.

(a) Effective Date

This airworthiness directive (AD) is effective April 1, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Helicopters Model SA-365N, SA-365N1, AS-365N2, AS 365 N3, EC 155B, and EC155B1 helicopters, certificated in any category, equipped with magnetic plugs, part number (P/N) 1B7807 or P/N 704A34543017 (electrical), or P/N 365A32-1711-00 (non-electrical), as applicable, installed in the main gearbox (MGB) pump intake.

(d) Subject

Joint Aircraft System Component (JASC) Code 6320, Main Rotor Gearbox.

(e) Reason

This AD was prompted by the FAA's determination that to improve the process and performance in collecting metal particles in MGB certain existing magnetic plugs (electrical and non-electrical) installed in the MGB pump intake must be replaced with improved non-electrical magnetic plugs. The FAA is issuing this AD to address metal particles causing seizure of the MGB, loss of power to the main rotor, and subsequent loss of control of the helicopter.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD 2018-0176, dated August 21, 2018 (EASA AD 2018-0176).

(h) Exceptions to EASA AD 2018-0176

(1) Where EASA AD 2018-0176 refers to its effective date, this AD requires using the effective date of this AD.

(2) The "Remarks" section of EASA AD 2018-0176 does not apply to this AD.

(3) Although the service information referenced in EASA AD 2018-0176 specifies to discard certain parts, this AD does not include that requirement.

(4) Where EASA AD 2018-0176 refers to flight hours (FH), this AD requires using hours time-in-service.

(i) Special Flight Permit

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the helicopter can be modified (if the operator elects to do so), provided the helicopter is operated using day visual flight rules and no passengers are onboard.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Strategic Policy Rotorcraft Section, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the Strategic Policy Rotorcraft Section, send it to: Manager, Strategic Policy Rotorcraft Section, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone 817-222-5110. Information may be emailed to: 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Related Information

For more information about this AD, contact Mahmood Shah, Aviation Safety Engineer, Fort Worth ACO Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX

76177; telephone 817 222 5538; email mahmood.g.shah@faa.gov.

(I) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Aviation Safety Agency (EASA) AD 2018–0176 dated August 21, 2018.

(ii) [Reserved]

(3) For EASA AD 2018–0176, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADS@easa.europa.eu; internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call 817–222–5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–1036.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on January 27, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–03664 Filed 2–24–21; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–0907; Product Identifier 2017–SW–072–AD; Amendment 39–21429; AD 2021–04–08]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for Airbus Helicopters Model AS350B3 helicopters. This AD requires modifying the electrical system of the throttle twist grip, inspecting the routing of a microswitch electrical harness, and

correcting the electrical harness routing if it is incorrect. This AD was prompted by reports of the engine remaining in idle when the twist grip was turned from the “forced idle” position to the “flight” position. The actions of this AD are intended to address an unsafe condition on these products.

DATES: This AD is effective April 1, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain document listed in this AD as of April 1, 2021.

ADDRESSES: For service information identified in this final rule, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; telephone 972–641–0000 or 800–232–0323; fax 972–641–3775; or at <https://www.airbus.com/helicopters/services/technical-support.html>. You may view the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0907.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0907; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Aviation Safety Agency (now European Union Aviation Safety Agency) (EASA) AD, any service information that is incorporated by reference, any comments received, and other information. The street address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Ronnea Derby, Aviation Safety Engineer, Denver ACO Branch, FAA, 26805 E 68th Ave., Denver, CO 80249; telephone 303–342–1093; email ronnea.l.derby@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to Airbus Helicopters Model AS350B3 helicopters with a Turbomeca ARRIEL 2B engine installed. The NPRM published in the **Federal Register** on October 15, 2020 (85 FR 65285). The

NPRM proposed to require, based on helicopter configuration, modifying the electrical system of the throttle twist grip. The proposed AD also proposed to require inspecting the routing of a microswitch electrical harness, and depending on the routing of that electrical harness, correcting the routing. The proposed requirements were intended to prevent failure of the electrical operation of the throttle twist grip, which can prevent switching from “IDLE” mode to “FLIGHT” mode. During autorotation training or during governor failure training (when the throttle grip is turned in the low flow direction), this condition prohibits recovery from a practice autorotation and compels the pilot to continue the autorotation to the ground. This condition could result in unintended touchdown to the ground at a flight-idle power setting, damage to the helicopter, and injury to occupants.

The NPRM was prompted by EASA AD No. 2017–0035, dated February 20, 2017 (EASA AD 2017–0035), to correct an unsafe condition for Airbus Helicopters (formerly Eurocopter) Model AS 350 B3 helicopters with ARRIEL 2B engines installed. EASA advises of an initial report of the microswitch pin jammed in the pushed-in position resulting in the engine remaining in idle when the twist grip had been turned back to the “flight” position during an autorotation training exercise. This condition could also occur during governor failure training when the twist grip is turned in the low flow rate direction. EASA also advises of two later reports of this condition, with one of those reports related to an incorrectly routed electrical harness. EASA advises that this condition, if not detected and corrected, could lead to reduced control of the helicopter.

EASA initially issued AD No. 2006–0094, dated April 21, 2006, which required repetitive testing of the microswitch and established a life limit for the microswitch. Subsequent EASA AD action required reducing that life limit, inspecting the travel of the collective lever, performing an additional check of the collective lever for free travel, and installing a terminating action modification that was available for certain helicopter configurations. That modification gave priority to the HydroMechanical Unit (HMU) flight position when the microswitch failed to operate correctly at forced idle. EASA most recently issued AD 2017–0035, which prompted this AD action, to include all of the previous AD requirements and expand the terminating action modification to other helicopter configurations.