

**(a) Effective Date**

This airworthiness directive (AD) is effective July 29, 2021.

**(b) Affected Airworthiness Directives**

None.

**(c) Applicability**

This AD applies to Airbus Helicopters Deutschland GmbH (AHD) Model MBB-BK 117 D-2 helicopters, certificated in any category, having an affected part as defined in European Union Aviation Safety Agency (EASA) AD 2019-0198, dated August 15, 2019 (EASA AD 2019-0198).

**(d) Subject**

Joint Aircraft System Component (JASC) Code 2700, Flight Control System.

**(e) Reason**

This AD was prompted by a short circuit in a yaw trim actuator connector that occurred during production electrical tests. Subsequent investigations determined that a sharp edge in the wire harness trim connector backshell damaged the wiring insulation. The FAA is issuing this AD to address an unsafe condition that could result in yaw or pitch trim runaway and subsequent loss of control of the helicopter.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Requirements**

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with EASA AD 2019-0198.

**(h) Exceptions to EASA AD 2019-0198**

(1) Where EASA AD 2019-0198 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (1) of EASA AD 2019-0198 specifies to replace each affected part with a serviceable part within 9 months, this AD requires replacing each affected part with a serviceable part within 30 hours time-in-service after the effective date of this AD.

(3) Although the service information referenced in EASA AD 2019-0198 specifies to discard certain parts, this AD requires removing those parts from service.

(4) Where the service information referenced in EASA AD 2019-0198 specifies to use tooling, equivalent tooling may be used.

(5) Paragraph (2) of EASA AD 2019-0198 does not apply to this AD; this AD requires compliance with paragraph (i) of this AD.

(6) The "Remarks" section of EASA AD 2019-0198 does not apply to this AD.

**(i) Parts Installation Prohibition**

As of the effective date of this AD, do not install a wire harness trim connector backshell identified in paragraph (c) of this AD on any helicopter.

**(j) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, International Validation Branch, FAA, has the authority to approve

AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: [9-AVS-AIR-730-AMOC@faa.gov](mailto:9-AVS-AIR-730-AMOC@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(k) Related Information**

For more information about this AD, contact Katherine Venegas, Aviation Safety Engineer, Los Angeles ACO Branch, Compliance & Airworthiness Division, FAA, 3960 Paramount Blvd., Lakewood, CA 90712; telephone (562) 627-5353; email [katherine.venegas@faa.gov](mailto:katherine.venegas@faa.gov).

**(l) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0198, dated August 15, 2019.

(ii) [Reserved]

(3) For EASA AD 2019-0198, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0256.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on May 28, 2021.

**Gaetano A. Sciortino,**

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-13127 Filed 6-23-21; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2021-0017; Project Identifier AD-2020-01186-T; Amendment 39-21600; AD 2021-12-13]

RIN 2120-AA64

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain The Boeing Company Model 737-8 and 737-9 airplanes. This AD was prompted by a report that during refueling of the right main tank, if there is a failure of the automatic shutoff system, the refueling panel does not provide the required indication that the automatic shutoff has failed. This AD requires installing a new fuel quantity processor unit (FQPU) and doing an FQPU software check. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective July 29, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 29, 2021.

**ADDRESSES:** For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0017.

**Examining the AD Docket**

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2021-0017; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:**

Chris Baker, Aerospace Engineer, Propulsion Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3552; email: christopher.r.baker@faa.gov.

**SUPPLEMENTARY INFORMATION:**

**Background**

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 737-8 and 737-9 airplanes. The NPRM published in the **Federal Register** on April 2, 2021 (86 FR 17324). The NPRM was prompted by a report that during refueling of the right main tank, if there is a failure of the automatic shutoff system, the refueling panel does not provide the required indication that

the automatic shutoff has failed. In the NPRM, the FAA proposed to require installing a new FQPU and doing an FQPU software check. The FAA is issuing this AD to address this indication failure to warn the person fueling the airplane, which could cause overfill of the right main tank, spilled fuel, and pooling on the ground that could come in contact with an ignition source, resulting in a ground fire.

**Discussion of Final Airworthiness Directive**

*Comments*

The FAA received comments from Boeing and United Airlines who supported the NPRM without change.

*Conclusion*

The FAA reviewed the relevant data, considered any comments received, and determined that air safety requires adopting this AD as proposed. Except for minor editorial changes, this AD is adopted as proposed in the NPRM.

None of the changes will increase the economic burden on any operator.

**Related Service Information Under 1 CFR Part 51**

The FAA reviewed Boeing Special Attention Requirements Bulletin 737-28-1363 RB, dated June 2, 2020. The service information specifies procedures for replacing the FQPU having an incorrect indication threshold with an FQPU with part number 30128-06 or 30128-58, as applicable, or an FQPU with a later-approved part number, and doing an FQPU software check. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

**Costs of Compliance**

The FAA estimates that this AD affects 66 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

| Action                                | Labor cost                                | Parts cost | Cost per product | Cost on U.S. operators |
|---------------------------------------|---|------------|------------------|------------------------|
| Installation and software check ..... | 3 work-hour × \$85 per hour = \$255 ..... | \$0        | \$255            | \$16,830               |

The FAA has included all known costs in this cost estimate. According to the manufacturer, however, some or all of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected operators.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**2021-12-13 The Boeing Company:**

Amendment 39-21600; Docket No. FAA-2021-0017; Project Identifier AD-2020-01186-T.

**(a) Effective Date**

This airworthiness directive (AD) is effective July 29, 2021.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 737-8 and 737-9 airplanes, certificated in any category, as identified in Boeing Special Attention Requirements Bulletin 737-28-1363 RB, dated June 2, 2020.

**(d) Subject**

Air Transport Association (ATA) of America Code 28, Fuel.

**(e) Unsafe Condition**

This AD was prompted by a report that during refueling of the right main tank, if there is a failure of the automatic shutoff system, the refueling panel does not provide the required flashing indication that the automatic shutoff has failed to shut off the fuel. The FAA is issuing this AD to address this indication failure to warn the person fueling the airplane, which could cause overflow of the right main tank, spilled fuel, and pooling on the ground that could come in contact with an ignition source, resulting in a ground fire.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Except as specified by paragraph (h) of this AD, at the applicable times specified in the "Compliance" paragraph of Boeing Special Attention Requirements Bulletin 737-28-1363 RB, dated June 2, 2020, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Special Attention Requirements Bulletin 737-28-1363 RB, dated June 2, 2020.

**Note 1 to paragraph (g):** Guidance for accomplishing the actions required by this AD can be found in Boeing Special Attention Service Bulletin 737-28-1363, dated June 2, 2020, which is referred to in Boeing Special Attention Requirements Bulletin 737-28-1363 RB, dated June 2, 2020.

**(h) Exception to Service Information Specifications**

Where Boeing Special Attention Requirements Bulletin 737-28-1363 RB, dated June 2, 2020, uses the phrase "the Original Issue date of Requirements Bulletin 737-28-1363 RB," this AD requires using "the effective date of this AD."

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration

deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**(j) Related Information**

(1) For more information about this AD, contact Chris Baker, Aerospace Engineer, Propulsion Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3552; email: [christopher.r.baker@faa.gov](mailto:christopher.r.baker@faa.gov).

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (4) of this AD.

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Requirements Bulletin 737-28-1363 RB, dated June 2, 2020.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on June 3, 2021.

**Gaetano A. Sciortino,**

*Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2021-13125 Filed 6-23-21; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2020-0680; Project Identifier 2020-NM-079-AD; Amendment 39-21598; AD 2021-12-11]**

**RIN 2120-AA64**

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** The FAA is superseding Airworthiness Directive (AD) 2016-25-29, which applied to certain The Boeing Company Model 767-200 and -300 series airplanes. AD 2016-25-29 required replacing the cargo compartment insulation blankets on the left and right sides with new insulation blankets that incorporate fire stops. This AD was prompted by a report of a fire in the bilge area of the cargo compartment that burned through the insulation blankets that were intended to prevent smoke from migrating behind the cargo compartment sidewall liners and upward into the main cabin. This AD continues to require the actions in AD 2016-25-29 for certain airplanes. This AD also adds airplanes to the applicability and requires a general visual inspection of the replacement insulation blankets to determine if the blankets are in serviceable condition and correctly installed, and applicable on-condition actions. For certain airplanes, this AD also requires an inspection to determine the insulation blanket part number installed; replacement of additional insulation blankets; and applicable on-condition actions. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective July 29, 2021.

The Director of the Federal Register approved the incorporation by reference of a certain publications listed in this AD as of July 29, 2021.

**ADDRESSES:** For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0680.

**Examining the AD Docket**

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0680; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this