

Proposed Rules

Federal Register

Vol. 87, No. 56

Wednesday, March 23, 2022

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2022-0288; Project Identifier MCAI-2021-00913-G]

RIN 2120-AA64

Airworthiness Directives; Alexander Schleicher GmbH & Co. Segelflugzeugbau Gliders

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Alexander Schleicher GmbH & Co. Segelflugzeugbau Model ASW-15 gliders. This proposed AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as wing root damage. This proposed AD would require repetitively inspecting the wing root ribs for cracks, looseness, and damage and replacing any root rib with a crack, a loose rib or lift pin bushing, or any damage. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by May 9, 2022.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5

p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Alexander Schleicher GmbH & Co. Segelflugzeugbau, Alexander-Schleicher-Str. 1, Poppenhausen, Germany D-36163; phone: +49 (0) 06658 89-0; email: info@alexander-schleicher.de; website: <https://www.alexander-schleicher.de>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0288; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the MCAI, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; email: jim.rutherford@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2022-0288; Project Identifier MCAI-2021-00913-G” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any

personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2021-0187, dated August 9, 2021 (referred to after this as “the MCAI”), to address an unsafe condition on certain Alexander Schleicher GmbH & Co. Segelflugzeugbau Model ASW 15 gliders. The MCAI states:

Occurrences were reported of finding wing root rib damage. Investigation is ongoing to determine the root cause of the damage.

This condition, if not detected and corrected, could reduce the structural integrity of the wing assembly of the sailplane.

To address this potential unsafe condition, Schleicher issued the TN [technical note] to provide inspection instructions.

For the reasons described above, this [EASA] AD requires repetitive inspections of each affected part and, depending on findings, replacement. This [EASA] AD also introduces restrictions for installation of an affected part.

You may examine the MCAI in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2022–0288.

Related Service Information Under 14 CFR Part 51

The FAA reviewed Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Technical Note No. 29, dated June 28, 2021. This service information specifies inspecting the root ribs at the wings.

The FAA also reviewed Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Repair instruction exchange of wing root ribs according to TN 29, dated June 28, 2021. This service information specifies procedures for replacing the root ribs.

In addition, the FAA reviewed Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Maintenance Instruction G, Issue 1, dated June 28, 2021. This service information specifies procedures for inspecting the root ribs at the wings for damage.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in **ADDRESSES**.

FAA's Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described

in the MCAI and service information referenced above. The FAA is issuing this NPRM after determining the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in the service information already described.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 20 gliders of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspect root ribs	1 work-hour × \$85 per hour = \$85	Not Applicable	\$85	\$1,700

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the proposed inspection. The agency has no way of determining the

number of gliders that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replace all four root ribs	8 work-hours × \$85 per hour = \$680	\$1,000	\$1,680

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Alexander Schleicher GmbH & Co.

Segelflugzeugbau: Docket No. FAA–2022–0288; Project Identifier MCAI–2021–00913–G.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by May 9, 2022.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Alexander Schleicher GmbH & Co. Segelflugzeugbau Model ASW-15 gliders, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 5712, Wing, Rib/Bulkhead.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as wing root rib damage. The FAA is issuing this AD to detect and correct damaged root ribs. The unsafe condition, if not addressed, could result in reduced structural integrity of the wing assembly, which could lead to loss of control of the glider.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Action

(1) Within 30 days after the effective date of this AD and thereafter at intervals not to exceed 12 months, inspect all wing root ribs (4 places) for cracks, looseness, and damage in accordance with the Action section in Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Maintenance Instruction G, Issue 1, dated June 28, 2021. If there is a crack in any root rib, a loose rib or lift pin bushing, or any damage, before further flight, replace the root rib in accordance with Action paragraph (B) in Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Technical Note No. 29, dated June 28, 2021, and steps 1 through 7 in Alexander Schleicher GmbH & Co. Segelflugzeugbau ASW 15 Repair instruction exchange of wing root ribs according to TN 29, dated June 28, 2021.

(2) Replacing all four wing root ribs is terminating action for the repetitive inspections required by this AD.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i)(1) of this AD and email to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

(1) For more information about this AD, contact Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft

Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; email: jim.rutherford@faa.gov.

(2) Refer to MCAI European Union Aviation Safety Agency (EASA) AD 2021-0187, dated August 9, 2021, for related information. You may examine the EASA AD in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0288.

(3) For service information identified in this AD, contact Alexander Schleicher GmbH & Co. Segelflugzeugbau, Alexander-Schleicher-Str. 1, Poppenhausen, Germany D-36163 ; phone: +49 (0) 06658 89-0; email: info@alexander-schleicher.de; website: <https://www.alexander-schleicher.de>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110.

Issued on March 15, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-05873 Filed 3-22-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2022-0167; Airspace Docket No. 22-AGL-14]

RIN 2120-AA66

Proposed Establishment of Class D Airspace; Chicago/Romeoville, IL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to establish Class D airspace at Chicago/Romeoville, IL. The FAA is proposing this action to support the establishment of an air traffic control tower at Lewis University Airport, Chicago/Romeoville, IL.

DATES: Comments must be received on or before May 9, 2022.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590; telephone (202) 366-9826, or (800) 647-5527. You must identify FAA Docket No. FAA-2022-0167/Airspace Docket No. 22-AGL-14 at the beginning of your comments. You may also submit comments through the internet at <https://www.regulations.gov>.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays.

FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

FOR FURTHER INFORMATION CONTACT:

Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5711.

SUPPLEMENTARY INFORMATION:**Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would establish Class D airspace at Lewis University Airport, Chicago/Romeoville, IL, to support instrument flight rule operations at this airport.

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped