

exceeds 880 FHs after the effective date of this AD.

(ii) For affected engines not requiring the performance of a rotational torque check by paragraph (g)(2)(i) of this AD, if the affected engine is installed on an airplane that was parked less than or equal to 50 miles from a saltwater coastline for 250 or more parked days, before exceeding 440 FHs after the effective date of this AD, perform a rotational torque check of the actuating linkage assembly. If an airplane has two affected engines installed while parked less than or equal to 50 miles from a saltwater coastline for 250 or more parked days, operators may perform the rotational torque check of the actuating linkage assembly on the second engine before the second engine exceeds 880 FHs after the effective date of this AD.

(iii) For affected engines not requiring the performance of a rotational torque check by paragraphs (g)(2)(i) or (g)(2)(ii) of this AD, before exceeding 880 FHs after the effective date of this AD, perform a rotational torque check of the actuating linkage assembly. If an airplane has two affected engines installed, operators may perform the rotational torque check of the actuating linkage assembly on the second engine before the second engine exceeds 1,680 FHs after the effective date of this AD.

(3) Torque Check: All Affected Engines That Are Not currently in Service

If the affected engine is installed on an airplane that was parked outdoors for 250 or more parked days within the 24 months prior to re-entering service, or if the engine was off-wing and stored outdoors for 250 or more days within the 24 months prior to reentering service, before further flight, perform a rotational torque check of the actuating linkage assembly.

(4) Replacement of the Compressor Inlet Guide Vane (IGV) Outer Shroud Bushing and Vane Spindle Bushing

If the actuating linkage assembly does not pass any rotational torque check required by paragraphs (g)(1) through (3) of this AD, before further flight, remove the compressor IGV outer shroud bushing and vane spindle bushing and replace with a zero cycles since new compressor IGV outer shroud bushing and vane spindle bushing.

(5) Service Information for Performance of the Rotational Torque Check and Replacement of the Compressor IGV Outer Shroud Bushing and Vane Spindle Bushing

Use the Accomplishment Instructions, paragraph 3.A.(1)(c), of GE CF34-8C Service Bulletin (SB) 72-0356 R00 or GE CF34-8E SB 72-0244 R00, both dated February 15, 2022, as applicable to the engine model, to perform the actions required by paragraphs (g)(1) through (4) of this AD.

(h) Reporting Requirements

Within 10 days after performing the rotational torque check required by paragraphs (g)(1) through (3) of this AD, in accordance with paragraph 3.A.(1)(c), of GE CF34-8C SB 72-0356 or GE CF34-8E SB 72-0244, send your inspection report form, pictures, or report findings to GE at aviation.fleetsupport@ge.com.

(i) Definition

(1) For the purpose of this AD, a “parked day” is 24 consecutive hours without engine operation.

(2) For the purpose of this AD, “outdoors” is any location that is not environmentally controlled, including any non-environmentally controlled facility.

(j) Special Flight Permit

Special flight permits are prohibited.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l) of this AD and email it to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

For more information about this AD, contact Scott Stevenson, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238-7132; email: Scott.M.Stevenson@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) GE CF34-8C Service Bulletin (SB) 72-0356 R00, dated February 15, 2022.

(ii) GE CF34-8E SB 72-0244 R00, dated February 15, 2022.

(3) For GE service information identified in this AD, contact General Electric Company, 1 Neumann Way, Cincinnati, OH 45215; phone: (513) 552-3272; email: aviation.fleetsupport@ge.com; website: <https://www.ge.com>.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on April 4, 2022.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-08037 Filed 4-11-22; 4:15 pm]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2021-1013; Project Identifier MCAI-2020-01530-T; Amendment 39-21980; AD 2022-06-14]

RIN 2120-AA64

Airworthiness Directives; BAE Systems (Operations) Limited Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2017-12-08, which applied to all BAE Systems (Operations) Limited Model BAe 146-100A, -200A, and -300A airplanes; and Model Avro 146-RJ70A, 146-RJ85A, and 146-RJ100A airplanes. AD 2017-12-08 required revising the maintenance or inspection program, as applicable, to incorporate new or revised structural inspection requirements. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective May 19, 2022.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 19, 2022.

ADDRESSES: For service information identified in this final rule, contact BAE Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email RAPublications@baesystems.com; internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch,

2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–1013.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–1013; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Todd Thompson, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3228; email todd.thompson@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The Civil Aviation Authority (CAA), which is the aviation authority for the United Kingdom, has issued CAA AD G–2021–0011, dated October 8, 2021 (CAA AD G–2021–0011) (also referred to as the Mandatory Continuing Airworthiness Information, or the MCAI), to correct an unsafe condition for all BAe 146 and AVRO 146–RJ airplanes. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–1013.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2017–12–08, Amendment 39–18923 (82 FR 27414, June 15, 2017) (AD 2017–12–08). AD 2017–12–08 applied to all BAE Systems (Operations) Limited Model BAe 146–100A, –200A, and –300A airplanes; and Model Avro 146–RJ70A, 146–RJ85A, and 146–RJ100A airplanes. The NPRM published in the **Federal Register** on November 23, 2021 (86 FR 66471). The NPRM was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The NPRM proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations.

The FAA is issuing this AD to address fatigue cracking of certain structural elements, which could adversely affect the structural integrity of the airplane. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA has considered the comment received. An individual indicated their support for the NPRM.

Conclusion

The FAA reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 14 CFR Part 51

BAE Systems has issued Chapter 05, Time Limits/Maintenance Checks, of the BAe 146 Series/AVRO 146–RJ Series Aircraft Maintenance Manual, Revision 132, dated June 15, 2021. This service information describes airworthiness limitations, including life limits, maintenance tasks, and critical design configuration control limitations (CDCLs).

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 30 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

The FAA estimates the total cost per operator for the retained actions from AD 2017–12–08 to be \$7,650 (90 work-hours × \$85 per work-hour).

The FAA has determined that revising the maintenance or inspection program takes an average of 90 work-hours per operator, although the agency recognizes that this number may vary from operator to operator. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), the FAA has determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, the agency estimates the average total cost per

operator to be \$7,650 (90 work-hours × \$85 per work-hour).

The FAA estimates the total cost per operator for the new actions to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
 - a. Removing Airworthiness Directive (AD) 2017–12–08, Amendment 39–18923 (82 FR 27414, June 15, 2017); and
 - b. Adding the following new AD:

2022–06–14 BAE Systems (Operations)

Limited: Amendment 39–21980; Docket No. FAA–2021–1013; Project Identifier MCAI–2020–01530–T.

(a) Effective Date

This airworthiness directive (AD) is effective May 19, 2022.

(b) Affected ADs

This AD replaces AD 2017–12–08, Amendment 39–18923 (82 FR 27414, June 15, 2017) (AD 2017–12–08).

(c) Applicability

This AD applies to all BAE Systems (Operations) Limited airplanes, certificated in any category, identified in paragraphs (c)(1) and (2) of this AD.

(1) Model BAe 146–100A, –200A, and –300A airplanes.

(2) Model Avro 146–RJ70A, 146–RJ85A, and 146–RJ100A airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address fatigue cracking of certain structural elements, which could adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Revision to the Maintenance or Inspection Program, With No Changes

This paragraph restates the requirements of paragraph (i) of AD 2017–12–08, with no changes. Within 90 days after July 20, 2017 (the effective date of AD 2017–12–08): Revise the maintenance or inspection program, as applicable, to incorporate new and revised limitations, tasks, thresholds, and intervals using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA.

Note 1 to paragraph (g): An additional source of guidance for the actions specified in paragraph (g) of this AD can be found in BAe 146/AVRO 146–RJ Airplane Maintenance Manual, Revision 112, dated October 15, 2013.

Note 2 to paragraph (g): An additional source of guidance for the actions specified in paragraph (g) of this AD can be found in Corrosion Prevention Control Program (CPCP) Document No. CPCP–146–01, Revision 4, dated September 15, 2010.

Note 3 to paragraph (g): An additional source of guidance for the actions specified

in paragraph (g) of this AD can be found in Supplemental Structural Inspections Document (SSID) Document No. SSID–146–01, Revision 2, dated August 15, 2012.

Note 4 to paragraph (g): An additional source of guidance for the actions specified in paragraph (g) of this AD can be found in Maintenance Review Board Report Document No. MRB 146–01, Issue 2, Revision 19, dated August 2012.

Note 5 to paragraph (g): An additional source of guidance for the actions specified in paragraph (g) of this AD can be found in BAE Systems (Operations) Limited Inspection Service Bulletin ISB.53–237, Revision 1, dated April 2, 2013.

(h) Retained No Alternative Actions, Intervals, and/or Critical Design Configuration Control Limitations (CDCCLs), With No Changes

This paragraph restates the requirements of paragraph (j) of AD 2017–12–08, with no changes. Except as specified in paragraph (i) of this AD: After accomplishing the revision required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, and/or CDCCLs may be used, unless the actions, intervals, and/or CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (k)(1) of this AD.

(i) New Maintenance or Inspection Program Revision

Within 90 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Chapter 05, Time Limits/Maintenance Checks, of the BAE Systems BAe 146 Series/AVRO 146–RJ Series Aircraft Maintenance Manual, Revision 132, dated June 15, 2021. The initial compliance time for doing the tasks is at the time specified in Chapter 05, Time Limits/Maintenance Checks, of the BAE Systems BAe 146 Series/AVRO 146–RJ Series Aircraft Maintenance Manual, Revision 132, dated June 15, 2021, or within 90 days after the effective date of this AD, whichever occurs later. Accomplishing the revision of the existing maintenance or inspections program required by this paragraph terminates the actions required by paragraph (g) of this AD.

(j) New No Alternative Actions, Intervals, or CDCCLs

After the existing maintenance or inspection program has been revised as required by paragraph (i) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs may be used unless the actions, intervals, and/or CDCCLs are approved as an AMOC in accordance with the procedures specified in paragraph (k)(1) of this AD.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures

found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (l)(2) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(ii) AMOCs approved for AD 2017–12–08 are approved as AMOCs for the corresponding provisions of this AD.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or the Civil Aviation Authority (CAA); or BAE Systems (Operations) Limited's CAA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) CAA AD G–2021–0011, dated October 8, 2021, for related information. This MCAI may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–1013.

(2) For more information about this AD, contact Todd Thompson, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3228; email todd.thompson@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Chapter 05, Time Limits/Maintenance Checks, of the BAE Systems BAe 146 Series/AVRO 146–RJ Series Aircraft Maintenance Manual, Revision 132, dated June 15, 2021.

(ii) [Reserved]

(3) For service information identified in this AD, contact BAE Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email RApublications@baesystems.com; internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th

St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 10, 2022.

Lance T. Gant,

*Director, Compliance & Airworthiness
Division, Aircraft Certification Service.*

[FR Doc. 2022-07935 Filed 4-13-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2021-0028; **Airspace**
Docket No. 21-ASO-41]

RIN 2120-AA66

Amendment of Class E Airspace; Dyersburg, TN

AGENCY: Federal Aviation
Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends Class E surface airspace in Dyersburg, TN, as the Nally Dunston non-directional beacon (NDB) has been decommissioned, and associated approaches cancelled for Dyersburg Regional Airport. This action updates the airport's name and geographic coordinates. In addition, this action makes an editorial change replacing the term Airport/Facility Directory with the term Chart Supplement in the legal description of associated Class E airspace. Controlled airspace is necessary for the safety and management of instrument flight rules (IFR) operations in the area.

DATES: Effective 0901 UTC, July 14, 2022. The Director of the Federal Register approves this incorporation by reference action under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order JO 7400.11F, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; Telephone: (202) 267-8783

FOR FURTHER INFORMATION CONTACT: John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Avenue, College Park, GA 30337; Telephone (404) 305-6364.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends the Class E surface airspace in Dyersburg, TN, to support IFR operations in the area.

History

The FAA published a notice of proposed rulemaking in the **Federal Register** (87 FR 6439, February 4, 2022) for Docket No. FAA-2021-0028 to amend Class E surface airspace at Dyersburg Regional Airport, Dyersburg, TN.

Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. One comment supporting this action was received.

Class E airspace designations are published in Paragraph 6002 of FAA Order JO 7400.11F, dated August 10, 2021, and effective September 15, 2021, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document will be published subsequently in FAA Order JO 7400.11.

Availability and Summary of Documents for Incorporation by Reference

This document amends FAA Order JO 7400.11F, Airspace Designations and Reporting Points, dated August 10, 2021, and effective September 15, 2021. FAA Order JO 7400.11F is publicly available as listed in the **ADDRESSES** section of this document. FAA Order JO 7400.11F lists Class A, B, C, D, and E airspace areas, air traffic routes, and reporting points.

The Rule

The FAA is amending 14 CFR part 71 by amending the Class E surface airspace at Dyersburg Regional Airport, Dyersburg, TN, due the decommissioning of the Nally Dunston NDB and cancellation of associated approaches. This action increases the radius to 4.7-miles (previously 4.1-miles), and updates the airport's name (formerly Dyersburg Municipal Airport), and geographic coordinates to coincide with the FAA's database.

This action also replaces the outdated term Airport/Facility Directory with the term Chart Supplement in the airport description.

Controlled airspace is necessary for the safety and management of instrument flight rules (IFR) operations in the area.

Class E airspace designations are published in Paragraph 6002 of FAA Order JO 7400.11F, dated August 10, 2021, and effective September 15, 2021, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designations listed in this document would be published subsequently in FAA Order JO 7400.11.

FAA Order JO 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

Regulatory Notices and Analyses

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is minimal. Since this is a routine matter that only affects air traffic procedures an air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5-6.5a. This airspace action is not expected to cause any potentially significant environmental impacts, and