

# Proposed Rules

Federal Register

Vol. 87, No. 132

Tuesday, July 12, 2022

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2022-0818; Project Identifier AD-2022-00299-R]

RIN 2120-AA64

#### Airworthiness Directives; Leonardo S.p.a. Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Leonardo S.p.a. Model A109, A109A, A109A II, A109C, A109K2, A109E, A109S, and AW109SP helicopters modified by Supplemental Type Certificate (STC) SR01812LA. This proposed AD was prompted by a report of certain floats not deploying due to a faulty plunger assembly. This proposed AD would require repairing or replacing certain float assemblies. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by August 26, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** (202) 493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- For service information identified in this NPRM, contact Apical Industries,

Inc., Jason Gardiner, 3030 Enterprise Ct., Vista, CA 92081, United States; phone: (760) 542-2096; email: [jgardiner@dartaero.com](mailto:jgardiner@dartaero.com); website: <https://www.dartaerospace.com/>. You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

#### Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0818; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

#### FOR FURTHER INFORMATION CONTACT:

Johann S. Magana, Aerospace Engineer, Cabin Safety & Environmental Systems Section, Los Angeles ACO Branch, Compliance & Airworthiness Division, FAA, 3960 Paramount Blvd., Lakewood, CA 90712; telephone (562) 627-5322; email [johann.magana@faa.gov](mailto:johann.magana@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-0818; Project Identifier AD-2022-00299-R" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

#### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Johann S. Magana, Aerospace Engineer, Cabin Safety & Environmental Systems Section, Los Angeles ACO Branch, Compliance & Airworthiness Division, FAA, 3960 Paramount Blvd., Lakewood, CA 90712; telephone (562) 627-5322; email [johann.magana@faa.gov](mailto:johann.magana@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Background

The FAA received a report of two forward floats not deploying after an inadvertent activation. It was discovered that the plunger assembly caused the forward floats to not deploy. Further investigation revealed that a design change in 2009 of the plunger assembly inadvertently changed the position of the bushing from a press fit to a threaded fit. The dimensions for the threaded fit were preventing the bushing from fully clearing the ball bearings when bottom out on the solenoid on the valve assemblies. The plunger assembly is contained within the float assembly and reservoir assembly. An emergency float kit consists of float assemblies, reservoir assemblies, and additional components. These emergency float kits (634.4100 Kit Series) are installed on Leonardo S.p.a. Model A109, A109A, A109A II, A109C, A109K2, A109E, A109S, and AW109SP helicopters modified by STC SR01812LA; this STC is held by Apical Industries, Inc., d/b/a DART Aerospace (DART). This condition, if not

addressed, could result in the helicopter either rolling to one side or capsizing in an event of an emergency landing on water.

#### FAA's Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type designs.

#### Related Service Information

The FAA reviewed DART Service Bulletin SB2021-05, dated December 6, 2021. This service bulletin specifies replacing certain serial-numbered float assemblies or, if the serial number is not included as part of the service bulletin, contacting DART to validate effectiveness. The service bulletin also provides procedures for removing the float assemblies from the helicopter, discharging the reservoirs, shipping the float assemblies, and re-installing the float assemblies.

The FAA also reviewed DART's Instructions for Continued Airworthiness ICA109-1, Rev. U, dated October 27, 2020. This service information provides description, operation, disassembly, inspection, assembly, repair, and testing instructions as well as an illustrated parts list for emergency float kits and emergency float with life raft kits.

#### Proposed AD Requirements in This NPRM

This proposed AD would require repairing or replacing each float assembly part number 644.0501, 644.0502, 644.0503, 644.0504, 644.0505, or 644.0506 in certain emergency float kits with a method approved by the Manager, Los Angeles ACO Branch, FAA. These actions would be required within 300 hours time-in-service or 6 months after the effective date of the final rule of this proposed AD, whichever occurs first.

#### Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 25 helicopters of U.S. registry. Labor rates are estimated at \$85 per work-hour. Based on these numbers, the FAA estimates the following costs to comply with this proposed AD.

Replacing each float assembly would take about 4 work-hours for an estimated cost of \$340 per helicopter and up to \$8,500 for the U.S. fleet. The FAA has received no definitive data that would enable the FAA to provide parts cost estimates for the proposed actions; however, according to the manufacturer, some or all of the costs of this proposed

AD may be covered under warranty, thereby reducing the cost impact on affected operators. The FAA does not control warranty coverage for affected operators. As a result, the FAA has included all known costs in the cost estimate.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

(3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

**Leonardo S.p.a.:** Docket No. FAA-2022-0818; Project Identifier AD-2022-00299-R.

#### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by August 26, 2022.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Leonardo S.p.a. Model A109, A109A, A109A II, A109C, A109K2, A109E, A109S, and AW109SP helicopters, certificated in any category, modified by Supplemental Type Certificate SR01812LA with A109 Float (with/without Liferrafts System) DART Aerospace 634.4100 Kit Series part number (P/N) 634.4101, 634.4102, 634.4103, 634.4104, 634.4106, or 634.4107 with float assembly P/N 644.0501, 644.0502, 644.0503, 644.0504, 644.0505, or 644.0506 installed.

#### (d) Subject

Joint Aircraft System Component (JASC) Code: 2560, Emergency Equipment.

#### (e) Unsafe Condition

This AD was prompted by a report of two forward floats not deploying after an inadvertent activation. The FAA is issuing this AD to ensure the affected floats work as intended. The unsafe condition, if not addressed, could result in the helicopter either rolling to one side or capsizing in an event of an emergency landing on water.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

Within 300 hours time-in-service or within 6 months after the effective date of this AD, whichever occurs first, remove each float assembly identified in paragraph (c) of this AD and repair or replace it in accordance with a method approved by the Manager, Los Angeles ACO Branch, FAA. For a repair or replacement method to be approved by the Manager, Los Angeles ACO Branch, as required by this paragraph, the Manager's approval letter must specifically refer to this AD.

#### (h) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures

found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (i) Related Information

For more information about this AD, contact Johann S. Magana, Aerospace Engineer, Cabin Safety & Environmental Systems Section, Los Angeles ACO Branch, Compliance & Airworthiness Division, FAA, 3960 Paramount Blvd., Lakewood, CA 90712; telephone (562) 627-5322; email [johann.magana@faa.gov](mailto:johann.magana@faa.gov).

Issued on July 5, 2022.

**Christina Underwood,**

*Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2022-14696 Filed 7-11-22; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2022-0817; Project Identifier MCAI-2022-00369-T]

**RIN 2120-AA64**

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model Airbus A350-941 and A350-1041 airplanes. This proposed AD was prompted by a determination that, in the event of rapid decompression at a specific location of the airplane, possible deflections of the passenger floor cross beams may result in wiring damages, leading to potential system losses. This proposed AD would require amending the existing airplane flight manual (AFM) to update the landing performance database, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by August 26, 2022.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.
- **Fax:** 202-493-2251.
- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material that will be incorporated by reference (IBR) in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this material on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0817.

#### Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2022-0817; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

**FOR FURTHER INFORMATION CONTACT:** Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone 206-231-3225; email [dan.rodina@faa.gov](mailto:dan.rodina@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include "Docket No. FAA-2022-0817; Project Identifier

MCAI-2022-00369-T" at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

#### Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Dan Rodina, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th Street, Des Moines, WA 98198; telephone and 206-231-3225; email [dan.rodina@faa.gov](mailto:dan.rodina@faa.gov). Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2022-0054, dated March 23, 2022 (EASA AD 2022-0054) (also referred to as the MCAI), to correct an unsafe condition for certain Airbus A350-941 and A350-1041 airplanes. EASA AD 2022-0054 supersedes EASA AD 2022-0045, dated March 16, 2022 (EASA AD 2022-0045), which was issued to correct the unsafe condition. However, the revision of the AFM referenced in EASA AD 2022-0045 did not include the required amendments.