

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Pratt & Whitney Canada Corp.: Docket No. FAA–2022–1477; Project Identifier MCAI–2022–00632–E.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by January 3, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Pratt & Whitney Canada Corp. (P&WC) PT6E–67XP model turboprop engines with serial number HP0194 and earlier, as identified in Transport Canada AD CF–2022–26, dated May 26, 2022 (Transport Canada AD CF–2022–26).

(d) Subject

Joint Aircraft Service Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by reports of multiple incidents in which engines were unable to achieve the required power (torque) during high power applications due to internal leaks in the bleed-off valves (BOVs) caused by glass bead contamination. The FAA is issuing this AD to prevent internal leaks in the BOVs, and to prevent the failure of the engine to achieve the required power (torque) during high power applications. The unsafe condition, if not addressed, could result in loss of thrust control and loss of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Except as specified in paragraphs (h) and (i) of this AD: Perform all required actions within the compliance times specified in, and in accordance with, Transport Canada AD CF–2022–26.

(h) Exceptions to Transport Canada AD CF–2022–26

(1) Where Transport Canada AD CF–2022–26 refers to hours air time, this AD requires using flight hours.

(2) Where Transport Canada AD CF–2022–26 specifies compliance from its effective date, this AD requires using the effective date of this AD.

(i) No Reporting Requirement

Although the service information referenced in Transport Canada AD CF–2022–26 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in § 39.19. In accordance with § 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD or email to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(k) Additional Information

For more information about this AD, contact Barbara Caufield, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7146; email: barbara.caufield@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Transport Canada AD CF–2022–26, dated May 26, 2022.

(ii) [Reserved]

(3) For Transport Canada AD CF–2022–26, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; phone: (888) 663–3639; email: AD-CN@tc.gc.ca; website: tc.canada.ca/en/aviation.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on November 10, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–25019 Filed 11–17–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2022–1421; Project Identifier MCAI–2022–01088–G]

RIN 2120–AA64

Airworthiness Directives; Stemme AG Gliders

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to supersede Airworthiness Directive (AD) 2022–01–09, which applies to certain Stemme AG Model Stemme S 10–VT and Model Stemme S 12 gliders. AD 2022–01–09 requires removing the affected freewheel clutch from service and prohibits the installation of affected parts. Since the FAA issued AD 2022–01–09, the European Union Aviation Safety Agency (EASA) superseded its mandatory continuing airworthiness information (MCAI) to amend the definition of an affected part. This proposed AD would retain the requirements of AD 2022–01–09 for removing the affected freewheel clutch from service and continue to prohibit the installation of an affected part, and would amend the definition of an affected part and clarify the part installation prohibition. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by January 3, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax:* (202) 493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2022–1421; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the MCAI, any comments received, and other

information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT: Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4165; email: jim.rutherford@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2022-1421; Project Identifier MCAI-2022-01088-G” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as

private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Jim Rutherford, Aviation Safety Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA issued AD 2022-01-09, Amendment 39-21897 (87 FR 1666, January 12, 2022) (AD 2022-01-09), for all Stemme AG Model Stemme S 10-VT and Model Stemme S 12 gliders with a freewheel clutch part number (P/N) 12AK with a serial number starting with “12-” installed. AD 2022-01-09 was prompted by MCAI originated by EASA, which is the Technical Agent for the Member States of the European Union. EASA issued EASA Emergency AD 2021-0278-E, dated December 15, 2021 (EASA AD 2021-0278-E), to correct an unsafe condition identified as unintended slipping of the freewheel clutch with overheating (burnishing) of the friction pads inside of the clutch.

AD 2022-01-09 requires removing the affected freewheel clutch from service and prohibits installing an affected part on any glider. The FAA issued AD 2022-01-09 to address unintended slipping of the freewheel clutch with overheating (burnishing) of the friction pads inside of the clutch, which if not addressed, could result in a loss of thrust and consequent loss of glider control.

Actions Since AD 2022-01-09 Was Issued

Since the FAA issued AD 2022-01-09, EASA superseded EASA AD 2021-0278-E and issued EASA AD 2021-0278R1, dated August 11, 2022 (referred to after this as “the MCAI”), to correct an unsafe condition on all Stemme AG Model Stemme S 10-VT and Stemme S 12 gliders. The MCAI states that the definition of affected part was amended to exclude certain modified and re-identified freewheel clutches.

You may examine the MCAI in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2022-1421.

FAA’s Determination

These products have been approved by the aviation authority of another country and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI and service information described above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of these same type designs.

Proposed AD Requirements in this NPRM

This proposed AD would retain the requirements of AD 2022-01-09 for removing the affected freewheel clutch from service and continue to prohibit the installation of an affected part, and would amend the definition of an affected part and clarify the part installation prohibition.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 63 gliders of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Remove freewheel clutch from service	4 work-hours × \$85 per hour = \$340	\$500	\$840	\$52,920

The new requirements of this proposed AD add no additional economic burden over that already required by AD 2022-01-09.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I,

section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under

that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
 - a. Removing Airworthiness Directive 2022–01–09, Amendment 39–21897 (87 FR 1666, January 12, 2022); and
 - b. Adding the following new airworthiness directive:

Stemme AG: Docket No. FAA–2022–1421; Project Identifier MCAI–2022–01088–G.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by January 3, 2023.

(b) Affected ADs

This AD replaces AD 2022–01–09, Amendment 39–21897 (87 FR 1666, January 12, 2022).

(c) Applicability

This AD applies to Stemme AG Model Stemme S 10–VT and Model Stemme S 12 gliders, all serial numbers, certificated in any category, with a freewheel clutch having part number 12AK with a serial number starting with “12-” installed, except those which

have been modified by following the instructions of Stemme Service Bulletin Doc. No. P062–980058, Revision 02, dated April 19, 2022, and have been re-identified with “M” at the end of the serial number.

(d) Subject

Joint Aircraft System Component (JASC) Code 7100, Powerplant System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI identifies the unsafe condition as unintended slipping of the freewheel clutch with overheating (burnishing) of the friction pads inside of the clutch. The FAA is issuing this AD to ensure removal of the affected freewheel clutch from service. The unsafe condition, if not addressed, could result in a loss of thrust and consequent loss of glider control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Action and Compliance

(1) Before further flight after the effective date of this AD, remove the freewheel clutch from service.

(2) As of the effective date of this AD, do not install a freewheel clutch part number 12AK with a serial number starting with 201F;12-” on any glider, unless it has been modified by following the instructions of Stemme Service Bulletin Doc. No. P062–980058, Revision 02, dated April 19, 2022, and has been re-identified with “/M” at the end of the serial number.

(h) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in § 39.19. In accordance with § 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to the address identified in paragraph (i)(2) of this AD or email to: 9-AVS-AIR-730-AMOC@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. AMOCs approved for AD 2022–01–09 are approved as AMOCs for the corresponding provisions of this AD.

(i) Additional Information

(1) Refer to European Union Aviation Safety Agency (EASA) AD 2021–0278R1, dated August 11, 2022, for related information. This EASA AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2022–1421.

(2) For more information about this AD, contact Jim Rutherford, Aviation Safety

Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329–4165; email: jim.rutherford@faa.gov.

(3) For service information identified in this AD that is not incorporated by reference, contact Stemme AG, Flugplatzstrasse F2, Nr. 6–7, D–15344 Strausberg, Germany; phone: +49 (0) 3341 3612–0; fax: +49 (0) 3341 3612–30; email: airworthiness@stemme.de; website: stemme.com. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

(j) Material Incorporated by Reference

None.

Issued on November 9, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022–25020 Filed 11–17–22; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2022–1412; Project Identifier MCAI–2022–00805–T]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Airbus SAS Model A300 B2K–3C, B2–203, B4–2C, and B4–203 airplanes. This proposed AD was prompted by a determination that internal system pollution can occur, most likely due to corroded unions in the pressurization lines, with an associated risk of contamination of the check valves. This proposed AD would require repetitive inspections (functional checks) of the pressurization of the hydraulic system reservoirs, and corrective actions if necessary, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 3, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR