

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2020–14–01 Bell Textron Inc. (Type Certificate Previously Held by Bell Helicopter Textron Inc.): Amendment 39–21155; Docket No. FAA–2020–0171; Product Identifier 2018–SW–028–AD.

(a) Applicability

This AD applies to Bell Textron Inc. (Bell) Model 214ST helicopters, certificated in any category, with a spindle to yoke bolt (bolt) part number (P/N) 214–010–262–103 and serial number (S/N) BH179163, BH179164, BH179169, BH179170, BH179171, BH179175, BH179176, BH179178, BH224783, BH224751, BH224756, BH224764, BH224765, BH383851, BH383853, BH383855, BH383856, BH383857, BH383858, BH383860, BH383861, BH383862, BH383864, BH383865, BH383868, BH383872, BH383873, BH383878, or BH383879 installed.

(b) Unsafe Condition

This AD was prompted by the discovery that bolts have nonconforming external thread root radii. The unsafe condition, if not addressed, could result in the spindle separating from the yoke and subsequent loss of control of the helicopter.

(c) Effective Date

This AD is effective August 11, 2020.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 25 hours time-in-service, remove from service each bolt listed in paragraph (a) of this AD.

(2) After the effective date of this AD, do not install on any helicopter a bolt with a P/N and S/N listed in paragraph (a) of this AD.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, DSCO Branch, FAA, may approve AMOCs for this AD. Send your proposal to Haytham Alaidy, Aviation Safety Engineer, DSCO Branch, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; phone: 817–222–5224; fax: 817–222–4960; email: haytham.alaidy@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, the FAA suggests that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before

operating any aircraft complying with this AD through an AMOC.

(g) Related Information

Bell Helicopter Textron Alert Service Bulletin 214ST–18–93 Revision A, dated April 17, 2019, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Bell Textron Inc., P.O. Box 482, Fort Worth, TX 76101; telephone 817–280–3391; fax 817–280–6466; or at <https://www.bellcustomer.com>. You may view a copy of information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 6200, Main Rotor.

Issued on June 23, 2020.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020–14210 Filed 7–6–20; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2019–0800; Project Identifier 2005–NE–24–AD; Amendment 39–21153; AD 2020–13–08]

RIN 2120–AA64

Airworthiness Directives; General Electric Company Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) 2005–23–09 for all General Electric Company (GE) CF6–80E1A1, –80E1A2, –80E1A3, –80E1A4, and –80E1A4/B model turbofan engines. AD 2005–23–09 required initial and repetitive fluorescent-penetrant inspections (FPI) of certain areas of high-pressure compressor (HPC) cases, part number (P/N) 1509M97G07 and P/N 2083M69G03. This AD requires an update of the Airworthiness Limitations Section (ALS) of GE Engine Manual GEK99376 and the operator's existing continuous airworthiness maintenance program (CAMP). This AD was prompted by GE performed an updated lifing analysis on the HPC case. As a result, GE found additional locations on the cases requiring FPI, revised the inspection interval for performing FPI of the existing location, and added an

additional P/N HPC case that requires inspection. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective August 11, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 11, 2020.

ADDRESSES: For service information identified in this final rule, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH, 45215; phone: 513–552–3272; email: aviation.fleetsupport@ge.com. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA, 01803. For information on the availability of this material at the FAA, call 781–238–7759. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0800.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0800; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Scott Stevenson, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: (781) 238–7132; fax: (781) 238–7199; email: Scott.M.Stevenson@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2005–23–09, Amendment 39–14367 (70 FR 67901, November 9, 2005), (“AD 2005–23–09”). AD 2005–23–09 applied to all GE CF6–80E1A1, –80E1A2, –80E1A3, –80E1A4, and –80E1A4/B model turbofan engines. The NPRM published in the **Federal Register** on January 21, 2020 (85 FR 3284). The NPRM was prompted by GE performing an updated lifing analysis on the HPC case. As a result, GE found additional locations on the cases

requiring FPI, revised the inspection interval for performing FPI of the existing location, and added an additional P/N HPC case that requires inspection. The NPRM proposed to require an update of the ALS of GE Engine Manual GEK99376 and the operator's existing CAMP. The FAA is issuing this AD to address the unsafe condition on these products.

Comments

The FAA gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA's response to each comment.

Request for Clarification on Task Referenced in AD

EASA and Delta Airlines (Delta) requested clarification on whether TASK 05–21–02–200–001, dated September 15, 2015, referenced in the AD and in the docket, should be from Revision 47 or from Revision 48 of GE CF6–80E1 Engine Manual GEK99376, dated September 15, 2019 (“GE Engine Manual”). Delta further questioned whether the task should have the same date as the GE Engine Manual.

The FAA agrees that TASK 05–21–02–200–001, dated September 15, 2015, in Revision 48 of the GE Engine Manual is referenced correctly in this AD. The FAA notes that the task has a different date than the GE Engine Manual and the task is dated correctly in the NPRM. This task from Revision 48 of the GE Engine Manual will be uploaded to the docket upon publication of the final rule.

Request To Include Reference to Later Revisions of Engine Manual

Delta requested that the FAA include a reference to “and later approved revisions” when referencing the GE Engine Manual in paragraph (g) of this AD.

The FAA disagrees because later revisions of the GE Engine Manual cannot be referenced in an AD.

Support for the AD

The Air Line Pilots Association, International, expressed support for the AD as written.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and

determined that air safety and the public interest require adopting this AD as proposed.

Related Service Information Under 1 CFR Part 51

The FAA reviewed TASK 05–21–02–200–001, dated September 15, 2015, from ESM 05–21–02, Life Limits 001 High Pressure Compressor HPC—Scheduled Maintenance Checks, of the GE CF6–80E1 Engine Manual GEK99376, Revision 48, dated September 15, 2019. The service information describes procedures for performing FPIs of the HPC case. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

The FAA estimates that this AD affects 20 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Update ALS of Engine Manual	2 work-hours × \$85 per hour = \$170	\$0	\$170	\$3,400

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA has determined that this AD will not have federalism implications under Executive Order 13132. This AD

will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by:
 - a. Removing Airworthiness Directive (AD) 2005–23–09, Amendment 39–14367 (70 FR 67901, November 9, 2005); and

- b. Adding the following new AD:

2020–13–08 General Electric Company:
Amendment 39–21153; Docket No. FAA–2019–0800; Project Identifier 2005–NE–24–AD.

(a) Effective Date

This AD is effective August 11, 2020.

(b) Affected ADs

This AD replaces AD 2005–23–09, Amendment 39–14367 (70 FR 67901, November 9, 2005).

(c) Applicability

This AD applies to General Electric Company (GE) CF6–80E1A1, –80E1A2,

–80E1A3, –80E1A4, and –80E1A4/B model turbofan engines.

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by GE performing an updated lifing analysis on the high-pressure compressor (HPC) case. Based on this analysis, GE found new locations on the case that require fluorescent penetrant inspection (FPI), identified a new inspection interval for the existing FPI location, and added another part-numbered HPC case that requires inspection. The FAA is issuing this AD to prevent failure of the HPC case. The unsafe condition, if not addressed, could result in uncontained release of the HPC case, engine fire, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Within 180 days after the effective date of this AD, replace TASK 05–21–02–200–001 in GE CF6–80E1 Engine Manual GEK99376 and the operator's existing continuous airworthiness maintenance program with TASK 05–21–02–200–001, dated September 15, 2015, from ESM 05–21–02, Life Limits 001 High Pressure Compressor HPC—Scheduled Maintenance Checks, of the GE CF6–80E1 Engine Manual GEK99376, Revision 48, dated September 15, 2019.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (i) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(i) Related Information

For more information about this AD, contact Scott Stevenson, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781–238–7132; fax: 781–238–7199; email: scott.m.stevenson@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) TASK 05–21–02–200–001, dated September 15, 2015, from ESM 05–21–02, Life Limits 001 High Pressure Compressor HPC—Scheduled Maintenance Checks, of the GE CF6–80E1 Engine Manual GEK99376, Revision 48, dated September 15, 2019.

(ii) [Reserved]

(3) For GE service information identified in this AD, contact General Electric Company, GE Aviation, Room 285, 1 Neumann Way, Cincinnati, OH 45215; phone: 513–552–3272; email: aviation.fleetsupport@ge.com.

(4) You may view this service information at FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781–238–7759.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on June 17, 2020.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020–14458 Filed 7–6–20; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2020–0298; Airspace Docket No. 19–ANM–97]

RIN 2120–AA66

Establishment of Class E Airspace; Quinter, KS

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action establishes Class E airspace extending upward from 700 feet above the surface of the earth at Gove County Airport, Quinter, KS, to accommodate new area navigation (RNAV) procedures at the airport. This action will ensure the safety and management of instrument flight rules (IFR) operations within the National Airspace System.

DATES: Effective 0901 UTC, November 5, 2020. The Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11D, Airspace Designations and Reporting

Points, and subsequent amendments can be viewed online at [publications/](https://www.federalregister.gov). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC, 20591; telephone: (202) 267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11D at NARA, email fedreg.legal@nara.gov or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FOR FURTHER INFORMATION CONTACT:

Richard Roberts, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 S. 216th Street, Des Moines, WA 98198; telephone (206) 231–2245.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes Class E airspace extending upward from 700 feet at Gove County Airport, Quinter, KS, in support of IFR operations at the airport.

History

The FAA published a notice of proposed rulemaking in the **Federal Register** (85 FR 23495; April 28, 2020) for Docket No. FAA–2020–0298 to establish Class E airspace at Gove County Airport, Quinter, KS, in support of IFR operations at the airport. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

Class E airspace designations are published in paragraph 6005 of FAA Order 7400.11D, dated August 8, 2019, and effective September 15, 2019, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.