

issuance of Boeing Alert Requirements Bulletin B787–81205–SB270044–00 RB, Issue 002, dated July 7, 2020. A review of airplane maintenance records is acceptable in lieu of this identification requirement, if the software version can be conclusively determined from that review.

(2) Identify the version of the DCA system and MS software installed. If the installed version is not DCA MS CBP4 or a later-approved version of DCA MS software: Within 6 months after the effective date of this AD, install a new DCA system and MS software and do a software check, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787–81205–SB310014, Issue 002, dated June 14, 2017. Later-approved software versions are only those Boeing software versions that are approved as a replacement for the applicable software, and are approved as part of the type design by the FAA or The Boeing Company ODA after issuance of Boeing Alert Service Bulletin B787–81205–SB310014, Issue 002, dated June 14, 2017.

(p) Credit for Previous Actions

This paragraph provides credit for actions specified in paragraphs (n)(1) and (o)(1) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Requirements Bulletin B787–81205–SB270044–00 RB, Issue 001, dated December 18, 2018.

(q) Terminating Action for Certain Requirements of This AD

(1) Except as specified in paragraph (q)(2) of this AD: Accomplishment of the actions required by paragraph (n) or (o) of this AD, as applicable, terminates the requirements of paragraphs (g) through (m) of this AD.

(2) Accomplishment of the actions required by paragraph (n) or (o) of this AD, as applicable, terminates the requirements of paragraph (k) of this AD for that airplane only.

(3) Accomplishment of the actions required by paragraph (n) or (o) of this AD, as applicable, on all affected airplanes in an operator's fleet, and subsequent removal of figure 1 to paragraph (k) of this AD from the existing AFM, terminates the requirements of paragraph (k) of this AD for the fleet. The removal must be done no later than 6 months after the effective date of this AD.

(r) Parts Installation Prohibition

As of the effective date of this AD, installation on any airplane of FCE CBP software with a version prior to CBP5 is prohibited.

(s) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (t)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company ODA that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2015–14–07, AD 2016–07–10, and AD 2016–24–09, are approved as AMOCs for the corresponding provisions of paragraphs (g) through (l) of this AD.

(t) Related Information

(1) For more information about this AD, contact Maureen G. Fallon, Aerospace Engineer, Systems and Equipment Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3690; email: maureen.g.fallon@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (u)(7) and (8) of this AD.

(u) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on November 13, 2020.

(i) Boeing Alert Requirements Bulletin B787–81205–SB270044–00 RB, Issue 002, dated July 7, 2020.

(ii) Boeing Alert Service Bulletin B787–81205–SB310014, Issue 002, dated June 14, 2017.

(4) The following service information was approved for IBR on June 6, 2019 (84 FR 18707, May 2, 2019).

(i) Boeing Alert Service Bulletin B787–81205–SB270039–00, Issue 002, dated March 8, 2018.

(ii) [Reserved]

(5) The following service information was approved for IBR on December 2, 2016 (81 FR 86912, December 2, 2016).

(i) Boeing Alert Service Bulletin B787–81205–SB270040–00, Issue 001, dated November 25, 2016.

(ii) [Reserved]

(6) The following service information was approved for IBR on August 20, 2015 (80 FR 42014, July 16, 2015).

(i) Boeing Alert Service Bulletin B787–81205–SB270017–00, Issue 001, dated September 18, 2013.

(ii) Boeing Alert Service Bulletin B787–81205–SB270020–00, Issue 002, dated February 12, 2015.

(iii) Boeing Service Bulletin B787–81205–SB270023–00, Issue 001, dated July 24, 2014.

(7) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>.

(8) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(9) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on September 23, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020–22236 Filed 10–8–20; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA–2020–0627; Airspace Docket No. 19–ANM–29]

RIN 2120–AA66

Establishment of Class E Airspace; Granby, CO

Correction

In the rule document 2020–21888 appearing on pages 62572–62573 in the issue of Monday, October 5, 2020, make the following correction:

§ 71.1 [Corrected]

■ 1. On page 62573, in the second column, line twenty, “2.2° miles” should read “2.2 miles”

■ 2. On page 62573, in the second column, line twenty-one, “110ß bearing” should read “110° bearing”

[FR Doc. C1–2020–21888 Filed 10–8–20; 8:45 am]

BILLING CODE 1301–00–D

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Part 744

[Docket No. 200831–0029]

RIN 0694–AI10

Revisions to the Unverified List (UVL)

AGENCY: Bureau of Industry and Security, Commerce.