

**LEARJET 40
MAINTENANCE MANUAL**

TEMPORARY REVISION NO. 04-33

MANUALS AFFECTED: Learjet 40 Maintenance Manual (MM-105).

FILING INSTRUCTIONS: Insert adjacent to CSS 04-10-01, page 9, dated Nov 03/17, and retain until further notice. Record this temporary change in the "List of Temporary Revisions" at the front of the Maintenance Manual.

REASON: Revised the inspection interval of IRN AC3010006. ** Anti-Ice Manifold - Perform Boroscope Inspection from 1,200 Hours to 600 Hours.

INSTRUCTIONS: Add the following revised Time Compliance Inspection.

CERTIFICATION MAINTENANCE REQUIREMENTS - STRUCTURE CHECKS

1. Time Compliance

A. NO CHANGE

IRN	ZONE/ ACCESS	MAINTENANCE REQUIREMENTS - STRUCTURE CHECKS	INTERVAL
	300	AFT FUSELAGE/EMPENNAGE	
AC3010006	310QR, 310HL	** Anti-Ice Manifold - Perform Boroscope Inspection.	600 Hours.

**LEARJET 40
MAINTENANCE MANUAL**

FAA Approved LINDA J DICKEN Digitally signed by LINDA J DICKEN
Date: 2022.01.07 05:53:00 -06'00' Date _____

PAUL NGUYEN, MANAGER
WICHITA ACO BRANCH, AIR-7K0
FEDERAL AVIATION ADMINISTRATION

FAA Approval
Figure 1

TEMPORARY REVISION: 04-33

MM-105

04-10-01

Page 2
Jan 18/22