

### A350 XWB

### ALS Part 4

# System Equipment Maintenance Requirements

# (SEMR)

## Variation 6.1

© AIRBUS SAS 2021. All rights reserved. Confidential and proprietary document.

This document and all information contained herein is the sole property of AIRBUS SAS. No intellectual property rights are granted by the delivery of this document or the disclosure of its content. This document shall not be reproduced or disclosed to a third party (except for the purposes of performing the tasks described hereunder and provided that any recipient of such document shall comply with the conditions herein) without the express written consent of AIRBUS SAS. This document and its content shall not be used for any purpose other than that for which it is supplied.

ISSUE: JUL 20/21



The ALS Part 4 is approved and Variations must also be approved.

The technical content of this document is approved under the authority of the DOA ref. EASA.21J.031.

Note: the present Variation includes ALS data already approved either by EASA for major changes or by Airbus under DOA privilege for minor changes.

### APPROVAL REFERENCES

#### A350 ALS Part 4:

REVISION NUMBER	APPROVAL REFERENCE	APPROVAL DATE
06	V050421060	JUN 30/21

#### VARIATION:

VARIATION	ISSUE	AFFECTED	APPROVAL	APPROVAL
NUMBER	NUMBER	SECTIONS	REFERENCE	DATE
6.1	01	Section 4-2	V05042106A	JUL 20/21

### <u>REASON</u>

This Variation revises the description and the applicability of the SEMR task 783500-R10001-1-E to clarify that it applies to all Locking Actuators (LA) P/N 351D9908-689 and all Locking Feedback Actuators (LFA) P/N 351 D9908-693 fitted on A350 A/C.

### <u>APPLICABILITY</u>

This Variation applies to the following aircraft series and models:

AIRCRAFT SERIES	AIRCRAFT MODELS	
A350-900	A350-941	
A350-1000	A350-1041	



#### AIRWORTHINESS LIMITATIONS SECTION

#### COMPLIANCE TIME

The content of this Variation will be introduced in next ALS Revision. Airbus recommends Operators to consider the implementation of the new or revised instructions and airworthiness limitations introduced by this Variation in the Operators approved Maintenance Program (OMP) at the next scheduled opportunity.

Replacement of items and Maintenance tasks in SECTIONS 3 and 4 are to be accomplished prior to the new/revised thresholds and/or intervals provided in this Variation.

#### VALIDITY

Instructions and airworthiness limitations stated in this Variation may be negated by instructions and airworthiness limitations published in (a) Variation(s) or a Revision subsequent to the approval date of this Variation. In such case, the validity of this Variation is suspended.

All other instructions and airworthiness limitations given in the A350 ALS Part 4 Revision 06 remains applicable.

#### DESCRIPTION

The approved changes to the mandatory instructions and airworthiness limitations provided in the A350 ALS Part 4 Revision 06 SECTION 4-2 – SYSTEM INSTALATION MAINTENANCE REQUIREMENTS controlled at aircraft system level can be found in the attached excel file "A350 ALS Part 4 Variation 6.1.xlsx"

ISSUE: JUL 20/21

ALS PART 4 VARIATION 6.1

PAGE: 3/3