

Hey Jim,

We have been made aware that following the release of the Revision 39 of the AFMs for the Global 6000 and Global 5000 GVFD that was mandated by AD CF-2021-35 Revisions 40 and 41 undid the corrections on Figures 07-35-02 and 07-35-04. If it is still possible and you have not release your AD you should point to Revision 42 as follows:

Aeroplane Model	Marketing Designation	AFM Publication Number and Revision, dated 19 May 2022
BD-700-1A10	Global 6000	CSP 700-1V Revision 42
BD-700-1A11	Global 5000 ft. GVFD	CSP 700-5000-1V Revision 42

Hopefully this can save you some work as TCCA is having to issue another AD to correct this error in documentation.

If you have any further questions please feel free to give me a call.

Best regards,

Scott W. Wales

Senior Engineer, Corrective Action, Continuing Airworthiness – A220 & Global
Transport Canada / Government of Canada
scott.wales@tc.gc.ca / Tel: 403-690-6527 / TTY: 1-888-675-6863

Ingénieur principal, Mesure corrective, Maintien de la navigabilité aérienne – A220 & Global
Transports Canada / Gouvernement du Canada
scott.wales@tc.gc.ca / Tél. : 403-690-6527 / ATS : 1-888-675-6863