

allowable limits, remove the blade from service before further flight.

(v) If there is no swelling, deformation or crack; or if bonding separation does not exceed allowable limits, continue to perform the inspections required by this AD.

(2) For an MRB with a tip cap P/N 709-0103-29-109 installed, perform the following at the specified intervals:

(i) For each tip cap with less than 600 hours TIS, before reaching 600 hours TIS, and thereafter, at intervals not to exceed 50 hours TIS or

(ii) For each tip cap with 600 or more hours TIS, within the next 5 hours TIS or 30 days after the effective date of this AD, whichever occurs first, and thereafter at intervals not to exceed 50 hours TIS.

(A) Dye-penetrant inspect the welded bead on the tip cap leading edge (joint line between the two metal shells) for a crack in accordance with the Accomplishment Instructions, steps 3.1 through 3.6, of Leonardo Helicopters Alert Service Bulletin (ASB) No. 109-125, ASB No. 109EP-085, or ASB No. 109K-048, each at Revision A and each dated October 19, 2020, as applicable your helicopter model.

(B) If there is a crack, remove the tip cap from service before further flight.

(3) As of the effective date of this AD, do not install any MRB with tip cap P/N 709-0103-29-109 on any helicopter unless it has been inspected in accordance with the inspection requirements of this AD.

(h) Special Flight Permits

Special flight permits may be issued in accordance with 14 CFR 21.197 and 21.199 to operate the helicopter to a location where the requirements of this AD can be accomplished provided that:

- (1) No passengers are onboard;
- (2) The time to fly to the location does not exceed 10 hours TIS; and
- (3) The airspeed does not exceed 70 knots indicated air speed (KIAS).

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Fred Guerin, Aerospace Engineer, General Aviation & Rotorcraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone (206) 231-3500; email fred.guerin@faa.gov.

(2) The subject of this AD is addressed in European Union Aviation Safety Agency (EASA) AD 2020-0230, dated October 22, 2020. You may view the EASA AD on the internet at <https://www.regulations.gov> in Docket No. FAA-2021-0194.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on April 8, 2021.

(i) Leonardo Helicopters Alert Service Bulletin No. 109-125, Revision A, dated October 19, 2020.

(ii) Leonardo Helicopters Alert Service Bulletin No. 109EP-085, Revision A, dated October 19, 2020.

(iii) Leonardo Helicopters Alert Service Bulletin No. 109K-048, Revision A, dated October 19, 2020.

(4) The following service information was approved for IBR on January 7, 2002 (66 FR 60144, December 3, 2001).

(i) Agusta Alert Bollettino Tecnico No. 109-106, Revision B, dated December 19, 2000.

(ii) Agusta Alert Bollettino Tecnico No. 109EP-1, Revision B, dated December 19, 2000.

(iii) Agusta Alert Bollettino Tecnico No. 109K-22, Revision B, dated December 9, 2000.

(5) For Leonardo Helicopters and Agusta service information identified in this AD, contact Leonardo S.p.a. Helicopters, Emanuele Bufano, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39-0331-225074; fax +39-0331-229046; or at <https://www.leonardocompany.com/en/home>.

(6) You may view this service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 19, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-06200 Filed 3-22-21; 4:15 pm]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 97

[Docket No. 31360; Amdt. No. 3948]

Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This rule amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide for the safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

DATES: This rule is effective March 24, 2021. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of March 24, 2021.

ADDRESSES: Availability of matter incorporated by reference in the amendment is as follows:

For Examination

1. U.S. Department of Transportation, Docket Ops-M30, 1200 New Jersey Avenue SE, West Bldg., Ground Floor, Washington, DC 20590-0001;

2. The FAA Air Traffic Organization Service Area in which the affected airport is located;

3. The office of Aeronautical Navigation Products, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA).

For information on the availability of this material at NARA, email fedreg.legal@nara.gov or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Availability

All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit the National Flight Data Center online at nfdc.faa.gov to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from the FAA Air Traffic Organization Service Area in which the affected airport is located.

FOR FURTHER INFORMATION CONTACT:

Thomas J. Nichols, Flight Procedures and Airspace Group, Flight Technologies and Procedures Division, Flight Standards Service, Federal Aviation Administration. Mailing Address: FAA Mike Monroney Aeronautical Center, Flight Procedures and Airspace Group, 6500 South MacArthur Blvd., Registry Bldg. 29, Room 104, Oklahoma City, OK 73169. Telephone: (405) 954-4164.

SUPPLEMENTARY INFORMATION: This rule amends 14 CFR part 97 by amending the referenced SIAPs. The complete regulatory description of each SIAP is listed on the appropriate FAA Form 8260, as modified by the National Flight Data Center (NFDC)/Permanent Notice to Airmen (P-NOTAM), and is incorporated by reference under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR 97.20. The large number of SIAPs, their complex nature, and the need for a special format make their verbatim publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, but refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP contained on FAA form documents is unnecessary. This amendment provides the affected CFR sections, and specifies the SIAPs and Takeoff Minimums and ODPs with their applicable effective dates. This amendment also identifies the airport and its location, the procedure and the amendment number.

Availability and Summary of Material Incorporated by Reference

The material incorporated by reference is publicly available as listed in the **ADDRESSES** section.

The material incorporated by reference describes SIAPs, Takeoff Minimums and ODPs as identified in the amendatory language for part 97 of this final rule.

The Rule

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP and Takeoff Minimums and ODP as amended in the transmittal. For safety and timeliness of change considerations, this amendment incorporates only specific changes contained for each SIAP and Takeoff Minimums and ODP as modified by FDC permanent NOTAMs.

The SIAPs and Takeoff Minimums and ODPs, as modified by FDC permanent NOTAM, and contained in this amendment are based on criteria contained in the U.S. Standard for Terminal Instrument Procedures (TERPS). In developing these changes to SIAPs and Takeoff Minimums and ODPs, the TERPS criteria were applied only to specific conditions existing at the affected airports. All SIAP amendments in this rule have been previously issued by the FAA in a FDC NOTAM as an emergency action of immediate flight safety relating directly to published aeronautical charts.

The circumstances that created the need for these SIAP and Takeoff Minimums and ODP amendments require making them effective in less than 30 days.

Because of the close and immediate relationship between these SIAPs, Takeoff Minimums and ODPs, and safety in air commerce, I find that notice and public procedure under 5 U.S.C. 553(b) are impracticable and contrary to the public interest and, where applicable, under 5 U.S.C. 553(d), good cause exists for making these SIAPs effective in less than 30 days.

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are

necessary to keep them operationally current. It, therefore—(1) is not a “significant regulatory action” under Executive Order 12866; (2) is not a “significant rule” under DOT regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. For the same reason, the FAA certifies that this amendment will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 97

Air traffic control, Airports, Incorporation by reference, Navigation (air).

Issued in Washington, DC, on March 5, 2021.

Wade Terrell,

Aviation Safety Manager, Flight Procedures & Airspace Group, Flight Technologies and Procedures Division.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me, Title 14, CFR part 97, (is amended by amending Standard Instrument Approach Procedures and Takeoff Minimums and ODPs, effective at 0901 UTC on the dates specified, as follows:

PART 97—STANDARD INSTRUMENT APPROACH PROCEDURES

■ 1. The authority citation for part 97 continues to read as follows:

Authority: 49 U.S.C. 106(f), 106(g), 40103, 40106, 40113, 40114, 40120, 44502, 44514, 44701, 44719, 44721–44722.

■ 2. Part 97 is amended to read as follows:

By amending: § 97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; § 97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; § 97.27 NDB, NDB/DME; § 97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; § 97.31 RADAR SIAPs; § 97.33 RNAV SIAPs; and § 97.35 COPTER SIAPs, Identified as follows:

* * * *Effective Upon Publication*

AIRAC date	State	City	Airport	FDC No.	FDC date	Subject
22-Apr-21 ...	IA	Marshalltown	Marshalltown Muni	0/0038	12/21/20	VOR RWY 31, Amdt 2A.
22-Apr-21 ...	IA	Marshalltown	Marshalltown Muni	0/0039	12/21/20	VOR RWY 13, Amdt 2A.
22-Apr-21 ...	MS	Jackson	Jackson-Medgar Wiley Evers Intl.	0/6207	12/8/20	RNAV (GPS) RWY 16L, Amdt 2B.
22-Apr-21 ...	MS	Jackson	Jackson-Medgar Wiley Evers Intl.	0/6217	12/8/20	RNAV (GPS) RWY 16R, Amdt 2B.
22-Apr-21 ...	MS	Jackson	Jackson-Medgar Wiley Evers Intl.	0/6231	12/8/20	RNAV (GPS) RWY 34R, Amdt 2B.

AIRAC date	State	City	Airport	FDC No.	FDC date	Subject
22-Apr-21 ...	MS	Jackson	Jackson-Medgar Wiley Evers Intl.	0/6232	12/8/20	RNAV (GPS) RWY 34L, Amdt 3B.
22-Apr-21 ...	MS	Jackson	Jackson-Medgar Wiley Evers Intl.	0/6237	12/8/20	RADAR-1, Amdt 12.
22-Apr-21 ...	MS	Jackson	Jackson-Medgar Wiley Evers Intl.	0/6238	12/8/20	ILS OR LOC RWY 16L, Amdt 8B.
22-Apr-21 ...	MS	Jackson	Jackson-Medgar Wiley Evers Intl.	0/6239	12/8/20	VOR/DME OR TACAN RWY 16L, Orig-A.
22-Apr-21 ...	MS	Jackson	Jackson-Medgar Wiley Evers Intl.	0/6241	12/8/20	VOR/DME OR TACAN RWY 16R, Orig-A.
22-Apr-21 ...	MS	Jackson	Jackson-Medgar Wiley Evers Intl.	0/6242	12/8/20	VOR/DME OR TACAN RWY 34L, Orig-A.
22-Apr-21 ...	MS	Jackson	Jackson-Medgar Wiley Evers Intl.	0/6257	12/8/20	ILS OR LOC RWY 34L, Amdt 6C.
22-Apr-21 ...	VA	Martinsville	Blue Ridge	0/6341	12/7/20	RNAV (GPS) RWY 31, Amdt 3.
22-Apr-21 ...	MT	Helena	Helena Rgnl	0/6933	12/30/20	RNAV (GPS) X RWY 27, Amdt 1C.
22-Apr-21 ...	MT	Helena	Helena Rgnl	0/6934	12/30/20	LOC/DME BC-C, Amdt 5A.
22-Apr-21 ...	MT	Helena	Helena Rgnl	0/6936	12/30/20	ILS OR LOC Z RWY 27, Amdt 2A.
22-Apr-21 ...	OK	Medford	Medford Muni	0/7900	12/30/20	RNAV (GPS) RWY 35, Orig-B.
22-Apr-21 ...	OK	Medford	Medford Muni	0/7901	12/30/20	RNAV (GPS) RWY 17, Orig-A.
22-Apr-21 ...	OH	Akron	Akron Fulton Intl	0/8976	12/30/20	LOC RWY 25, Amdt 14A.
22-Apr-21 ...	OH	Akron	Akron Fulton Intl	0/8977	12/30/20	NDB RWY 25, Amdt 15B.
22-Apr-21 ...	OH	Akron	Akron Fulton Intl	0/8979	12/30/20	RNAV (GPS) RWY 25, Orig-B.
22-Apr-21 ...	MO	Gideon	Gideon Meml	1/0607	2/8/21	RNAV (GPS) RWY 33, Orig-A.
22-Apr-21 ...	MO	Gideon	Gideon Meml	1/0608	2/8/21	RNAV (GPS) RWY 15, Orig-A.
22-Apr-21 ...	WV	Charleston	Yeager	1/0749	2/5/21	ILS OR LOC RWY 5, Orig.
22-Apr-21 ...	TX	Center	Center Muni	1/1436	2/8/21	RNAV (GPS) RWY 35, Orig-B.
22-Apr-21 ...	TX	Center	Center Muni	1/1437	2/8/21	RNAV (GPS) RWY 17, Orig-C.
22-Apr-21 ...	TX	Henderson	Rusk County	1/1587	1/27/21	VOR/DME-A, Amdt 3B.
22-Apr-21 ...	GA	Toccoa	Toccoa Rg Letourneau Fld ..	1/1862	1/11/21	RNAV (GPS) RWY 21, Amdt 2.
22-Apr-21 ...	CO	Steamboat Springs	Steamboat Springs/Bob Adams Fld.	1/1865	1/14/21	VOR/DME-C, Amdt 1C.
22-Apr-21 ...	MA	Northampton	Northampton	1/1884	1/11/21	RNAV (GPS) RWY 14, Orig-A.
22-Apr-21 ...	MA	Northampton	Northampton	1/1885	1/11/21	VOR/DME-B, Amdt 5A.
22-Apr-21 ...	CA	Crescent City	Jack Mc Namara Field	1/1981	1/14/21	RNAV (GPS) RWY 36, Amdt 1.
22-Apr-21 ...	PA	Philipsburg	Mid-State	1/2045	2/24/21	RNAV (GPS) RWY 16, Orig-D.
22-Apr-21 ...	TX	Uvalde	Garner Fld	1/2055	2/11/21	RNAV (GPS) RWY 33, Orig-A.
22-Apr-21 ...	TX	Uvalde	Garner Fld	1/2057	2/11/21	NDB RWY 33, Amdt 2.
22-Apr-21 ...	RI	Westerly	Westerly State	1/2432	2/25/21	RNAV GPS RWY 7, Orig-B.
22-Apr-21 ...	GA	Atlanta	Covington Muni	1/2761	2/22/21	NDB RWY 28, Amdt 3B.
22-Apr-21 ...	KY	Hartford	Ohio County	1/2796	1/21/21	RNAV (GPS) RWY 21, Orig-D.
22-Apr-21 ...	KY	Hartford	Ohio County	1/2797	1/21/21	RNAV (GPS) RWY 3, Orig-D.
22-Apr-21 ...	MO	Bolivar	Bolivar Muni	1/3140	1/22/21	RNAV (GPS) RWY 36, Orig-A.
22-Apr-21 ...	MO	Bolivar	Bolivar Muni	1/3141	1/22/21	RNAV (GPS) RWY 18, Orig.
22-Apr-21 ...	TX	Lubbock	Lubbock Preston Smith Intl ..	1/3930	1/15/21	RNAV (GPS) Y RWY 17R, Amdt 2C.
22-Apr-21 ...	IA	Keokuk	Keokuk Muni	1/4082	2/17/21	RNAV (GPS) RWY 32, Orig-B.
22-Apr-21 ...	IA	Keokuk	Keokuk Muni	1/4083	2/17/21	RNAV (GPS) RWY 26, Orig-B.
22-Apr-21 ...	IA	Keokuk	Keokuk Muni	1/4086	2/17/21	RNAV (GPS) RWY 14, Orig-C.
22-Apr-21 ...	IA	Keokuk	Keokuk Muni	1/4088	2/17/21	RNAV (GPS) RWY 8, Orig-B.
22-Apr-21 ...	IA	Keokuk	Keokuk Muni	1/4090	2/17/21	ILS OR LOC/DME RWY 26, Orig-D.
22-Apr-21 ...	MO	Harrisonville	Lawrence Smith Meml	1/4305	1/22/21	RNAV (GPS) RWY 35, Orig-B.
22-Apr-21 ...	MO	Harrisonville	Lawrence Smith Meml	1/4306	1/22/21	RNAV (GPS) RWY 17, Orig-A.
22-Apr-21 ...	IL	Chicago	Chicago O'Hare Intl	1/5384	1/20/21	RNAV (GPS) Y RWY 10R, Orig-A.
22-Apr-21 ...	IL	Chicago	Chicago O'Hare Intl	1/5385	1/20/21	RNAV (GPS) PRM Y RWY 10R, Orig-A.
22-Apr-21 ...	IL	Chicago	Chicago O'Hare Intl	1/5386	1/20/21	ILS Y OR LOC Y RWY 10R, Orig-C.
22-Apr-21 ...	IL	Chicago	Chicago O'Hare Intl	1/5387	1/20/21	ILS PRM Y RWY 10R (CLOSE PARALLEL), Orig-C.
22-Apr-21 ...	IL	Sparta	Sparta Community-Hunter Fld.	1/5602	2/25/21	RNAV (GPS) RWY 18, Amdt 1B.
22-Apr-21 ...	IL	Sparta	Sparta Community-Hunter Fld.	1/5603	2/25/21	RNAV (GPS) RWY 36, Orig-A.
22-Apr-21 ...	PA	Reedsville	Mifflin County	1/5610	2/25/21	LOC RWY 6, Amdt 8C.
22-Apr-21 ...	PA	Reedsville	Mifflin County	1/5611	2/25/21	RNAV (GPS) RWY 6, Orig-B.
22-Apr-21 ...	PA	Reedsville	Mifflin County	1/5612	2/25/21	RNAV (GPS) RWY 24, Orig-C.
22-Apr-21 ...	OR	Pendleton	Eastern Oregon Rgnl At Pendleton.	1/5636	1/26/21	RNAV (GPS) RWY 29, Orig-A.
22-Apr-21 ...	CA	Sacramento	Sacramento Exec	1/6082	2/2/21	VOR RWY 2, Amdt 10E.

AIRAC date	State	City	Airport	FDC No.	FDC date	Subject
22-Apr-21 ...	CA	Sacramento	Sacramento Exec	1/6083	2/2/21	ILS OR LOC RWY 2, Amdt 24E.
22-Apr-21 ...	MD	Fort Meade(Odenton)	Tipton	1/6445	2/24/21	RNAV (GPS) RWY 10, Amdt 1B.
22-Apr-21 ...	MD	Fort Meade(Odenton)	Tipton	1/6446	2/24/21	RNAV (GPS) RWY 28, Amdt 1B.
22-Apr-21 ...	AK	Adak Island	Adak	1/6455	2/23/21	RNAV (GPS) RWY 23, Orig-A.
22-Apr-21 ...	TX	Vernon	Wilbarger County	1/6456	2/24/21	RNAV (GPS) RWY 2, Orig.
22-Apr-21 ...	TX	Vernon	Wilbarger County	1/6457	2/24/21	RNAV (GPS) RWY 20, Orig.
22-Apr-21 ...	TX	Wink	Winkler County	1/6460	2/24/21	RNAV (GPS) RWY 31, Amdt 1A.
22-Apr-21 ...	TX	Wink	Winkler County	1/6469	2/24/21	RNAV (GPS) RWY 13, Amdt 1A.
22-Apr-21 ...	TX	Palacios	Palacios Muni	1/6476	2/24/21	RNAV (GPS) RWY 13, Orig-C.
22-Apr-21 ...	VA	Staunton/Waynesboro/Harri- sonburg.	Shenandoah Valley Rgnl	1/6478	2/23/21	RNAV (GPS) RWY 5, Orig.
22-Apr-21 ...	VA	Staunton/Waynesboro/Harri- sonburg.	Shenandoah Valley Rgnl	1/6479	2/23/21	RNAV (GPS) RWY 23, Orig.
22-Apr-21 ...	VA	Staunton/Waynesboro/Harri- sonburg.	Shenandoah Valley Rgnl	1/6480	2/23/21	NDB RWY 5, Amdt 10.
22-Apr-21 ...	VA	Staunton/Waynesboro/Harri- sonburg.	Shenandoah Valley Rgnl	1/6481	2/23/21	ILS OR LOC RWY 5, Amdt 9.
22-Apr-21 ...	TX	Palacios	Palacios Muni	1/6490	2/24/21	VOR RWY 13, Amdt 10F.
22-Apr-21 ...	TX	Edinburg	South Texas Intl At Edinburg	1/6564	1/26/21	RNAV (GPS) RWY 14, Orig.
22-Apr-21 ...	TX	Edinburg	South Texas Intl At Edinburg	1/6566	1/26/21	RNAV (GPS) RWY 32, Orig.
22-Apr-21 ...	TX	Madisonville	Madisonville Muni	1/6568	1/26/21	VOR/DME RWY 18, Amdt 2B.
22-Apr-21 ...	MT	Helena	Helena Rgnl	1/6593	1/26/21	RNAV (GPS) Y RWY 9, Amdt 1B.
22-Apr-21 ...	TX	Amarillo	Rick Husband Amarillo Intl ...	1/6703	1/29/21	RADAR 1, Amdt 16A.
22-Apr-21 ...	TX	Henderson	Rusk County	1/7186	2/2/21	RNAV (GPS) RWY 17, Amdt 1.
22-Apr-21 ...	NJ	Newark	Newark Liberty Intl	1/7776	2/17/21	ILS OR LOC RWY 4R, ILS RWY 4R (CAT II AND III), Amdt 13B.
22-Apr-21 ...	NJ	Newark	Newark Liberty Intl	1/7777	2/17/21	ILS OR LOC RWY 22L, ILS RWY 22L (SA CAT I), ILS RWY 22L (CAT II AND III), Amdt 13D.
22-Apr-21 ...	KS	Wichita	Wichita Dwight D Eisen- hower National.	1/8084	3/1/21	ILS OR LOC RWY 1R, Amdt 17C.
22-Apr-21 ...	AR	Newport	Newport Rgnl	1/8232	3/1/21	VOR RWY 18, Amdt 4B.
22-Apr-21 ...	KS	Belleville	Belleville Muni	1/8987	2/2/21	VOR-A, Amdt 3D.
22-Apr-21 ...	TN	Morristown	Moore-Murrell	1/9040	3/2/21	RNAV (GPS) RWY 23, Orig-D.
22-Apr-21 ...	TN	Morristown	Moore-Murrell	1/9041	3/2/21	NDB RWY 5, Amdt 5C.
22-Apr-21 ...	TN	Morristown	Moore-Murrell	1/9042	3/2/21	SDF RWY 5, Amdt 5C.
22-Apr-21 ...	TN	Morristown	Moore-Murrell	1/9043	3/2/21	RNAV (GPS) RWY 5, Orig-C.
22-Apr-21 ...	OH	Bellefontaine	Bellefontaine Rgnl	1/9053	3/2/21	VOR/DME RWY 25, Orig-B.
22-Apr-21 ...	OH	Bellefontaine	Bellefontaine Rgnl	1/9055	3/2/21	VOR RWY 7, Orig-C.
22-Apr-21 ...	OH	Bellefontaine	Bellefontaine Rgnl	1/9056	3/2/21	RNAV (GPS) RWY 25, Amdt 1A.
22-Apr-21 ...	OH	Bellefontaine	Bellefontaine Rgnl	1/9057	3/2/21	RNAV (GPS) RWY 7, Amdt 1A.
22-Apr-21 ...	NC	Elizabethtown	Curtis L Brown Jr Fld	1/9085	3/2/21	VOR/DME RWY 15, Amdt 2.
22-Apr-21 ...	NC	Elizabethtown	Curtis L Brown Jr Fld	1/9087	3/2/21	RNAV GPS RWY 15, Orig.
22-Apr-21 ...	NC	Elizabethtown	Curtis L Brown Jr Fld	1/9088	3/2/21	RNAV GPS RWY 33, Orig-A.
22-Apr-21 ...	WI	Eagle River	Eagle River Union	1/9105	3/2/21	VOR/DME RWY 4, Amdt 1B.
22-Apr-21 ...	WI	Eagle River	Eagle River Union	1/9106	3/2/21	RNAV (GPS) RWY 22, Orig-B.
22-Apr-21 ...	WI	Eagle River	Eagle River Union	1/9107	3/2/21	RNAV (GPS) RWY 4, Orig-A.
22-Apr-21 ...	WI	Eagle River	Eagle River Union	1/9108	3/2/21	LOC/DME RWY 4, Orig-B.
22-Apr-21 ...	CO	Gunnison	Gunnison-Crested Butte Rgnl.	1/9142	3/2/21	GPS-B, Orig-A.
22-Apr-21 ...	CO	Gunnison	Gunnison-Crested Butte Rgnl.	1/9143	3/2/21	ILS OR LOC RWY 6, Amdt 5B.
22-Apr-21 ...	CO	Gunnison	Gunnison-Crested Butte Rgnl.	1/9145	3/2/21	VOR OR GPS-A, Amdt 7C.
22-Apr-21 ...	CA	Lompoc	Lompoc	1/9554	3/2/21	RNAV (GPS) RWY 25, Amdt 1B.
22-Apr-21 ...	CA	Lompoc	Lompoc	1/9555	3/2/21	VOR/DME-A, Amdt 5A.
22-Apr-21 ...	AK	Adak Island	Adak	1/9716	3/3/21	NDB/DME RWY 23, Orig-A.
22-Apr-21 ...	FL	Apopka	Orlando Apopka	1/9948	2/11/21	RNAV (GPS)-B, Orig.
22-Apr-21 ...	FL	Apopka	Orlando Apopka	1/9949	2/11/21	RNAV (GPS)-A, Orig.