

Proposed Rules

Federal Register

Vol. 88, No. 93

Monday, May 15, 2023

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2023-1042; Project Identifier MCAI-2023-00274-A]

RIN 2120-AA64

Airworthiness Directives; Pilatus Aircraft Ltd. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Pilatus Aircraft Ltd. (Pilatus) Model PC-24 airplanes. This proposed AD was prompted by reports of an electrical burning smell in the cabin without the presence of smoke. This proposed AD would require revising the Limitations Section of the existing airplane flight manual (AFM) for your airplane, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this NPRM by June 29, 2023.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to [regulations.gov](https://www.regulations.gov). Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket

No. FAA-2023-1042; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA service information that is proposed for IBR in this NPRM, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; website: easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

- You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222-5110. The EASA service information is also available at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-1042.

FOR FURTHER INFORMATION CONTACT:

Doug Rudolph, Aviation Safety Engineer, International Validation Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (816) 329-4059; email: doug.rudolph@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA-2023-1042; Project Identifier MCAI-2023-00274-A” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend the proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [regulations.gov](https://www.regulations.gov), including any personal information you provide. The agency

will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Doug Rudolph, Aviation Safety Engineer, International Validation Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2023-0038, dated February 14, 2023 (EASA AD 2023-0038) (referred to after this as the MCAI), to correct an unsafe condition for all Pilatus Model PC-24 airplanes.

The MCAI states that there have been reports of an electrical burning smell in the cabin without the presence of smoke and there is currently no AFM procedure for addressing this condition. The current AFM procedure for smoke/fume in the cockpit and/or cabin requires the immediate use of supplemental oxygen and smoke goggles for the flight crew, which leads to increased flight crew workload. Failure to revise the AFM to include a new task addressing an electrical burning smell in the cabin without the presence of smoke could result in an unsafe condition.

The FAA is proposing this AD to provide the flight crew with a new procedure in the existing AFM for your airplane to address the presence of an electrical burning smell in the cabin

without the presence of smoke. This condition, if not addressed, could lead to increased pilot workload, possibly resulting in a reduction of safety margins and an emergency landing. See EASA AD 2023–0038 for additional background information.

Related Service Information Under 1 CFR Part 51

EASA AD 2023–0038 requires revising the AFM by inserting a copy of Pilatus PC–24 AFM Temporary Revision 02371–055 (AFM TR 02371–055) into the Abnormal Procedures Section, informing all flight crews, and operating the airplane accordingly. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in ADDRESSES.

FAA’s Determination

These products have been approved by EASA and are approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the European Union, EASA, has notified the FAA about the unsafe condition described in its AD. The FAA is proposing this AD after evaluating all known relevant information and determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in EASA AD 2023–0038, described previously, as incorporated by reference, except for any differences

identified as exceptions in the regulatory text of this proposed AD and except as discussed under “Differences Between this Proposed AD and the EASA AD.”

The owner/operator (pilot) holding at least a private pilot certificate may revise the existing AFM for your airplane and must enter compliance with the applicable paragraph of this proposed AD into the aircraft records in accordance with 14 CFR 43.9(a) and 14 CFR 91.417(a)(2)(v). The pilot may perform this action because it only involves revising the AFM. This action could be performed equally well by a pilot or a mechanic. This is an exception to the FAA’s standard maintenance regulations.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2023–0038 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2023–0038 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Service information referenced in EASA AD 2023–0038 for compliance will be available at *regulations.gov* under Docket No. FAA–2023–1042 after the FAA final rule is published.

Differences Between This Proposed AD and the EASA AD

EASA AD 2023–0038 requires inserting AFM TR 02371–055 into the Abnormal Procedures Section of the AFM but this proposed AD would require inserting AFM TR 02371–055 into the Limitations Section of the existing AFM because FAA regulations mandate compliance with only the operating limitations section of the flight manual.

EASA AD 2023–0038 specifies to “inform all flight crews and, thereafter, operating the airplane accordingly” and this proposed AD would not specifically require those actions.

14 CFR 91.9 requires that no person may operate a civil aircraft without complying with the operating limitations specified in the AFM. Therefore, including a requirement in this proposed AD to operate the airplane according to the revised AFM would be redundant and unnecessary. Further, compliance with such a requirement in an AD would be impracticable to demonstrate or track on an ongoing basis; therefore, a requirement to operate the airplane in such a manner would be unenforceable.

Interim Action

The FAA considers that this proposed AD would be an interim action. If final action is later identified, the FAA may consider further rulemaking.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 97 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Revise AFM	0.50 work-hour × \$85 per hour = \$42.50	\$0	\$42.50	\$4,122.50

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA

with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order

13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Pilatus Aircraft Ltd: Docket No. FAA–2023–1042; Project Identifier MCAI–2023–00274–A.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by June 29, 2023.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Pilatus Aircraft Ltd. Model PC–24 airplanes, all serial numbers, certificated in any category.

(d) Subject

Joint Aircraft System Component (JASC) Code 2100, Heating System.

(e) Unsafe Condition

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI states that there have been reports of an electrical burning smell in the cabin without the presence of smoke and there is currently no airplane flight manual (AFM) procedure for addressing this condition. The FAA is issuing this AD to provide the flight crew with a new procedure in the existing AFM for your airplane to address the presence of an electrical burning smell in the cabin without the presence of smoke. This condition, if not addressed, could lead to increased pilot workload, possibly resulting in a reduction of safety margins and an emergency landing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Action

(1) Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2023–0038, dated February 14, 2023 (EASA AD 2023–0038).

(2) The actions required by paragraph (g)(1) of this AD may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the aircraft records showing compliance with this AD in accordance with 14 CFR 43.9(a) and 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.439.

(h) Exceptions to EASA AD 2023–0038

(1) Where EASA AD 2023–0038 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph (1) of EASA AD 2023–0038 specifies to “amend the AFM by inserting a copy of the AFM TR,” this AD requires revising the Limitations Section of the existing AFM for your airplane by inserting a copy of the AFM TR as defined in EASA AD 2023–0038.

(3) Where paragraph (1) of EASA AD 2023–0038 specifies to “inform all flight crews and, thereafter, operate the [airplane] accordingly,” this AD does not require those actions.

(4) This AD does not adopt the Remarks paragraph of EASA AD 2023–0038.

(i) Alternative Methods of Compliance (AMOCs)

The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD or email to: 9-AVS-AIR-730-AMOC@faa.gov. If mailing information, also submit information by email. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(j) Additional Information

For more information about this AD, contact Doug Rudolph, Aviation Safety Engineer, International Validation Branch, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: (816) 329–4059; email: doug.rudolph@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) European Union Aviation Safety Agency AD 2023–0038, dated February 14, 2023.

(ii) [Reserved]

(3) For EASA AD 2023–0038, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 8999 000; email: ADS@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (817) 222–5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on May 9, 2023.

Gaetano A. Sciortino,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–10282 Filed 5–12–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–1043; Project Identifier MCAI–2022–01295–E]

RIN 2120–AA64

Airworthiness Directives; Safran Helicopter Engines, S.A. Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for all Safran Helicopter Engines, S.A. (Safran) Model Arrius 2B2 engines. This proposed AD was prompted by the manufacturer revising the airworthiness limitations section (ALS) of the existing engine maintenance manual (EMM), introducing new and more restrictive tasks and limitations for certain life-limited parts. This proposed AD would require revising the ALS of the existing EMM or instructions for continued airworthiness (ICA) and the existing approved maintenance or inspection program, as applicable, by incorporating the actions and associated thresholds and intervals, including life limits, as specified in a European Union Aviation Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.