

(h) Retained Optional Mitigation for Certain Airplanes, With No Changes

This paragraph restates the provisions of paragraph (h) of AD 2023–12–20, with no changes. For airplanes identified in Bombardier Service Bulletin 650–35–002, Revision 01, dated January 28, 2022, having, as of the effective date of this AD, less than 6 years from the completion of the interior modification specified in STC ST02355NY: In lieu of accomplishing the oxygen system hose replacement required by paragraph (g) of this AD, comply with all conditions specified in paragraphs (h)(1) through (3) of this AD.

(1) The passenger oxygen system is tested within 6 months after the effective date of this AD, and thereafter at intervals not to exceed 36 months, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 650–35–002, Revision 01, dated January 28, 2022.

(2) If, during a test specified in paragraph (h)(1) of this AD, any leak is found on any hose, all oxygen system hoses having a part number in the O2C20T1 series must be replaced before further flight in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 650–35–002, Revision 01, dated January 28, 2022. Doing this replacement terminates the tests specified in paragraph (h)(1) of this AD.

(3) Except as specified by paragraph (h)(2) of this AD, all oxygen system hoses having a part number in the O2C20T1 series must be replaced within 6 years from the completion of the interior modification specified in STC ST02355NY. Doing this replacement terminates the tests specified in paragraph (h)(1) of this AD.

(i) Retained Parts Installation Prohibition, With No Changes

This paragraph restates the requirements of paragraph (i) of AD 2023–12–20, with no changes. As of the effective date of this AD, no person may install any oxygen system hose having a part number in the O2C20T1 and O2C20T14 series on any airplane.

(j) Retained Credit for Previous Actions, With No Changes

This paragraph restates the provisions of paragraph (j) of AD 2023–12–20, with no changes.

(1) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 605–35–006, dated August 23, 2021; or Bombardier Service Bulletin 650–35–002, dated August 23, 2021; as applicable.

(2) This paragraph provides credit for actions specified in paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 650–35–002, dated August 23, 2021.

(k) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to

approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, mail it to ATTN: Program Manager, Continuing Operational Safety, at the address identified in paragraph (l)(2) of this AD or email to: 9-avs-nyaco-cos@faa.gov. If mailing information, also submit information by email.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(ii) AMOCs approved for AD 2023–12–20 are approved as AMOCs for the corresponding provisions of this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or Bombardier, Inc.'s Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(l) Additional Information

(1) Refer to Transport Canada AD CF–2022–34, dated June 20, 2022, for related information. This Transport Canada AD may be found in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–1654.

(2) For more information about this AD, contact Elizabeth Dowling, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; email 9-avs-nyaco-cos@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(4) and (5) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on August 23, 2023 (88 FR 46063, July 19, 2023).

(i) Bombardier Service Bulletin 605–35–006, Revision 01, dated January 28, 2022.

(ii) Bombardier Service Bulletin 650–35–002, Revision 01, dated January 28, 2022.

(4) For service information identified in this AD, contact Bombardier Business Aircraft Customer Response Center, 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–2999; email ac.yul@aero.bombardier.com; website [bombardier.com](https://www.bombardier.com).

(5) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on July 31, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023–16648 Filed 8–4–23; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2023–0927; Project Identifier MCAI–2023–00013–T; Amendment 39–22461; AD 2023–12–03]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes; Correction

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting an airworthiness directive (AD) that was published in the **Federal Register**. That AD applies to certain Airbus SAS Model A350–941 and –1041 airplanes. As published, a European Union Aviation Safety Agency (EASA) AD number specified in the regulatory text is incorrect. This document corrects that error. In all other respects, the original document remains the same.

DATES: This correction is effective August 7, 2023. The effective date of AD 2023–12–03 remains August 7, 2023.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of August 7, 2023 (88 FR 42598, July 3, 2023).

ADDRESSES:

AD Docket: You may examine the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA–2023–0927; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule; correction, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

Material Incorporated by Reference:

• For material incorporated by reference in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this IBR material on the EASA website at ad.easa.europa.eu.

• You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket at [regulations.gov](https://www.regulations.gov) under Docket No. FAA-2023-0927.

FOR FURTHER INFORMATION CONTACT: Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7317; email dat.v.le@faa.gov.

SUPPLEMENTARY INFORMATION:**Background**

AD 2023-12-03, Amendment 39-22461 (88 FR 42598, July 3, 2023) (AD 2023-12-03), requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations for airplane structures and safe life limits. That AD applies to certain Airbus SAS Model A350-941 and -1041 airplanes.

Need for the Correction

As published, paragraph (i) in the regulatory text of AD 2023-12-03 is incorrect. Paragraph (i) of AD 2023-12-03 refers to “EASA AD 2023-0017.” The correct reference is “EASA AD 2023-0004.”

Related Service Information Under 14 CFR Part 51

EASA AD 2023-0004, dated January 6, 2023, describes new or more restrictive airworthiness limitations for airplane structures and safe life limits. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Correction of Publication

This document corrects an error and correctly adds the AD as an amendment to 14 CFR 39.13. Although no other part of the preamble or regulatory information has been corrected, the FAA is publishing the entire rule in the **Federal Register**.

The effective date of this AD remains August 7, 2023.

Since this action only corrects an EASA AD reference, it has no adverse

economic impact and imposes no additional burden on any person. Therefore, the FAA has determined that notice and public procedures are unnecessary.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the FAA amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Corrected]

■ 2. The FAA corrects § 39.13 by correcting the airworthiness directive published at 88 FR 42598 (July 3, 2023) to read:

2023-12-03 Airbus SAS: Amendment 39-22461; Docket No. FAA-2023-0927; Project Identifier MCAI-2023-00013-T.

(a) Effective Date

This airworthiness directive (AD) is effective August 7, 2023.

(b) Affected ADs

This AD affects AD 2023-04-05, Amendment 39-22352 (88 FR 13668, March 6, 2023) (AD 2023-04-05).

(c) Applicability

This AD applies to Airbus SAS Model A350-941 and -1041 airplanes, certificated in any category, with an original airworthiness certificate or original export certificate of airworthiness issued on or before November 1, 2022.

(d) Subject

Air Transport Association (ATA) of America Code: 05, Time Limits/Maintenance Checks.

(e) Unsafe Condition

This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. The FAA is issuing this AD to address reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation

Safety Agency (EASA) AD 2023-0004, dated January 6, 2023 (EASA AD 2023-0004).

(h) Exceptions to EASA AD 2023-0004

(1) This AD does not adopt the requirements specified in paragraphs (1) and (2) of EASA AD 2023-0004.

(2) Paragraph (3) of EASA AD 2023-0004 specifies revising “the approved AMP” within 12 months after its effective date, but this AD requires revising the existing maintenance or inspection program, as applicable, within 90 days after the effective date of this AD.

(3) The initial compliance time for doing the tasks specified in paragraph (3) of EASA 2023-0004 is on or before the applicable “associated thresholds” as incorporated by the requirements of paragraph (3) of EASA AD 2023-0004, or within 90 days after the effective date of this AD, whichever occurs later.

(4) This AD does not adopt the provisions specified in paragraph (4) of EASA AD 2023-0004.

(5) This AD does not adopt the “Remarks” section of EASA AD 2023-0004.

(i) Provisions for Alternative Actions and Intervals

After the existing maintenance or inspection program has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections) and intervals are allowed unless they are approved as specified in the provisions of the “Ref. Publications” section of EASA AD 2023-0004.

(j) Terminating Action for AD 2023-04-05

Accomplishing the actions required by this AD terminates the corresponding requirements of AD 2023-04-05, for the tasks identified in the service information referenced in EASA AD 2023-0004 only.

(k) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the International Validation Branch, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(l) Additional Information

For more information about this AD, contact Dat Le, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7317; email Dat.V.Le@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on August 7, 2023 (88 FR 42598, July 3, 2023).

(i) European Union Aviation Safety Agency (EASA) AD 2023-0004, dated January 6, 2023.

(ii) [Reserved]

(4) For EASA AD 2023-0004, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this EASA AD on the EASA website at ad.easa.europa.eu.

(5) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(6) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on August 1, 2023.

Victor Wicklund,

Deputy Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2023-16884 Filed 8-3-23; 11:15 am]

BILLING CODE 4910-13-P

DEPARTMENT OF THE TREASURY**Office of Foreign Assets Control****31 CFR Part 555****Mali Sanctions Regulations**

AGENCY: Office of Foreign Assets Control, Treasury.

ACTION: Final rule.

SUMMARY: The Department of the Treasury's Office of Foreign Assets Control (OFAC) is adopting a final rule amending and replacing the Mali Sanctions Regulations, published in abbreviated form on February 7, 2020, to further implement a July 26, 2019 Mali-related Executive order and provide a more comprehensive set of regulations, including additional interpretive and

definitional guidance, general licenses, and other regulatory provisions.

DATES: This rule is effective August 7, 2023.

FOR FURTHER INFORMATION CONTACT:

OFAC: Assistant Director for Licensing, 202-622-2480; Assistant Director for Regulatory Affairs, 202-622-4855; or Assistant Director for Compliance, 202-622-2490.

SUPPLEMENTARY INFORMATION:**Electronic Availability**

This document and additional information concerning OFAC are available on OFAC's website: <https://ofac.treasury.gov>.

Background

On February 7, 2020, OFAC issued the Mali Sanctions Regulations, 31 CFR part 555 (85 FR 7223, February 7, 2020) (the "Regulations"), to implement Executive Order (E.O.) 13882 of July 26, 2019, "Blocking Property and Suspending Entry of Certain Persons Contributing to the Situation in Mali" (84 FR 37055, July 30, 2019), pursuant to authorities delegated to the Secretary of the Treasury in E.O. 13882. The Regulations were initially issued in abbreviated form for the purpose of providing immediate guidance to the public. OFAC is revising the Regulations to further implement E.O. 13882. OFAC is amending and reissuing the Regulations as a more comprehensive set of regulations that includes additional interpretive guidance and definitions, general licenses, and other regulatory provisions that will provide further guidance to the public. Due to the number of regulatory sections being updated or added, OFAC is reissuing the Regulations in their entirety.

On July 26, 2019, the President, invoking the authority of, *inter alia*, the International Emergency Economic Powers Act (50 U.S.C. 1701 *et seq.*) (IEEPA) and the United Nations Participation Act (22 U.S.C. 287c) (UNPA), issued E.O. 13882. In E.O. 13882, the President determined that the situation in Mali, including repeated violations of ceasefire arrangements made pursuant to the 2015 Agreement on Peace and Reconciliation in Mali; the expansion of terrorist activities into southern and central Mali; the intensification of drug trafficking and trafficking in persons, human rights abuses, and hostage-taking; and the intensification of attacks against civilians, the Malian defense and security forces, the United Nations Multi-dimensional Integrated Stabilizations Mission in Mali

(MINUSMA), and international security presences, constituted an unusual and extraordinary threat to the national security and foreign policy of the United States and declared a national emergency to deal with that threat.

Section 1 of E.O. 13882 blocks, with certain exceptions, all property and interests in property that are in the United States, that come within the United States, or that are or come within the possession or control of any U.S. person of any person determined by the Secretary of the Treasury, in consultation with the Secretary of State to: (i) be responsible for or complicit in, or to have directly or indirectly engaged in, any of the following in or in relation to Mali: (A) actions or policies that threaten the peace, security, or stability of Mali; (B) actions or policies that undermine democratic processes or institutions in Mali; (C) a hostile act in violation of, or an act that obstructs, including by prolonged delay, or threatens the implementation of, the 2015 Agreement on Peace and Reconciliation in Mali; (D) planning, directing, sponsoring, or conducting attacks against local, regional, or state institutions, the Malian defense and security forces, any international security presences, MINUSMA peacekeepers, other United Nations or associated personnel, or any other peacekeeping operations; (E) obstructing the delivery or distribution of, or access to, humanitarian assistance; (F) planning, directing, or committing an act that violates international humanitarian law or that constitutes a serious human rights abuse or violation, including an act involving the targeting of civilians through the commission of an act of violence, abduction or enforced disappearance, forced displacement, or an attack on a school, hospital, religious site, or location where civilians are seeking refuge; (G) the use or recruitment of children by armed groups or armed forces in the context of the armed conflict in Mali; (H) the illicit production or trafficking of narcotics or their precursors originating or transiting through Mali; (I) trafficking in persons, smuggling in migrants, or trafficking or smuggling arms or illicitly acquired cultural property; or (J) any transaction or series of transactions involving bribery or other corruption, such as the misappropriation of Malian public assets or expropriation of private assets for personal gain or political purposes; (ii) have materially assisted, sponsored, or provided financial, material, or technological support for, or goods or services in support of, any person