

bleed system. The FAA is issuing this AD to address the unsafe condition, which if not addressed, could result in dual engine failure.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with Transport Canada AD CF–2024–30, dated August 27, 2024 (Transport Canada AD CF–2024–30).

(h) Exception to Transport Canada AD CF–2024–30

(1) Where Transport Canada AD CF–2024–30 refers to its effective date, this AD requires using the effective date of this AD.

(2) Where paragraph B. of Transport Canada AD CF–2024–30 specifies to “inform all flight crews of these changes in the AFM procedures and thereafter operate the aeroplane accordingly,” this AD does not require those actions as those actions are already required by existing FAA operating regulations (see 14 CFR 91.9, 14 CFR 91.505, and 14 CFR 121.137).

(i) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD and email to: AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or Transport Canada; or Airbus Canada Limited Partnership’s Transport Canada Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(j) Additional Information

For more information about this AD, contact Joseph Catanzaro, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516–228–7300; email: 9-avs-nyaco-cos@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Transport Canada AD CF–2024–30, dated August 27, 2024.

(ii) [Reserved]

(3) For Transport Canada material identified in this AD, contact Transport Canada, Transport Canada National Aircraft Certification, 159 Cleopatra Drive, Nepean, Ontario K1A 0N5, Canada; telephone 888–663–3639; email TC.AirworthinessDirectives-Consignesdenavigabilite.TC@tc.gc.ca; website at tc.canada.ca/en/aviation.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on December 9, 2024.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2024–29302 Filed 12–12–24; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2024–2556; Project Identifier MCAI–2024–00247–T]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A300 series airplanes; Model A300 B4–600, B4–600R, and F4–600R series airplanes, and Model A300 C4–605R Variant F airplanes (collectively called Model A300–600 series airplanes); and Model A310 series airplanes. This proposed AD was prompted by investigations that found cracks on the main deck cargo door (MDCD) actuator bearing fitting caused by fatigue. This proposed AD would require an operational limitation to the MDCD opening angle, repetitive detailed visual inspection (DET) of the MDCD actuator bearing fittings, and replacement if any cracks are found, as specified in a European Union Aviation

Safety Agency (EASA) AD, which is proposed for incorporation by reference (IBR). The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by January 27, 2025.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal*: Go to regulations.gov. Follow the instructions for submitting comments.

- *Fax*: 202–493–2251.

- *Mail*: U.S. Department of

Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery*: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

AD Docket: You may examine the AD docket at regulations.gov under Docket No. FAA–2024–2556; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.

Material Incorporated by Reference:

- For EASA material identified in this proposed AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu. It is also available at regulations.gov under Docket No. FAA–2024–2556.

- You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 206–231–3225; email: Dan.Rodina@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2024–2556; Project Identifier MCAI–2024–00247–T” at the

beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to *regulations.gov*, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Dan Rodina, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 206-231-3225; email: *Dan.Rodina@faa.gov*. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2024-0092R1, dated July 10, 2024 (EASA AD 2024-0092R1) (also referred to as the

MCAI), to correct an unsafe condition for certain Airbus SAS Model A300 series, A300-600 series, and A310 series airplanes. The MCAI states that investigations found cracks on the MDCD actuator bearing fitting caused by fatigue. There is no unsafe condition during flight when the cargo door is fully closed, latched, and locked. However, if not detected and corrected, this cracking could lead to MDCD undamped free fall from the open position during MDCD operations or during cargo loading/off-loading, resulting in injury to people on the ground.

The FAA is proposing this AD to address the unsafe condition on these products.

You may examine the MCAI in the AD docket at *regulations.gov* under Docket No. FAA-2024-2556.

Material Incorporated by Reference Under 1 CFR Part 51

EASA AD 2024-0092R1 specifies procedures for an operational limitation to the MDCD opening angle, repetitive DET of the MDCD actuator bearing fittings, and replacement of both MDCD actuator bearing fittings if any crack is found on any MDCD actuator bearing fitting.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with this State of Design Authority, it has notified the FAA of the unsafe condition described in the MCAI referenced above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements in This NPRM

This proposed AD would require accomplishing the actions specified in

EASA AD 2024-0092R1 described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

Explanation of Required Compliance Information

In the FAA's ongoing efforts to improve the efficiency of the AD process, the FAA developed a process to use some civil aviation authority (CAA) ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has been coordinating this process with manufacturers and CAAs. As a result, the FAA proposes to incorporate EASA AD 2024-0092R1 by reference in the FAA final rule. This proposed AD would, therefore, require compliance with EASA AD 2024-0092R1 in its entirety through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Using common terms that are the same as the heading of a particular section in EASA AD 2024-0092R1 does not mean that operators need comply only with that section. For example, where the AD requirement refers to "all required actions and compliance times," compliance with this AD requirement is not limited to the section titled "Required Action(s) and Compliance Time(s)" in EASA AD 2024-0092R1. Material required by EASA AD 2024-0092R1 for compliance will be available at *regulations.gov* under Docket No. FAA-2024-2556 after the FAA final rule is published.

Interim Action

The FAA considers that this proposed AD would be an interim action. If final action is later identified, the FAA might consider further rulemaking then.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 128 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$10,880

The FAA estimates the following costs to do any necessary on-condition

actions that would be required based on the results of any required actions. The

FAA has no way of determining the

number of aircraft that might need this on-condition action:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
500 work-hours × \$85 per hour = \$42,500	\$34,600	\$77,100

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

Airbus SAS: Docket No. FAA–2024–2556; Project Identifier MCAI–2024–00247–T.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by January 27, 2025.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus SAS airplanes identified in paragraphs (c)(1) through (6) of this AD, certified in any category, manufactured in freighter model configuration.

- (1) Model A300 B4–2C, B4–103, and B4–203 airplanes.
- (2) Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes.
- (3) Model A300 B4–605R and B4–622R airplanes.
- (4) Model A300 C4–605R Variant F airplanes.
- (5) Model A300 F4–605R and F4–622R airplanes.
- (6) Model A310–203, –204, –221, –222, –304, –322, –324, and –325 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Unsafe Condition

This AD was prompted by investigations that found cracks on the main deck cargo door (MDCD) actuator bearing fitting caused by fatigue. The FAA is issuing this AD to address potential cracking of the MDCD actuator bearing fittings. The unsafe condition, if not addressed, could lead to MDCD undamped free fall from open position during MDCD operations or during cargo loading/off-loading, resulting in injury to people on the ground.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraphs (h) and (i) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2024–0092R1, dated July 10, 2024 (EASA AD 2024–0092R1).

(h) Exceptions to EASA AD 2024–0092R1

(1) Where EASA AD 2024–0092R1 refers to April 26, 2024 (the effective date of the original issue of EASA AD 2024–0092R1), this AD requires using the effective date of this AD.

(2) This AD does not adopt the “Remarks” section of EASA AD 2024–0092R1.

(i) No Reporting Requirement

Although the material referenced in EASA AD 2024–0092R1 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(j) Additional AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the International Validation Branch, send it to the attention of the person identified in paragraph (k) of this AD and email to: *AMOC@faa.gov*. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Validation Branch, FAA; or EASA; or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* Except as required by paragraph (j)(2) of this AD, if any material referenced in EASA AD 2024–0092R1 contains paragraphs that are labeled as RC, the instructions in RC paragraphs, including subparagraphs under an RC paragraph, must be done to comply with this AD; any paragraphs, including subparagraphs under those paragraphs, that are not identified as RC are recommended. The instructions in paragraphs, including subparagraphs under those paragraphs, not

identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the instructions identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to instructions identified as RC require approval of an AMOC.

(k) Additional Information

For more information about this AD, contact Dan Rodina, Aviation Safety Engineer, FAA, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 206-231-3225; email: Dan.Rodina@faa.gov.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the material listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this material as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2024-0092R1, dated July 10, 2024.

(ii) [Reserved].

(3) For EASA material identified in this AD, contact EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; website easa.europa.eu. You may find this material on the EASA website at ad.easa.europa.eu.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this material at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, visit www.archives.gov/federal-register/cfr/ibr-locations or email fr.inspection@nara.gov.

Issued on December 9, 2024.

Peter A. White,

Deputy Director, Integrated Certificate Management Division, Aircraft Certification Service.

[FR Doc. 2024-29356 Filed 12-12-24; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 122

[EPA-HQ-OW-2021-0169; FRL-12219-01-OW]

Modification to 2022 National Pollutant Discharge Elimination System (NPDES) Construction General Permit (CGP) for Stormwater Discharges From Construction Activities

AGENCY: Environmental Protection Agency (EPA).

ACTION: Notification; request for public comment.

SUMMARY: The Environmental Protection Agency (EPA) is proposing a narrow modification to its 2022 CGP to expand the list of areas eligible for coverage to include construction projects in Lands of Exclusive Federal Jurisdiction. This modification is necessary because the EPA is the permitting authority in Lands of Exclusive Federal Jurisdiction, and when the CGP was issued on February 17, 2022, the permit did not specifically provide eligibility for all of these areas. The proposed modification would also clarify the CGP requirements that apply to projects that discharge to receiving waters within Lands of Exclusive Federal Jurisdiction. The EPA seeks comment only on the proposed permit revisions and the accompanying fact sheet. The fact sheet and proposed permit modification can be found at <https://www.epa.gov/npdes/stormwater-discharges-construction-activities>.

DATES: Comments on the proposed permit modification must be received on or before January 13, 2025.

ADDRESSES: You may send comments, identified by Docket ID No. EPA-HQ-OW-2021-0169, by any of the following methods:

- *Federal eRulemaking Portal:* <https://www.regulations.gov/>. Follow the online instructions for submitting comments.
- *Mail:* U.S. Environmental Protection Agency, EPA Docket Center, Office of Water, Docket, Mail Code 28221T, 1200 Pennsylvania Avenue NW, Washington, DC 20460.
- *Hand Delivery or Courier:* EPA Docket Center, WJC West Building, Room 3334, 1301 Constitution Avenue NW, Washington, DC 20004. The Docket Center's hours of operations are 8:30 a.m. to 4:30 p.m., Monday—Friday (except Federal Holidays).

Instructions: All submissions received must include the Docket ID No. for this rulemaking. Comments received may be

posted without change to <https://www.regulations.gov>, including personal information provided. For detailed instructions on sending comments and additional information on the rulemaking process, see the "Public Participation" heading of the **SUPPLEMENTARY INFORMATION** section of this document.

FOR FURTHER INFORMATION CONTACT: Greg Schaner, EPA Headquarters, Office of Water, Office of Wastewater Management at (202) 564-0721 or by email at schaner.greg@epa.gov.

SUPPLEMENTARY INFORMATION: This section is organized as follows:

Table of Contents

- I. General Information
 - A. Does this action apply to me?
 - B. Public Participation
 - C. Finalizing the Proposed Permit Modification
 - D. Who are the EPA Regional Contacts for This Permit?
- II. Permit Modification Background
 - A. Permitting of Stormwater Discharges From Construction Activities
 - B. Background on Lands of Exclusive Federal Jurisdiction
 - C. Why is a Modification to the 2022 CGP Necessary?
- III. Summary of Proposed Permit Changes
- IV. Public Notice of Clean Water Act Section 401 Certification for Lands of Exclusive Federal Jurisdiction
- V. Paperwork Reduction Act (PRA)
- VI. 2022 CGP Incremental Cost Analysis
- VII. Executive Order 12866: Regulatory Planning and Review and Executive Order 14094: Modernizing Regulatory Review
- VIII. Executive Order 12898: Federal Actions To Address Environmental Justice in Minority Populations and Low-Income Populations and Executive Order 14096: Revitalizing Our Nation's Commitment to Environmental Justice for All
- IX. Executive Order 13175: Consultation and Coordination With Indian Tribal Governments
- X. Executive Order 13211: Actions That Significantly Affect Energy Supply, Distribution, or Use
- XI. Compliance With the National Environmental Policy Act (NEPA) for the National Pollutant Discharge Elimination System (NPDES) General Permit for Discharges from Construction Activities

I. General Information

A. Does this action apply to me?

This proposed permit modification covers the following entities, as categorized in the North American Industry Classification System (NAICS), where they are conducting construction activities in Lands of Exclusive Federal Jurisdiction: