

this AD requires using “the effective date of this AD.”

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to 9-ANMSeattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office of the responsible Flight Standards Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(j) Related Information

For more information about this AD, contact Julie Linn, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone: 206-231-3684; email: Julie.Linn@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Requirements Bulletin 747-25-3726 RB, dated January 6, 2022.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; website myboeingfleet.com.

(4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, fr.inspection@nara.gov, or go to

www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on November 28, 2022.

Christina Underwood,

Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-27302 Filed 12-15-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2022-0571; Airspace Docket No. 22-ANM-46]

RIN 2120-AA66

Establishment of Class E Airspace; Christmas Valley Airport, OR; Correction

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting a final rule that appeared in the **Federal Register** on December 9, 2022. The Final Rule incorrectly annotated the airspace class designation in the text header of the newly designated Class E airspace beginning at 700 feet above the surface at Christmas Valley Airport, OR. This action corrects the error.

DATES: Effective 0901 UTC, February 23, 2023. The Director of the Federal Register approves this incorporation by reference under 1 CFR part 51, subject to the annual revision of FAA Order JO 7400.11, *Airspace Designations and Reporting Points*, and publication of conforming amendments.

FOR FURTHER INFORMATION CONTACT:

Nathan A. Chaffman, Federal Aviation Administration, Western Service Center, Operations Support Group, 2200 S. 216th Street, Des Moines, WA 98198; telephone (206) 231-3460.

SUPPLEMENTARY INFORMATION:

History

The FAA published a final rule in the **Federal Register** (87 FR 75465; December 9, 2022) for Docket FAA-2022-0571, which established Class E airspace extending upward from 700 feet above the surface at Christmas Valley Airport, OR. Subsequent to publication, the FAA identified that the Final Rule incorrectly annotated the airspace class designator in the text header of the newly established Class E airspace beginning at 700 feet above the surface at Christmas Valley Airport, OR. The legal description's text header

currently reads “ANM OR E Christmas Valley, OR [New], but should read “ANM OR E5 Christmas Valley, OR [New].” This action corrects the error.

The Class E5 airspace designation is published in paragraph 6005 of FAA Order JO 7400.11G, dated August 19, 2022, and effective September 15, 2022, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in FAA Order JO 7400.11.

FAA Order JO 7400.11 is published annually and becomes effective on September 15.

Correction to Final Rule

Accordingly, pursuant to the authority delegated to the FAA, “Establishment of Class E Airspace; Christmas Valley Airport, OR”, published in the **Federal Register** of December 9, 2022 (87 FR 75465), FR Doc. 2022-26646, is corrected as follows:

§ 71.1 [Corrected]

■ 1. On page 75466, in the third column, line 1 is corrected to read:

ANM OR E5 Christmas Valley, OR [New]

Issued in Des Moines, Washington, on December 12, 2022.

B.G. Chew,

Group Manager, Operations Support Group, Western Service Center.

[FR Doc. 2022-27268 Filed 12-15-22; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE

Bureau of Industry and Security

15 CFR Part 744

[Docket No. 221209-0268]

RIN 0694-AJ02

Revisions to the Unverified List and the Entity List

AGENCY: Bureau of Industry and Security, Department of Commerce.

ACTION: Final rule.

SUMMARY: The Bureau of Industry and Security (BIS) is amending the Export Administration Regulations (EAR) by removing 9 persons from the Unverified List (UVL) and adding them to the Entity List, all under the destination of Russia. BIS has been unable to verify the *bona fides* of all 9 persons being removed from the UVL and added to the Entity List, due to the foreign government's prevention of timely end-use checks. BIS is also amending the