

Rules and Regulations

Federal Register

Vol. 85, No. 204

Wednesday, October 21, 2020

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2020–0918; Project Identifier MCAI–2020–01335–T; Amendment 39–21299; AD 2020–22–03]

RIN 2120–AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A330–200, –200 Freighter, and –300 series airplanes. This AD was prompted by a report that during a certification exercise, it was identified that there was a risk of an engine bleed system over-temperature, without the engine bleed valve closing; the associated engine bleed valve should automatically close. This AD requires revising the existing airplane flight manual (AFM) to incorporate procedures to be applied if an engine bleed over-temperature occurs when the associated engine bleed valve is jammed open, and provides for the optional embodiment of updated flight warning computer (FWC) software, which would terminate the AFM revision, as specified in a European Union Aviation Safety Agency (EASA), which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective November 5, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 5, 2020.

The FAA must receive comments on this AD by December 7, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202–493–2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0918.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0918; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax: 206–231–3229; email: vladimir.ulyanov@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD

2020–0205, dated September 24, 2020 (“EASA AD 2020–0205”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus SAS Model A330–200, –200 Freighter, and –300 series airplanes.

This AD was prompted by a report that during a certification exercise, it was identified that there was a risk of an engine bleed system over-temperature, without the engine bleed valve closing; the associated engine bleed valve should automatically close. The FAA is issuing this AD to address the possibility of a jammed engine bleed valve, which could lead to damage of the bleed manifold and the ducts downstream of the engine bleed system, exposure of the surrounding structure to heat stress, and possible reduced structural integrity of the airplane. See the MCAI for additional background information.

Related IBR Material Under 1 CFR Part 51

EASA AD 2020–0205 describes procedures for amending the applicable AFM to incorporate procedures to be applied if an engine bleed over-temperature occurs when the associated engine bleed valve is jammed open. EASA AD 2020–0205 also specifies that embodiment of updated FWC software would eliminate the need for the AFM amendment. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to the FAA’s bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is issuing this AD because the FAA evaluated all pertinent information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Requirements of This AD

This AD requires accomplishing the actions specified in EASA AD 2020–0205, described previously, as

incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and EASA to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, EASA AD 2020–0205 is incorporated by reference in this final rule. This AD, therefore, requires compliance with EASA AD 2020–0205 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this AD. Using common terms that are the same as the heading of a particular section in the EASA AD does not mean that operators need comply only with that section. For example, where the AD requirement refers to “all required actions and compliance times,” compliance with this AD requirement is not limited to the section titled “Required Action(s) and Compliance Time(s)” in the EASA AD. Service information specified in EASA AD 2020–0205 that is required for compliance with EASA AD 2020–0205 is available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2020–0918.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C. 551 *et seq.*) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for “good cause,” finds that those procedures are “impracticable, unnecessary, or contrary to the public interest.” Under this section, an agency, upon finding good cause, may issue a final rule without providing notice and seeking comment prior to issuance. Further, section 553(d) of the APA authorizes agencies to make rules

effective in less than thirty days, upon a finding of good cause. An unsafe condition exists that requires the immediate adoption of this AD without providing an opportunity for public comments prior to adoption. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because there is a possibility of a jammed engine bleed valve, which could lead to damage of the bleed manifold and the ducts downstream of the engine bleed system and exposure of the surrounding structure to heat stress, and possibly result in reduced structural integrity of the airplane. In addition, the compliance time for the required action is shorter than the time necessary for the public to comment and for publication of the final rule. Therefore this rule must be issued immediately, to ensure the safety of the flight crews conducting such flights. Accordingly, notice and opportunity for prior public comment are impracticable and contrary to the public interest pursuant to 5 U.S.C. 553(b)(3)(B). In addition, the FAA finds that good cause exists pursuant to 5 U.S.C. 553(d) for making this amendment effective in less than 30 days, for the same reasons the FAA found good cause.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, the FAA invites you to send any written comments, data, or views about this AD. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should submit only one copy of the comments. Send your comments to an address listed under the ADDRESSES section. Include “Docket No. FAA–2020–0918; Project Identifier MCAI–2020–01355–T” at the beginning of your comments. Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR

11.35, the FAA will post all comments received, without change, as well as a report summarizing each substantive public contact with FAA personnel concerning this AD. The FAA will consider all comments received by the closing date for comments. The FAA may amend this AD because of those comments.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this AD contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this AD, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this AD. Submissions containing CBI should be sent to Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3229; email vladimir.ulyanov@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Regulatory Flexibility Act (RFA)

The requirements of the RFA do not apply when an agency finds good cause pursuant to 5 U.S.C. 553 to adopt a rule without prior notice and comment. Because the FAA has determined that it has good cause to adopt this rule without notice and comment, RFA analysis is not required.

Costs of Compliance

The FAA estimates that this AD affects 105 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$8,925

ESTIMATED COSTS FOR OPTIONAL SOFTWARE UPDATE

Labor cost	Parts cost	Cost per product
2 work-hours × \$85 per hour = \$170	\$0	\$170

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866, and
- (2) Will not affect intrastate aviation in Alaska.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2020-22-03 Airbus SAS: Amendment 39-21299; Docket No. FAA-2020-0918; Project Identifier MCAI-2020-01335-T.

(a) Effective Date

This AD becomes effective November 5, 2020.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Airbus SAS Model airplanes, certificated in any category, as identified in paragraphs (c)(1) through (3) of this AD.

(1) Model A330-201, -202, -203, -223, and -243 airplanes.

(2) Model A330-223F and -243F airplanes.

(3) Model A330-301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 75, Air.

(e) Reason

This AD was prompted by a report that during a certification exercise, it was identified that there was a risk of an engine bleed system over-temperature, without the engine bleed valve closing; the associated engine bleed valve should automatically close. The FAA is issuing this AD to address the possibility of a jammed engine bleed valve, which could lead to damage of the bleed manifold and the ducts downstream of the engine bleed system and exposure of the surrounding structure to heat stress, and possibly result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, EASA AD 2020-0205, dated September 24, 2020 ("EASA AD 2020-0205").

(h) Exceptions to EASA AD 2020-0205

(1) Where EASA AD 2020-0205 refers to its effective date, this AD requires using the effective date of this AD.

(2) The "Remarks" section of EASA AD 2020-0205 does not apply to this AD.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Large Aircraft Section, International Validation Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the Large Aircraft Section, International Validation Branch, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-AVS-AIR-730-AMOC@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, Large Aircraft Section, International Validation Branch, FAA; or EASA; or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* For any service information referenced in EASA AD 2020-0205 that contains RC procedures and tests: Except as required by paragraph (i)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(j) Related Information

For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, Large Aircraft Section, International Validation Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax: 206-231-3229; email: vladimir.ulyanov@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2020-0205, dated September 24, 2020.

(ii) [Reserved]

(3) For EASA AD 2020-0205, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 8999 000; email ADs@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0918.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on October 13, 2020.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-23280 Filed 10-20-20; 8:45 am]

BILLING CODE 4910-13-P

ENVIRONMENTAL PROTECTION AGENCY

40 CFR Part 52

[EPA-R04-OAR-2020-0224; FRL-10015-13-Region 4]

Air Plan Approval; KY; Jefferson County Administrative Procedures

AGENCY: Environmental Protection Agency (EPA).

ACTION: Final rule.

SUMMARY: The Environmental Protection Agency (EPA) is approving changes to the Jefferson County portion of the Kentucky State Implementation Plan (SIP), submitted by the Commonwealth of Kentucky, through the Energy and Environment Cabinet (Cabinet), on March 4, 2020. The changes were submitted by the Cabinet on behalf of the Louisville Metro Air Pollution Control District (District or APCD) and make minor changes for clarity, remove an exemption for public hearings for permitting actions, and amend the procedures for open records requests to maintain consistency with the Kentucky Open Records Act (KORA). This action is being taken pursuant to the Clean Air Act (CAA or Act).

DATES: This rule is effective November 20, 2020.

ADDRESSES: EPA has established a docket for this action under Docket Identification No. EPA-R04-OAR-2020-0224. All documents in the docket are listed on the www.regulations.gov website. Although listed in the index, some information is not publicly available, *i.e.*, Confidential Business Information or other information whose disclosure is restricted by statute. Certain other material, such as copyrighted material, is not placed on the internet and will be publicly available only in hard copy form. Publicly available docket materials can either be retrieved electronically via www.regulations.gov or in hard copy at the Air Regulatory Management Section, Air Planning and Implementation Branch, Air and Radiation Division, U.S. Environmental Protection Agency, Region 4, 61 Forsyth Street SW, Atlanta, Georgia 30303-8960. EPA requests that if at all possible, you contact the person listed in the **FOR FURTHER INFORMATION CONTACT** section to schedule your inspection. The Regional Office's official hours of business are Monday through Friday 8:30 a.m. to 4:30 p.m., excluding Federal holidays.

FOR FURTHER INFORMATION CONTACT: Sarah LaRocca, Air Regulatory Management Section, Air Planning and Implementation Branch, Air and Radiation Division, Region 4, U.S. Environmental Protection Agency, 61 Forsyth Street SW, Atlanta, Georgia 30303-8960. The telephone number is (404) 562-8994. Ms. LaRocca can also be reached via electronic mail at larocca.sarah@epa.gov.

SUPPLEMENTARY INFORMATION:

I. Background

EPA is approving changes to APCD Regulation 1.08, *Administrative Procedures*, of the Jefferson County portion of the Kentucky SIP, submitted by the Commonwealth on March 4, 2020.¹ The March 4, 2020, SIP revision makes minor changes to Regulation 1.08 that do not alter the meaning of the regulation, for example, changes to clarify public hearing requirements, and relocation and reorganization of several sections. In addition, other changes strengthen the SIP by removing language exempting certain permitting actions from public hearings. Last, the SIP revision contains changes to sections related to public records to

maintain consistency with the KORA. The SIP revision updates the current SIP-approved version of Regulation 1.08 (Version 13) to Version 14.

In a notice of proposed rulemaking (NPRM) published on July 22, 2020 (85 FR 44258), EPA proposed to approve changes to the Jefferson County portion of the Kentucky SIP, provided on March 4, 2020. The July 22, 2020, NPRM provides additional detail regarding the background and rationale for EPA's action. Comments on the July 22, 2020, NPRM were due on or before August 21, 2020. EPA received no adverse comments on the July 22, 2020, NPRM.

II. Incorporation by Reference

In this document, EPA is finalizing regulatory text that includes incorporation by reference. In accordance with requirements of 1 CFR 51.5, EPA is finalizing the incorporation by reference APCD Regulation 1.08, *Administrative Procedures*, Version 14, effective November 20, 2019, which provides clarity, revises provisions related to Board meetings, and maintains consistency with KORA. EPA has made, and will continue to make, these materials generally available through www.regulations.gov and at the EPA Region 4 office (please contact the person identified in the **FOR FURTHER INFORMATION CONTACT** section of this preamble for more information). Therefore, these materials have been approved by the EPA for inclusion in the State implementation plan, have been incorporated by reference by EPA into the plan, are fully federally enforceable under sections 110 and 113 of the CAA as of the effective date of the final rulemaking of EPA's approval, and will be incorporated by reference in the next updated to the SIP compilation.²

III. Final Action

EPA is approving the changes to APCD Regulation 1.08, *Administrative Procedures*, Version 14, of the Jefferson County portion of the Kentucky SIP, submitted by the Commonwealth on March 4, 2020. The March 4, 2020, SIP revision updates the current SIP-approved version of APCD Regulation 1.08, Version 13 to Version 14. EPA is approving these changes because they are minor edits to clarify provisions related to public hearing requirements, SIP strengthening by removing an exemption from public hearings for certain permitting requirements, and maintaining consistency with KORA.

¹ The submittal includes a courtesy copy of Regulation 2.08, *Fees*, Version 24 which was adopted by the Commonwealth at the same time; however, the Commonwealth did not request that EPA incorporate that regulation into the SIP.

² See 62 FR 27968 (May 22, 1997).