

(3) AMOCs approved for AD 79–01–03 and AD 83–20–03 are approved as AMOCs for the corresponding provisions of this AD.

(k) Related Information

(1) For more information about this AD, contact Dan McCully, Aviation Safety Engineer, FAA, Atlanta ACO Branch, 1701 Columbia Avenue, College Park, GA 30337; phone: (404) 474–5548; fax: (404) 474–5606; email: william.mccully@faa.gov.

(2) For service information identified in this AD, contact Piper Aircraft, Inc., 2926 Piper Drive, Vero Beach, FL 32960; phone: (772) 567–4361; website: www.piper.com. You may view this service information at the FAA, Policy and Innovation Division, 901 Locust, Kansas City, MO 64106. For information on the availability of this material at the FAA, call (816) 329–4148.

Issued on March 12, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021–05584 Filed 3–22–21; 8:45 am]

BILLING CODE 4910–13–C

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2021–0187; Project Identifier AD–2020–01664–E]

RIN 2120–AA64

Airworthiness Directives; CFM International, S.A. Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain CFM International, S.A. (CFM) LEAP–1A23, LEAP–1A24, LEAP–1A24E1, LEAP–1A26, LEAP–1A26CJ, LEAP–1A26E1, LEAP–1A29, LEAP–1A29CJ, LEAP–1A30, LEAP–1A32, LEAP–1A33, LEAP–1A33B2, and LEAP–1A35A model turbofan engines. This proposed AD was prompted by a report of a manufacturing quality escape found during an inspection of a high-pressure turbine (HPT) case. This proposed AD would require the removal from service of the affected HPT case. The FAA is proposing this AD to address the unsafe condition on these products.

DATES: The FAA must receive comments on this proposed AD by May 7, 2021.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493–2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact CFM International, S.A., Aviation Operations Center, 1 Neumann Way, M/D Room 285, Cincinnati, OH 45125; phone: (877) 432–3272; email: aviation.fleetsupport@ge.com. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238–7759.

Examining the AD Docket

You may examine the AD docket at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2021–0187; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, any comments received, and other information. The street address for Docket Operations is listed above.

FOR FURTHER INFORMATION CONTACT:

Chris McGuire, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7120; fax: (781) 238–7199; email: Chris.McGuire@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under **ADDRESSES**. Include “Docket No. FAA–2021–0187; Project Identifier AD–2020–01664–E” at the beginning of your comments. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to [https://](https://www.regulations.gov)

www.regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

Confidential Business Information

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as “PROPIN.” The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Chris McGuire, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

Background

The FAA received a report of a manufacturing quality escape that identified certain HPT cases did not meet their approved type design. CFM determined the nonconforming parts could lead to over-temperature of the HPT mid-seal and uncontained rotor failure. A review of several x-rays of the bleed ports of the HPT case showed 148 parts with nonconforming indications, 8 of which were significant enough to impact the life of the HPT case. This condition, if not addressed, could result in failure of the HPT case, uncontained rotor release, damage to the engine, and damage to the airplane.

FAA’s Determination

The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Related Service Information Under 14 CFR Part 51

The FAA reviewed CFM Service Bulletin (SB) LEAP–1A–72–00–0421–01A–930A–D, Issue 001, dated October 22, 2020. This SB specifies procedures for replacing the affected HPT cases. This service information is reasonably available because the interested parties

have access to it through their normal course of business or by the means identified in **ADDRESSES**.

Proposed AD Requirements in This NPRM

This proposed AD would require removing the affected HPT cases from service and replacing the HPT case with a part eligible for installation.

Costs of Compliance

The FAA estimates that this AD, if adopted as proposed, would affect 8 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Remove and replace the HPT case	1 work-hour × \$85 per hour = \$85	\$217,600	\$217,685	\$1,741,480

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive:

CFM International, S.A.: Docket No. FAA–2021–0187; Project Identifier AD–2020–01664–E.

(a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by May 7, 2021.

(b) Affected ADs

None.

(c) Applicability

This AD applies to CFM International, S.A. (CFM) LEAP–1A23, LEAP–1A24, LEAP–1A24E1, LEAP–1A26, LEAP–1A26CJ, LEAP–1A26E1, LEAP–1A29, LEAP–1A29CJ, LEAP–1A30, LEAP–1A32, LEAP–1A33, LEAP–1A33B2, and LEAP–1A35A model turbofan engines, with a high-pressure turbine (HPT) case, part number (P/N) 2668M94G01, that contains a stage 7 port, P/N 2614M30P01, with a port casting serial number (S/N) listed in Table 1 in Planning Information, Paragraph 3.A., of CFM Service Bulletin (SB) LEAP–1A–72–00–0421–01A–930A–D, Issue 001, dated October 22, 2020.

(d) Subject

Joint Aircraft System Component (JASC) Code of America Code 7250, Turbine Section.

(e) Unsafe Condition

This AD was prompted by a report of a manufacturing quality escape found during inspection of an HPT case. The FAA is issuing this AD to prevent failure of the HPT case. The unsafe condition, if not addressed, could result in failure of the HPT case, uncontained rotor release, damage to the engine, and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

Before the HPT case exceeds the cycles since new limit in Table 1 in Planning Information, Paragraph 3.A., of CFM SB LEAP–1A–72–00–0421–01A–930A–D, Issue 001, dated October 22, 2020, or during the next piece part exposure, whichever occurs first after the effective date of this AD, remove the affected HPT case from service and replace with a part eligible for installation.

(h) Definitions

For the purpose of this AD:

(1) A part eligible for installation is an HPT case, P/N 2668M94G01, that contains a stage 7 port, P/N 2614M30P01, with an S/N that is not listed in Table 1 in Planning Information, Paragraph 3.A., of CFM SB LEAP–1A–72–00–0421–01A–930A–D, Issue 001, dated October 22, 2020.

(2) Piece-part exposure is when the HPT case is removed from the engine and fully disassembled.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in Related Information. Information may be emailed to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Chris McGuire, Aviation Safety Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: (781) 238–7120; fax: (781) 238–7199; email: Chris.McGuire@faa.gov.

(2) For service information identified in this AD, contact CFM International, S.A.,

Aviation Operations Center, 1 Neumann Way, M/D Room 285, Cincinnati, OH 45125; phone: (877) 432-3272; email: aviation.fleetsupport@faa.gov. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call (781) 238-7759.

Issued on March 12, 2021.

Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2021-05591 Filed 3-22-21; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2021-0176; Airspace Docket No. 21-ACE-8]

RIN 2120-AA66

Proposed Amendment of Class D and E Airspace; Sioux City, IA

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend the Class D and Class E airspace at Sioux Gateway Airport/Brigadier General Bud Day Field, Sioux City, IA. The FAA is proposing this action as the result of an airspace review caused by the decommissioning of the Sioux City VHF omnidirectional range (VOR) navigation aid as part of the VOR Minimum Operational Network (MON) Program. The name and geographic coordinates of the airport would also be updated to coincide with the FAA's aeronautical database.

DATES: Comments must be received on or before May 7, 2021.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590; telephone (202) 366-9826, or (800) 647-5527. You must identify FAA Docket No. FAA-2021-0176/Airspace Docket No. 21-ACE-8 at the beginning of your comments. You may also submit comments through the internet at <https://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays.

FAA Order 7400.11E, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at https://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11E at NARA, email: fedreg.legal@nara.gov or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FOR FURTHER INFORMATION CONTACT:

Jeffrey Claypool, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5711.

SUPPLEMENTARY INFORMATION:

Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it would amend the Class D airspace, the Class E surface airspace, and the Class E airspace extending upward from 700 feet above the surface at Sioux Gateway Airport/Brigadier General Bud Day Field, Sioux City, IA, to support instrument flight rule operations at this airport.

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both

docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2021-0176/Airspace Docket No. 21-ACE-8." The postcard will be date/time stamped and returned to the commenter.

All communications received before the specified closing date for comments will be considered before taking action on the proposed rule. The proposal contained in this notice may be changed in light of the comments received. A report summarizing each substantive public contact with FAA personnel concerned with this rulemaking will be filed in the docket.

Availability of NPRMs

An electronic copy of this document may be downloaded through the internet at <https://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's web page at https://www.faa.gov/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office (see the **ADDRESSES** section for the address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except federal holidays. An informal docket may also be examined during normal business hours at the Federal Aviation Administration, Air Traffic Organization, Central Service Center, Operations Support Group, 10101 Hillwood Parkway, Fort Worth, TX 76177.

Availability and Summary of Documents for Incorporation by Reference

This document proposes to amend FAA Order 7400.11E, Airspace Designations and Reporting Points, dated July 21, 2020, and effective September 15, 2020. FAA Order 7400.11E is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11E lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Proposal

The FAA is proposing an amendment to 14 CFR part 71 by:

Amending the Class D airspace at Sioux Gateway Airport/Brigadier General Bud Day Field, Sioux City, IA,